



# Commercial Vehicle Inspection Report

Decal Number: GB74018  
Decal Expiry Date: 2024-Sep-30  
Inspection Number: 20851662

Inspection Result:

**PASS**

FACILITY:	OKEOVER SERVICES LTD / S10390	INSP. TYPE:	Complete	INSP. START:	2024-Mar-12 10:30 AM PDT
INSPECTOR:	Depape, Gene Raymond / 200023	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Mar-13 09:10 AM PDT
WORK ORDER #:	571	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	09873087	VIN:	4V5JC8UE31N306324
PLATE #:	RJ9314	UNIT/FLEET#:	M12	OWNER/LESSEE NAME:	Adams Concrete LTD, Wayne
LICENCED GVW(kg):	26100	BODY STYLE:	Cement Mixer	ADDRESS:	7095 Duncan ST, 7095 Duncan ST Powell River, British Columbia
VEHICLE YEAR:	2001	ODOMETER:	351128 KM		V8a 1W1, Canada
MAKE:	VOLVO	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) replaced #3 LS brake shoes ( note Drum was to 16.61 max 16.62 ) , replace Maxi pots #2&3 LS , replace Drain cock at tank,
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) hi beam indicator light ,
Section 6 - Lamps	Repaired (same day)
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed with Caution drivers door handle hard to open from outside
Section 9A - Tires	Passed with Caution inner tire tread #3 RS
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	34	28	12			10	✓
2	Clamp	30	Automatic	21	30	14	14	13	14	
3	Clamp	30	Automatic	22	19	13	11	7	12	

Comment: REPLACED SHOES #3 DRUM IS TO 16.61

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	20	Lining (Shoe)	20	20	Drum		
2	70	70	Lining (Shoe)	14	14	Drum		
3	105	75	Lining (Shoe)	10	12	Drum		

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

#### Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: Depape, Gene Raymond

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Mar-13 09:11 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.  
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/13/2024 9:12:09 AM PDT