



# Commercial Vehicle Inspection Report

Decal Number: GN75501  
 Decal Expiry Date: 2026-Nov-30  
 Inspection Number: 21781588

Inspection Result:  
**PASS**

**FACILITY:** TWISTED METAL MECHANICS LTD. / S20269  
**INSPECTOR:** BOLIVAR, MICHAEL BRANDON / 202902  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Semi-annual

**INSP. START:** 2026-May-22 06:42 AM MST  
**INSP. COMPLETE:** 2026-May-22 09:43 AM MST

H11-1

**VEHICLE JUR:** British Columbia  
**PLATE #:** A3G2U8  
**LICENCED GWV(kg):** 999999  
**VEHICLE YEAR:** 2014  
**MAKE:** LODE KING  
**MODEL:**

**REGI:** 11169025  
**UNIT/FLEET#:**  
**BODY STYLE:** High Boy Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 2LDPF483XE9057967  
**OWNER/LESSEE NAME:** SOLES, REMINGTON  
**ADDRESS:** 4651 OLD ALASKA HIGHWAY  
 Dawson Creek, British Columbia  
 V1G0J3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	28	28	13	13	13	13	
2	Clamp	30	Automatic	30	30	13	13	13	13	
3	Clamp	30	Automatic	28	29	13	13	13	13	

**Comment:**

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	0	0	Lining (Shoe)		19	19	Drum	424.00	425.00
2	0	0	Lining (Shoe)		19	19	Drum	423.00	426.00
3	0	0	Lining (Shoe)		19	19	Drum	425.00	424.00

**Comment:**

**Inspection Comments:**  
 Has this Vehicle been road tested? No  
**Inspector:** BOLIVAR, MICHAEL BRANDON  
**Road Test Date:**  
**Signature:** *m. Bolivar*  
**Road Tester:**

This Inspection Report was submitted to CVSE on 2026-May-22 01:45 PM MST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.