

## HEAVY VEHICLE INSPECTION SCHEME (HVIS) Inspection Report (Truck, Bus and Trailer)

Inspection Report:

AZ2941595

1. HVIS Location				
Site Name	Unanderra HVIS	3		
2. Vehicle Class			ler X Other	
z. vemole olass	Track	ous IIai	Other	
3. Reason for Inspection				
Renew Other (Please Indicate) Registration X				
4. Replacement Vehicle	Registration Num	ber		
X Yes N		The vehicle in advise the Tra	spected is a replacement to that originally booked. Insport for NSW of this change so that inspection ducted from the current vehicle.	You must
5. Vehicle Details				
Registration Number Odometer Reading			VIN or Chassis	
	TA92YP		6B93147JAVK7W8011	
Vehicle make			Body type	
LUSTY		OTHER TRAILERS		
VIN / Chassis Number	P		Lights and Reflectors	P
Brakes	F		Mirrors, Windscreen & Windows	N
Tow Couplings	Р		Engine & Driveline	N
Steering	N		Fuel System	N
Suspension	F		Public Vehicle Fittings	N
Wheels Tyres & Hubs	F		Exhaust System Visual	N
Structure & Bodywork	F		Exhaust System Detailed (meter)	N
Seats & Seatbelts	N		Modifications	N
. Repairs Needed				
Defect Notice Issued	Yes X No	Defect Notice Nur	mbers AHV1582088	
3. Comments				
				1110 15
				NHVR
and	Road Transport (Vehicle Re	egistration) Regulation 201	with the inspection standards of the National Heavy 7 or Heavy Vehicles (Vehicle Standards) National Regulat	Vehicle Inspection Man
at the time of Inspection and all details are correct.  Spection SCO Number Office Number		Date:		
Passed X Failed	Manager Committee Committe	Office Number 2867	Date Signature   1	niett
	nether or not the vehicle		04/00/2025	mes

Note: This report indicates whether or not the vehicle met NSW registration standards at the time of inspection. It is not a comprehensive report on the condition of the vehicle, nor is it a guarantee that the vehicle is not stolen. For all types of checks a 'passed' inspection result may be accepted for registration for 3 months after the inspection, except where the Transport for NSW is informed that the vehicle is not roadworthy. Any alterations to the details of this report after its issue will render the document invalid.

nspection number : CA2848726 Inspection date : 05/08/2025 nspection status : Pass Amount paid : 27.00 nspection station **Jumber** : S02398 Jame : Manuel Aranega ddress : 6-8 Waynote Pl UNANDERRA, NSW 2526 ehicle details lumber plate : TA92YP ADR category code : HEAVY TRAILER lass : Trailer Engine capacity lake : LUSTY Number of cylinders or: lodel : TRI AXLE TABLE TOP rotors IN/Chassis : 6B93147JAVK7W8011 Motive Power ngine number Sleeping berth fitted? dometer reading R or L hand drive? ompliance date : 8/1997 Wheelbase lanufacture year Length imary colour : YELLOW Width nape : LOW LOADER TRAILER Height VM : 43000 Rear overhang(R) CMProjection re weight : 8920 Sleeping berth variant xle code : T6 - Trailer - dual/dual/dual Trailer Brakes : MECHANICAL o. of driven wheels Monitoring device : No tal No. of seated Conditions : HVIS INSPECTION TO BE rsons COMPLETED WITHIN 1 o. of standing persons: MONTH HVIS INSPECTION TO BE COMPLETED WITHIN 1 MONTH HVIS INSPECTION TO BE COMPLETED WITHIN 1 MONTH **Fittings** efect notice(s) cleared HV1582088 ason for inspection : Defect notice clearance

aminer's certification

mments

n satisfied that the vehicle I inspected is the same vehicle for which the defect notice was issued and have found tha defect(s) specified have been properly rectified and any labels affixed have been removed or defaced by me.

miner's signature

**Privacy Statement** 

Any personal information is being collected under the Road Transport Act 2013 to notify Roads and Maritime Services (RMS) in relation to the nspection of a motor vehicle. Failure to supply the information may result in a refusal to renew the registration. The information is being collected for RMS and may be disclosed in accordance with the exemptions provided under the Privacy and Personal Information Protection Act 1998. Individuals may also seek to have their personal information amended or corrected in accordance with the provisions of that Act.

Customer Copy