

RITCHIE BROS. Diagnostic Report
 Auctioneers®

2017 International DuraStar 4300
Test Information

Engine	Cummins B 6.7 (6.7)
Engine Serial	CMMNS*6B u13D0670000000*74005014
VIN	1HTMMMMN2HH486684
Driveline	Class 7 4x2
Body	Truck
Test Time	Aug. 24, 2026, 8:17 a.m.
File Length	43.3142 s

Usage

Label	Value	Units
Engine Odometer	178,488	mi
Odometer (Instrument Cluster #1)	178,500	mi
Engine Total Hours of Operation	11,443.7	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	14	%

Engine On/Off

Engine running

Check Engine Light

No check engine lights on

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Previous	Instrument Cluster #1	Source Address 33	Abnormal Update Rate	1
Previous	Instrument Cluster #1	Source Address 0	Abnormal Update Rate	1
Previous	Instrument Cluster #1	Source Address 11	Abnormal Update Rate	1
Previous	Instrument Cluster #1	Source Address 23	Other Failure Mode	1
Previous	Body Controller	Headlamp Low Beam Left #1	Current Below Normal	16
Previous	Body Controller	Right Turn Signal Lights	Current Below Normal	10
Previous	Body Controller	Cab HVAC System Controller	Abnormal Update Rate	2
Previous	Body Controller	Wiper Motor	Current Above Normal	2
Previous	Body Controller	Headlamp 1 High Beam	Current Below Normal	3
Previous	Body Controller	Source Address 23	Abnormal Update Rate	8
Previous	Body Controller	Headlamp 2 High Beam	Current Below Normal	5
Previous	Body Controller	Windshield Wiper Motor Speed	Current Below Normal	3
Previous	Body Controller	Source Address 0	Abnormal Update Rate	1
Previous	Body Controller	Cab HVAC Recirculation Door Control Actuator	Erratic, Intermittent, or Incorrect	1