



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GP23618
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21891679

Inspection Result:

PASS

2026253

FACILITY: APS TRUCK & TRAILER REPAIR LTD / S12970
INSPECTOR: SINGH, DAMAN / 200740
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2026-Aug-21 02:24 PM PDT
INSP. COMPLETE: 2026-Aug-21 03:35 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 82165P
LICENCED GVW(kg): 11957
VEHICLE YEAR: 2020
MAKE: KENWORTH
MODEL:

REGI: 15235610
UNIT/FLEET#: 368
BODY STYLE: Truck Tractor
ODOMETER: 1142801 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1XKYDP9X5LJ960143
OWNER/LESSEE NAME: ATLANTIC TRUCK LINES (2019) LTD.,
ADDRESS: 17065 26 AVE
Surrey, British Columbia
V3Z 0A4, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	REPLACED STEADY BEARING
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Repaired (same day)	REPALCED DRAG LINK
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	ADJUST FIFTH WHEEL
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Disc	N/A	Not Applicable	0	0	12			12	✓
2	Clamp	30L	Automatic	37	38	15	15	14	14	
3	Clamp	30L	Automatic	35	36	14	14	14	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)				
			Lining/Pad		Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad		16	16	Drum		
2	55	55	Lining (Shoe)		17	17	Drum		
3	60	65	Lining (Shoe)		16	15	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: SINGH, DAMAN

Signature:

This Inspection Report was submitted to CVSE on 2026-Aug-21 04:10 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement:

CVSED014

8/21/2026 4:10:28 PM PDT