Vehicle History Report # 74380201
Report Date: November 23, 2026 | 11:10 a.m. EST
Report Status: Complete

2013 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas
3VW2K7AJ9DM391118
Country of Assembly: Mexico
Last Reported Odometer: 155,673 KM



Accident/Damage Records Found

Last Registered In:
Ontario (Normal)

12 Service Records Found

No U.S. History Found

1 Open Recall Found

Not Actively Declared Stolen

No Import/Export Records Found

Questions? We're here to help.
Visit us at **support.carfax.ca**

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of November 23, 2026 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VW2K7AJ9DM391118

Vehicle History Report

Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2019 Apr 30	**Ontario, Canada**	
	Estimate | Estimate Date: 2019 Apr 30	$1,962.39
	Claim: Collision	$2,140.00

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2019 May 3	**n/a**	
	Damage Event: Damage reported: minor damage Damage to front Damage to rear	

Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Feb 21	22,083 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Drivability/performance checked • Ignition coil(s) replaced
2014 Jun 28	29,760 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Fluids checked • Horn replaced • Oil and filter changed • Tire condition and pressure checked
2014 Dec 30	37,221 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Fluids checked

	ODOMETER	SOURCE	DETAILS
			• Oil and filter changed • Tire condition and pressure checked • Tires rotated
2015 Jun 15	46,193 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Fluids checked • Oil and filter changed • Tire condition and pressure checked
2015 Jul 9	46,793 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Exterior light bulb(s) replaced
2015 Oct 26	51,753 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Drivability/performance checked • Emission system checked • Stabilizer bar links replaced
2015 Nov 25		Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Camshaft position sensor replaced • Drivability/performance checked
2016 Jan 25	54,599 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Cowl/firewall panel resealed • Wiper arm(s) replaced • Wiper arm/linkage adjusted • Wiper arms adjusted • Wiper motor replaced/repaired • Vehicle washed/detailed
2016 Feb 23	57,275 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Drivability/performance checked • Ignition coil(s) replaced • Vehicle washed/detailed
2016 Mar 31		Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Fluids checked • Oil and filter changed • Tire condition and pressure checked • Vehicle washed/detailed
2016 Dec 30	71,315 KM	Maple Volkswagen Maple, Ontario, Canada	**Vehicle serviced** • Maintenance inspection completed • Brake calipers cleaned/serviced • Fluids checked • Oil and filter changed • Rear brake pads replaced • Tire condition and pressure checked
2025 Apr 14		Lube Express Etobicoke, Ontario, Canada	**Vehicle serviced** • One tire replaced

Open Recalls

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open

micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy
Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit **Volkswagen's website.** (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

Stolen Vehicle Check

This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Dec 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray
2013 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2014 Feb 21	22,083 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2014 Jun 28	29,760 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2014 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2014 Dec 30	37,221 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2015 Jun 15	46,193 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2015 Jul 9	46,793 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2015 Oct 26	51,753 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial
2015 Nov 25		Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Jan 25	54,599 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Feb 23	57,275 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Mar 31		Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2016 Nov 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2016 Dec 30	71,315 KM	Maple Volkswagen Maple, Ontario, Canada	Service Record	Vehicle serviced
2017 May 10	77,796 KM	Auto Auction Toronto, Ontario, Canada	Auction Announcement	AUCTION ANNOUNCED AS PREVIOUS DAILY RENTAL
2017 Jun 23	77,796 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
2017 Aug 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2018 Aug 11		Motor Vehicle Dept. Windsor, Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2019 Apr 30		Insurance Records Ontario, Canada		
2019 Apr 30	155,673 KM	Insurance Records	Estimate Repair	Estimate Date: 2019-04-30
2019 May 3			Damage Event	Damage reported: minor damage Damage to front Damage to rear
2019 Jul 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Sep 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2021 Sep 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
				Vehicle colour noted as gray
2023 Jan 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2024 Jul 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2025 Apr 14		Lube Express Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2025 Jul 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2026 Jul 15		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at **support.carfax.ca**

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.
https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use

© 2026 CARFAX Canada ULC. All rights reserved.

CARFAX

3VW2K7AJ9DM391118