

J22-14
May



Cariboo Rail Hi-Rail Inspection

Equipment Manager 250-612-7010

DATE: April 19/2025

VIN #: 1FD0WSHT8KEE15143

Job Number: _____

Unit #: 57

Odometer: 181158 Km MI

Vendor: _____

Front Hirail: Make: RAFNA Model: R-450 S/N: 017336
 Rear Hirail: Make: RAFNA Model: R-450 S/N: 017337

#	DESCRIPTION	"R" Re-Work/Future Attention					Notes	
		"P" Pass	"F" Fail	P	F	R		A
1	Manufacturer Manual			X				No Manual
2	Lights, Beacon			X				
3	Back up alarm			X				Not working Replaced with New AR
4	Measure Tire Thread Depth							95 PSI
5	Tire Air Pressure							Fronts 1/2" Rears 1/4 - 3/8
6	Front & Rear Bellows			X				Requires all four to be replaced
7	Rubber Jounce					X		some play with no pressure on axle
8	Steering Lock			X				
9	Steering Stoppers			X				
10	Suspension Locks / Rods			X				Left in shut position
11	Lock Pins			X				sized cleaned & lubed locking grease
12	Electrical box / Wiring			X				
13	Guide Wheels for Wear			X				No signs of wear.
14	Guide Wheel Bearings / Seals			X				packed with grease
15	Spindles			X				
16	GuideTube & Pivot			X				Day? locking grease * AR
17	Lube Complete Hirail			X				Day? locking grease * All
18	Rail Sweeps (1/8 Gap)			X				
19	Hi rail Brakes			X				lubed pivot points & Adjusted
20	Hi Rail Pressure						X	Not set up to test
21	String Line (if required)						X	Not set up
22	Hirail Weight, (Record next page)					X		Not set up to test
23	Hirail Height, (Record next page)					X		Not set up to test
24	Torque wheel Nuts lbs lbs			X				
25	Air System Operation						X	
26	Air System Components						X	
27	Hydraulic System Operation			X				
28	Hydraulic Components			X				low oil (no leaks)
29	Creep Drive Operation						X	
30	Track Test						X	Not on Rail

Inspected By: _____

P F R A N

Signature: _____

Galaxy S23 FE