



26632 111 Ave Unit 100  
 Acheson AB T7X6E1  
 1-855-349-7245

J22-4

# Hi-Rail Inspection

Company Name: Coriboo Date: March 9, 2024  
 Vehicle Model, Year, make: 2020 Ford F-550 Unit #: 68  
 VIN: 1FD0W5HT7LEC93991  
 Odometer: 139 800 km

Front Hi-Rail Make: Continental Model: G-20 S/N: V406180  
 Rear Hi-Rail Make: Continental Model: G-20 S/N: V406180

G = Good S = Serviced R = Replaced Or Repaired N/A = Not Applicable To This Unit

Items for inspection	G	S	R	N/A
Steering Lock	✓			
Lights & Safety Markings	✓			
Back Up Alarm	✓			
Body Condition	✓			
Safety Handles	✓			
Ladders, Side Steps, Running Boards	✓			
Tire Tread Depth	✓			
Tire Air Pressure	✓			
Rims & Studs (without removal of tire)	✓			
Steering Stopper				✓
Suspension Lock				✓
Locking Pins	✓			
Lifting Bar				✓
Manual Lock	✓			
Rail Sweeps	✓			
Guide Wheels	✓			
Bearings		✓		
Seals			✓	
Spindles	✓			
Hi-Rail Brakes				✓
De-Rail Skids				✓
Tube & Pivot	✓			
Set Screw				✓
Grease Hi-Rail	✓			
Air System				✓
Hydraulic System	✓			
Inspection Service Sticker	✓			

Notes

Removed Hi-rail wheels & cleaned & greased bearings.  
Replaced Hi rail wheel seals (All)  
Greased & tested complete system.

Inspected by: [Signature] Print Name: Tyler Neufeld Date: March 9, 2024