



26632 111 Ave Unit 100  
 Acheson AB T7X6E1  
 1-855-349-7245

J22-6  
 MAY

# Hi-Rail Inspection

Company Name: Cariboo Rail Date: Dec 20, 2024  
 Vehicle Model, Year, make: 2019 Ford F-550 Unit #: 53  
 VIN: 1FD0W3HT2KEE15140  
 Odometer: 269475

Front Hi-Rail Make: Rafra Model: R-450 S/N: N/A  
 Rear Hi-Rail Make: Rafra Model: R-450 S/N: N/A

G = Good S = Serviced R = Replaced Or Repaired N/A = Not Applicable To This Unit

Items for inspection	G	S	R	N/A
Steering Lock	✓			
Lights & Safety Markings	✓			
Back Up Alarm	✓			
Body Condition	✓			
Safety Handles	✓			
Ladders, Side Steps, Running Boards	✓			
Tire Tread Depth	✓			
Tire Air Pressure	✓			
Rims & Studs (without removal of tire)	✓			
Steering Stopper				✓
Suspension Lock	✓			
Locking Pins	✓			
Lifting Bar				✓
Manual Lock	✓			
Rail Sweeps	✓			
Guide Wheels		✓	✓	
Bearings		✓	✓	
Seals		✓	✓	
Spindles		✓	✓	
Hi-Rail Brakes	✓			
De-Rail Skids				✓
Tube & Pivot				✓
Set Screw				✓
Grease Hi-Rail		✓		
Air System				✓
Hydraulic System	✓			
Inspection Service Sticker	✓			

Notes

Inspected hi-rail

Replaced 4 bearings, 4 seals, LR spindle + wheel

Aligned hi-rail

Tested for proper operation

Inspected by: [Signature] Print Name: Tyler Newfold Date: Dec 20, 2024