



J22-8
MAY

DATE: _____

VIN #: 1FD0W5HT6KEE15142

Job Number: _____

Unit #: 54

Odometer: 137455.4 Km MI

Vendor: _____

Front Hirail: Make: RAFNA Model: R-450 S/N: 016940

Rear Hirail: Make: RAFNA Model: R-450 S/N: N/A

K DESCRIPTION

#	Items to Inspect	"R" Repair/Future Attention					Notes
		"P" Pass	"F" Fail	"R" Repair	"A" Attention	"N" Not Applicable	
1	Manufacturer Manual	X					
2	Lights, Beacon	X			✓		Requires 2 New Tail Light Mount Boxes
3	Back up alarm	X					
4	Measure Tire Thread Depth	X					fronts 7/16" Rears (4) 1/2"
5	Tire Air Pressure	X					95 PSI
6	Front & Rear Bellows	X					good conditions clamps in place.
7	Rubber Jounce	X					good conditions no signs of cracking.
8	Steering Lock		X				Missing.
9	Steering Stoppers	X					
10	Suspension Locks / Rods	X					good condition & has lube.
11	Lock Pins	X			X		* Rear lock up pins should be replaced.
12	Electrical box / Wiring	X					
13	Guide Wheels for Wear	X					No signs of Bad wear.
14	Guide Wheel Bearings / Seals	X					
15	Spindles	X					
16	Guide Tube & Pivot	X					
17	Lube Complete Hirail	X					
18	Rail Sweeps (1/8 Gap)	X					small adjustment
19	Hi rail Brakes	X					Adjusted RT & Left.
20	Hi Rail Pressure				X		Not set up to perform.
21	String Line (if required)				X		Not set up to perform task.
22	Hirail Weight, (Record next page)				X		Not set up to perform task.
23	Hirail Height, (Record next page)	X			X		
24	Torque wheel Nuts <u>165</u> lbs	X					
25	Air System Operation					X	
26	Air System Components					X	
27	Hydraulic System Operation	X					good working order. fluids full.
28	Hydraulic Components				✓		left front Hyd cylinder shows signs of leak.
29	Creep Drive Operation					X	
30	Track Test					X	No track Available

P F R A N

Inspected By: _____

Signature: _____

Galaxy S23