



TILL HINO

1300 446 663

Till Automotive Group Pty Ltd ACN 620 672 611
 ATF Till Automotive Group Unit Trust
 ABN 81 952 343 665 LMCT: 0011771
 11-13 Industrial Pl, Breakwater VIC 3219

Email: service@tillhino.com.au
 Visit us online: www.tillhino.com.au

Vehicle ID HINOHOME		Description HINO MOTOR HOME			Key Tag	Service Tax Invoice Number 1424466		
Series			Model			Page 3 of 3	Date 25/02/2021	
Colour	Engine	Trans	VIN 1148305			Engine No.	Fuel Type	
Paint Code	Radio Pin	Manufactured Date	Compliance Date	Manufacturer ID	Date First Registered	Stock Number		
Account 51	Order Number	Deal No.	Salesperson	Dealer	Warranty Expiry	Ext Warranty Expiry	Odometer 273505	
Driver Name			Time In 07:30	Time Out 17:00	Date Out 24/02/2021	Phone 0419393884		

Booking: pratr - Rachel
 Advisor: pratr - Rachel
 Costing: pratr - Rachel
 Finalised: pratr - Rachel
 RO: 1307555

JOHN WILMOT

Job No	B/Code	Description	Units	Amount
--------	--------	-------------	-------	--------

Warranties, Payments and Privacy Act Disclosure

Note: Parts, accessories and products as defined with the prefix "Generic" are non genuine and are not approved by the vehicle manufacturer. The use of "Generic" items may affect the warranty provided by the vehicle manufacturer.

The customer/s hereby agree that in the event of default of payment of my debts that the company may disclose all information relating to my/our account to its collection agency for purpose of receiving any or all outstanding amounts.

The customer/s acknowledge that they have the opportunity to read the Dealership Privacy Act if so requested which is readily available upon demand for availability and in public view to the customer within the Dealership.


Payments for deposits for equipment including trucks and machinery up to and including \$2,000 will not attract any additional bank/merchant fee(s) than those already associated with the card or bank. All payments exceeding \$2,000 made by Credit Card are subject to a 1.5% Surcharge over and above the amount charged and you duly authorize such an amount to be charged to the card provided to enable such fee charges. Payments for service and parts accounts or counter cash purchases will be subject to a 1.5% Surcharge over and above the amount charged on the invoice and you/customer/client/ authorized agent or collector duly authorize such an amount to be charged to the card provided to enable such fee charges.

Invoice Total	"Cash On Delivery"
Total Labour	\$840.00
Total Parts	\$0.00
Total Part Sundries	\$0.00
Total Service Sundries	\$0.00
Invoice Total (Excluding GST)	\$840.00
GST	\$84.00
Invoice Total (Including GST)	\$924.00

Direct Bank Payment Details

Account Name: Till Automotive Group Pty Ltd Bank: WBC BSB: 033226 Account: 540721

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.



TILL HINO

1300 446 663

Till Automotive Group Pty Ltd ACN 620 672 611
ATF Till Automotive Group Unit Trust
ABN 81 952 343 665 LMCT: 0011771
11-13 Industrial Pl, Breakwater VIC 3219

Email: service@tillhino.com.au
Visit us online: www.tillhino.com.au

Vehicle ID HINOHOME		Description HINO MOTOR HOME		Key Tag	Service Tax Invoice Number 1424466	
Series		Model		Page 2 of 3	Date 25/02/2021	
Colour	Engine	Trans	VIN 1148305	Engine No.	Fuel Type	
Paint Code	Radio Pin	Manufactured Date	Compliance Date	Manufacturer ID	Date First Registered	Stock Number
Account 51	Order Number	Deal No.	Salesperson	Dealer	Warranty Expiry	Ext Warranty Expiry
Driver Name		Time In 07:30	Time Out 17:00	Date Out 24/02/2021	Odometer 273505	
					Phone 0419393884	

Booking: pratr - Rachel
Advisor: pratr - Rachel
Costing: pratr - Rachel
Finalised: pratr - Rachel
RO: 1307555

JOHN WILMOT

Job No	B/Code	Description	Units	Amount
		Labour		\$840.00

Summary For Job 1


Job 1	Total (Excluding GST)	\$840.00
Job 1	Total (Including GST)	\$924.00

2 R licence number : 027945496, exp 3.8.22

Labour \$0.00

Summary For Job 2

Job 2	Total (Excluding GST)	\$0.00
Job 2	Total (Including GST)	Not Applicable



TILL HINO

1300 446 663

Till Automotive Group Pty Ltd ACN 620 672 611
 ATF Till Automotive Group Unit Trust
 ABN 81 952 343 665 UIC: 0011771
 11-13 Industrial Pl, Breakwater VIC 3219

Email: service@tillhino.com.au
 Visit us online: www.tillhino.com.au

Vehicle ID HINOHOME		Description HINO MOTOR HOME			Key Tag	Service Tax Invoice Number 1424466		
Series			Model			Page 1 of 3	Date 25/02/2021	
Colour	Engine	Trans	VIN 1148305			Engine No.	Fuel Type	
Paint Code	Radio Pin	Manufactured Date	Compliance Date	Manufacturer ID	Date First Registered	Stock Number		
Account 51	Order Number	Deal No.	Salesperson	Dealer	Warranty Expiry	Ext Warranty Expiry	Odometer 273505	
Driver Name			Time In 07:30	Time Out 17:00	Date Out 24/02/2021	Phone 0419393884		

Booking: pratr - Rachel
 Advisor: pratr - Rachel
 Costing: pratr - Rachel
 Finalised: pratr - Rachel
 RO: 1307555

JOHN WILMOT

Job No	B/Code	Description	Units	Amount
1	R	Carried out RWC test- failed due to : PARK BRAKE LIGHT MUST BE RED 3 SIDE CLEARANCE LIGHTS N/W BRAKE LIGHTS N/W NUMBER PLATE LIGHT N/W + LENSES DAMAGED AIR SCOOP CLEARANCE LIGHTS N/W X8 FRONT ROOF CLEARANCE LIGHTS N/W X3 RH HEADLIGHT AIM TOO HIGH LH HEADLIGHT HI-BEAM N/W STARTER MOTOR FAILING RH DRIVER AXLE AIR BAG SIDEWALL CRACKS ALL DRIVE BELTS LOOSE ALTERNATOR BELTS DAMAGE FAN BELTS CRACKED L+R LAZY AXLE TYRES -U/S - SIDEWALL WORN RH PASSENGER SEAT BELT FRAYED FIRE EXTINGUISHER NOT SECURE + OUT OF DATE NO GRIP ON ACCELERATOR PEDAL LH DRIVE AXLE INNER WHEEL RIM ODD BRAKE BACKING PLATES MISSING X11 WIRING ABOVE BATTERY - FIRE HAZARD WIRING ABOVE ENGINE - FIRE HAZARD WIRING BEHIND TAIL LIGHTS LOOSE + NOT SECURE RH FRONT BRAKE DRUM RUBBING ON BACKING PLATE RH + LH FRONT BRAKE LINING UNEVEN WEAR - REPLACE L+R SIDE RH + LH FRONT HUB SEALS LEAKING RH + LH DRIVE AXLE BRAKE LININGS NON MATCHING DESIGN - RELINE +REPLACED AND BRAKE DRUMS HEAT CRACKS TO LARGE HOSE RUBBING ON TAIL SHAFT TRANSMISSION LEAK AT REAR DIFF LEAK AROUND DRAIN RH + LH LAZY AXLE WHEEL HUB SEALS LEAKING RH + LH LAZY BRAKE DRUMS OVERSIZE ENGINE OIL LEAKS - L+R SIDES DRIVE AXLE SWAYBAR L+R TOP AND REAR BUSHES WORN LAZY AXLE L+R UPPER & LOWER SUPPORT ARM BUSHES WORN RH FRONT WHEEL HITS DRAG LINK AT FULL LOCK LEFT LAZY AXLE L+R BRAKE SLACK ADJUSTERS OVER STROKING MULTIPLE AREAS UNDERNEITH WHERE ORING RUBBING ON BRACKETS / METAL EDGES ETC MULTIPLE WIRES CUT OFF ANT NOT INSULATED L+R FRONT WHEEL BEARING LOOSE DRAG LINK - CYLINDER END TIE ROD MOVEMENT LAZY AXLE RH SLACK ADJUSTER HITTING BRACKET		

Certifier's Name	Julian Callahan	Licence No.	100148	Compliance Cert No.	Compliance Cert PIN
				15725326	4738

INSTALLATION ADDRESS			
Site Address	455 BIRREGURRA RD		
Town/Suburb	BIRREGURRA	Post Code	3242

PLUMBING WORK INFORMATION		BELOW GROUND SANITARY DRAINS	
Date of completion of plumbing work	25/05/2021	'As Laid' plans lodged	
Value of plumbing work	Less than \$750	Water Authority 'Consent to Connect' number	

TYPE OF WORK		GAS METER / LPG	
Residential / Commercial	Residential	Authorisation number	

SPECIALITY DETAILS			
Modification details	X	Recreational vehicle's chassis number	1148305
Cooling tower	X	Performance solution	X
6 Star Sustainability	X		

INSTALLATION INFORMATION
Gasfitting

INSTALLATION DETAILS
We tested gas service pipe on bus which passed.

APPLIANCE/PRODUCT INFORMATION

DECLARATION

I certify that the above plumbing work complies in all respects with the plumbing laws as defined in Part 12A of the *Building Act 1993*.

The plumbing work was carried out by me or under my supervision			✓
I have inspected and tested the work started by another licensed practitioner. Any necessary further work was carried out by me or under my supervision			
The above compliance certificate details are correct and ready to be lodged with the VBA			✓
I provide this compliance certificate in accordance with 221ZH(2)(a) of the Building Act 1993 initiating the status of a signed document			✓
Compliance Certificate Status	Lodged	Date Lodged	25/05/2021

IMPORTANT NOTE TO PRACTITIONERS

A misstatement of fact, including an omission, is an offence under the *Building Act 1993*.

This Compliance Certificate must be given to the owner/consumer (or if issued to a building practitioner or person other than the owner/consumer), then that person must give it to the consumer within five (5) days of receipt.

IMPORTANT NOTE TO CONSUMERS

Information on this Compliance Certificate has been given to the Victorian Building Authority (VBA) in accordance with the *Building Act 1993*. The information also assists the VBA for its statutory functions to monitor and enforce compliance under that Act and for statistical purposes in a way that does not identify consumers. At www.vba.vic.gov.au you may view the details of this Compliance Certificate by using the Compliance Certificate number and PIN number in the top right corner of this Compliance Certificate, and also view the VBA's Privacy Policy. All work subject to a Compliance Certificate carries insurance to protect the owner/consumer against defective work by a plumbing practitioner. You should retain your Compliance Certificate for six (6) years as evidence of your cover.



ROADS AND MARITIME SERVICES NSW
HEAVY VEHICLE INSPECTION SCHEME (HVIS)
Inspection Report (Truck, Bus and Trailer)

Inspection Report:

AZ2423546

1. HVIS Location

Site Name

Leeton HVIS

2. Vehicle Class

Truck ☒

Bus ☐

Trailer ☐

Other

3. Reason for Inspection

Renew
Registration ☒

Other (Please Indicate)

4. Replacement Vehicle

☐ Yes

☒ No

Registration Number

The vehicle inspected is a replacement to that originally booked. You must advise the Roads and Maritime Services (RMS) of this change so that inspection credits are deducted from the current vehicle.

5. Vehicle Details

Registration Number

BJ51AR

Odometer Reading

272772

VIN or Chassis

1148305

Vehicle make

HINO

Body type

GOODS VEHICLE - RIGI

6. Inspection Checklist ☒ = pass; ☐ = fail; ☐ = not applicable / not available

VIN / Chassis Number

☒

Brakes

☒

Tow Couplings

☒

Steering

☒

Suspension

☒

Wheels Tyres & Hubs

☒

Structure & Bodywork

☒

Seats & Seatbelts

☒

Lights and Reflectors

☒

Mirrors, Windscreen & Windows

☒

Engine & Driveline

☒

Fuel System

☒

Public Vehicle Fittings

☐

Exhaust System Visual

☒

Exhaust System Detailed (meter)

☐

Modifications

☒

7. Repairs Needed

Defect Notice Issued Yes ☐ No ☒ Defect Notice Numbers

8. Comments

9. IVR Certification

I certify that this is true record of the vehicle's compliance with the inspection standards of the *Rules for Authorised Inspection Stations (Heavy Vehicles)* and *Road Transport (Vehicle Registration) Regulation 2017* or *Heavy Vehicles (Vehicle Standards) National Regulation (NSW)* at the time of inspection and all details are correct.

Inspection

☒ Passed ☐ Failed

IVR Number

1179

Office Number

3613

Date

01/02/2021

Signature

Note: This report indicates whether or not the vehicle met NSW registration standards at the time of inspection. It is not a comprehensive report on the condition of the vehicle, nor is it a guarantee that the vehicle is not stolen. For all types of checks a 'passed' inspection result may be accepted for registration for 3 months after the inspection, except where the RMS is informed that the vehicle is not roadworthy. Any alterations to the details of this report after its issue will render the document invalid.