

YA09-4



J14 23

Date Completed:

Year: 21

Make/Model:

Outlander 850 Serial #: 3JLBKAU45M3007005

Can-Am Inspection/Work Report

Exterior	
Drivers side Body	
Pass side Body	
Front End Body	
Grill/Bumper	
Rear end Body	
Bumper	
Tail Lights	
Roof	
Hood Release	
Windshield	
Side Windows	
Pass Mirror	
Drivers Mirror	
Drivers Front Tire	
Tread	
Sidewall	
Rims	
Pressure	
Pass Front / Tire	
Tread	
Sidewall	
Rims	
Pressure	
Drivers Rear Tire	
Tread	
Sidewall	
Rims	
Pressure	
Pass Rear Tire	
Tread	
Sidewall	
Rims	
Pressure	

Mechanical	
Oil	
Trans Fluid Level	
Brake Fluid	
Coolent Level	
Radiator	
Radiator Hoses	
Belts/Pully's	
Power Steering Fluid/operation	
Washer Fluid	
Battery Connections	
Battery Load Test	
Head Lights Hi/Low	
Turn Signals	
Hazards	
Reverse Lights	
Oil Leaks	
Exhaust System	
Drive Line/U-Joints	
Frame	
Spare Tire	
Brakes/ABS	
Drivers Front	
Brake Pad	
Rotor	
Pass Front	
Brake Pad	
Rotor	
Drivers Rear	
Brake Pad	
Rotor	
Pass Rear	
Brake Pad	
Rotor	

Interior	
Horn	
Dash	
Interior Mirror	
Door Locks	
Tilt Wheel	
No ABS Lights	
Guages	
Radio	
Nav	
Back up Camera	
Wipers	
Heater/A/C	
Driver Seat Belt	
Driver Seat Adj	
Front Seats Condition	
Rear Seats Condition	
Carpets	
Headliner	
Sun Roof	
Park Brake	
4x4 engage Hi/Low	
Engine Starter	
Engine Runs Smooth	

MECHANIC INITIAL

OFFICE INITIAL

TOTAL CHARGE

TOTAL HRS
9 hrsTOTAL PARTS
\$395.06

COMMENTS/REPAIRS REQUIRED	DATE/HOURS
check spark plugs grease job	8 hrs
dielectric grease job brakes all new pads oil change w/ filter engine diff oil change ft and rear	1 hr
T/case oil change new air filter	
clean air box of dirt	

INSPECTOR SIGNATURE: _____

403 228 4696