

E014-79



Mechanical

Whitecloud Mechanical

58030 RR100
PO Box 1098
Saint Paul, AB T0A 3A0
(780) 227-6202
whitecloudmechanical@outlook.com

Invoice for RO #9201

Service Advisor: Lynnal Barton
Date Created: 07/22/25 at 04:13 PM MDT
Client: Location Cats
Vehicle: 2011 Ram 2500 Power Wagon

Location Cats	2011 Ram 2500 Power Wagon 5.7L 8Cyl GAS EZC Naturally Aspirated VIN: 3D7TT2CT0BG570977 License: N/A Unit #: U039-1 Color: N/A Odometer In: 198525 / Out: 198525	RO # 9201 PO # - Time-In: 07/22/25 at 04:13 PM MDT Save Parts: No
Phone:		
Email:		

Client concerns:

- Peace of mind inspection
- Please pay attention to front end suspension, steering and brakes
- Please find aftermarket replacement for broken rear driver's tail light

1 - Peace of mind inspection		
Tech: DR		
Labor:	Perform peace of mind inspection	
✓ Approved on 07/22/25 at 04:14 PM MDT		Subtotal \$145.00 + est. Tax \$7.25 \$152.25

2 - QC Inspection		
Tech: GR		
Labor:	A technician who is not working on the vehicle must go through unit to inspect for any leaks or other repairs that original technician may have missed. Go to inspection page and follow step procedure.	
✓ Approved on 07/22/25 at 04:14 PM MDT		0 0

RO Fees		
Fee:	Shop supplies	\$8.70
Subtotal		\$8.70

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work detailed in this invoice. Partial payments are considered agreement to pay the entirety of the invoice, regardless of whether you have signed the invoice.

if your tires have been removed they must be retorqued at 100km. If you have had Ubolts replaced they must be retorqued at 500km.

All payments are due within 30 days of the invoice date. On commercial there will be 2% interest charged to all outstanding balances over 30 days.

Please send Etransfers to whitecloudmechanical@outlook.com, we do not require a password for etransfers.

GST NUMBER 763748472RT0001

Total Repair Order & Signature:X

Total Jobs:	\$145.00
Total Fees:	\$8.70
Subtotal:	\$153.70
Taxes:	\$7.69
Grand Total:	\$161.39
BALANCE DUE:	\$161.39

Declined Jobs:**1 - Tail Lamps**

Note: Left tail lamp broken

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$168.73 + est. Tax \$8.44

\$177.17**2 - Wiper Blades**

Note: worn

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$112.79 + est. Tax \$5.64

\$118.43**3 - Windshield Condition**

Note: cracked

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$360.50 + est. Tax \$18.03

\$378.53**4 - Diagnose check engine light**

Note: Check engine

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$145.00 + est. Tax \$7.25

\$152.25**5 - Replace Steering linkage**

Note: drag links, tie rod ends, worn

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$952.79 + est. Tax \$47.64

\$1,000.43**6 - Replace right upper and lower ball joints**

Note: Right upper ball joint excessive play, lower and upp control arms have seperating bushings, track bar has some play

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$706.80 + est. Tax \$35.34

\$742.14**7 - Replace upper and lower control arms**

Note: Right upper ball joint excessive play, lower and upp control arms have seperating bushings, track bar has some play

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$1,305.28 + est. Tax \$65.26

\$1,370.54**8 - Replace track bar**

Note: Right upper ball joint excessive play, lower and upp control arms have seperating bushings, track bar has some play

X Declined on 07/24/25 at 11:49 AM MDT

Subtotal \$317.64 + est. Tax \$15.88

\$333.52

9 - Coolant Leaks Note: water pump leaking		
X Declined on 07/24/25 at 11:49 AM MDT	Subtotal \$905.96 + est. Tax \$45.30	\$951.26
10 - Replace both front axle ujoints and front brakes Note: both front axle ujoints missing bearings		
X Declined on 07/24/25 at 11:49 AM MDT	Subtotal \$2,243.93 + est. Tax \$112.20	\$2,356.13
11 - Replace lifters, repair exhaust gasket Note: lifters making noise		
X Declined on 07/24/25 at 11:49 AM MDT	Subtotal \$4,916.89 + est. Tax \$245.84	\$5,162.73
12 - Perform 4x4 service Note: diffs, transmission, transference dirty fluid		
X Declined on 07/24/25 at 11:49 AM MDT	Subtotal \$562.05 + est. Tax \$28.10	\$590.15
13 - Perform transmission service Note: diffs, transmission, transference dirty fluid		
X Declined on 07/24/25 at 11:49 AM MDT	Subtotal \$479.95 + est. Tax \$24.00	\$503.95
14 - Alignment - Automotive Note: Brought unit in, measured all alignment components and adjusted as necessary. Replacing parts is extra		
X Declined on 07/24/25 at 11:49 AM MDT	Subtotal \$145.00 + est. Tax \$7.25	\$152.25



Commercial Vehicle Maintenance / Service Inspection Record


LC-0001

Supplementary For All Vehicles

> 4500 kg, cube van, boom truck, lift deck, service truck, 1 ton deck etc & Light Duty Trucks

✓ = Pass. F = Fail. R = Repaired. N/A = Not Applicable

EQUIPMENT TYPE:		Pickup Truck				UNIT#:		39-1					
		ODOMETER:		193,504km		ENGINE HOURS:		7258		DATE:		July 22/25	
		P	F	R	N/A			P	F	R	N/A		
1	LOCKOUT IN PLACE	✓				20	BATTERY SERVICE / CABLE CONDITION	✓					
2	WHEEL CHOCKS IN PLACE	✓				21	WINDSHIELD	✓					
3	OIL SAMPLES				✓	22	TIRE ROTATION						✓
4	OVERALL CONDITION OF UNIT		✓			23	CLUTCH OPERATION / ADJUSTMENT						✓
5	OIL LEVEL / CONDITION	✓				24	WIPERS	✓					
6	OIL CHANGE STICKER / MAINT. REMINDER RESET	✓				25	ALL FILTERS CHECKED-INCLUDING CAB FILTER	✓					
7	TRANS FLUID LEVEL / CONDITION	✓				26	SPILL KIT PROVIDED FOR VEHICLES WITH HYDRAULICS	✓					
8	FRONT DIFF. FLUID LEVEL / CONDITION	✓				27	SPARE TIRE CONDITION / MOUNTING	✓					
9	REAR DIFF. FLUID LEVEL / CONDITION	✓				28	POWER TAIL GATE OPERATION / FLUID / LEVEL / CONDITION						✓
10	TRANSFER CASE FLUID LEVEL / CONDITION	✓				29	SEAT COVER, BELTS (LEAVE LATCHED) / CONDITION	✓					
11	COOLANT LEVEL / CONDITION	✓				30	LICENCE PLATE CONDITION / STICKER / INSURANCE / REGISTRATION / CVP PAPERWORK / FOSS CARD	✓					
12	P/S FLUID LEVEL / CONDITION	✓				31	FLOOR MATS	✓					
13	BRAKE FLUID LEVEL / CONDITION	✓				32	MUD FLAPS / HANGERS / ANTI SAIL	✓					
14	W.W. FLUID LEVEL / WINTER / SUMMER	✓				33	HUB CAPS	✓					
15	BLOCK HEATER OPERATION / CONDITION	✓				34	OVERALL CONDITION OF BODY & DOORS	✓					
16	COMMAND START OPERATION				✓	35	DOOR HANDLE, TAILGATE HANDLE, TAILGATE CABLES	✓					
17	COMPLETE GREASE OF CHASSIS & ALL ATTACHED EQUIPMENT	✓				36	DEER WHISTLES	✓					
18	TUNE UP CONDITION, SCAN TEST, ALL FILTERS CHECKED / CONDITION	✓				37	BACK UP ALARM, BEACON, LIGHTS, SIGNALS, LAMPS, HORN	✓					
19	BELTS, IDLERS, TENSIONERS, & FAN OPERATION / CONDITION	✓				38	BUGGY WHIP	✓					

	Commercial Vehicle Maintenance / Service Inspection Record	LC-0001
---	---	----------------

Supplementary For All Vehicles


> 4500 kg, cube van, boom truck, tilt deck, service truck, 1 ton deck etc & Light Duty Trucks
 ✓ P = Pass F = Fail R = Repaired N/A = Not Applicable

39	CLEANED EXTERIOR & INTERIOR	✓					48	VERIFY REMOTE STARTER OPERATION (If Equipped)	✓
----	-----------------------------	---	--	--	--	--	----	--	---



	P	F	R	N/A		P	F	R	N/A
40	✓				49				✓
41	✓				50				✓
42	✓				51				✓
43	✓				52				✓
44	✓				53	✓			
45	✓				54	✓			
46	✓				55	✓			
47	✓								

TIRE PRESSURE (if not recorded on prescribed Alberta Inspection Record)				[] psi	[] kPa
LF:		RF:		LR:	
				RR:	

AVR TEST			
VOLTS:		AMPS:	
		RPM:	
		STARTER LOAD TEST	PASS / FAIL

FUEL LEVEL (Mark Level) 	TEST / DRIVE TEST [] or TEST DRIVE [] Comments: <div style="border: 1px solid black; height: 20px; margin-top: 5px;"></div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div style="width: 45%;">Technician (Print Name)</div> <div style="width: 45%;">Technician Signature</div> </div>
---	--

MAINTENANCE REQUIRED/REMARKS: LHS Tail light broken. 5440 oil : 7.5L -changed Engine oil & Filter Eng Filter # 7899(NAPA) -changed air filter Air Filter # 22725 (NAPA)	
--	--

INSPECTION REPORT SIGN-OFF		
 Technician (Print Name)	 Technicians Signature	Supervisors Signature