

firth.ca

PO BOX 191 GRANDE PRAIRIE, AB T8V 3A4 PHONE: (780)876-6709

Our File G01240

TECHNICAL FIELD REPORT

Inspection Date 2025-05-02

_ ...

To: North West Crane Enterprises Ltd

9301 102 Street Clairmont, AB T8X5G8

Attn: Mr. Kyle Hislop

Re:

Inspection of National Truckmount Crane

Model 1800, S/N 294616, Unit PT-7101

Owner: Capstan LaPrairie Work Order: W02889



Visual examinations and magnetic particle inspections were performed on the above-described equipment. The specific items examined and our inspection findings were as follows:

- 1. Front Outriggers and Box Frames no defects noted.
- 2. Rear Outriggers and Box Frames no defects noted.
- 3. Main Frame no defects noted.
- 4. Ring Gear (visual) no defects noted.
- 5. Rotating Frame no defects noted.
- 6. Counterweight Assembly no defects noted.
- 7. Winch Attachment no defects noted.
- 8. Boom Butt Section no defects noted.
- 9. First Boom Intermediate Section no defects noted.
- 10. Second Boom Intermediate Section no defects noted.
- 11. Boom Tip Section no defects noted.
- 12. Sheaves (visual) no defects noted.
- 13. Load Line (spooled) no defects noted.
- 14. 25-Ton SWL Load Block and Hook (S/N 0756295) no defects noted.
- 15. 1/2"-5/8" Wedge Socket no defects noted.

Notes:

BC certification will be provided upon review of completed mechanical and control element inspections.

FORMAL REPORT TO FOLLOW

Inspector:

Darren Kunyk



Appendix



Figure 1: ID tag for record