



Low Stage Work Order Inspection

Increation Date:	00 4F 202F	Unit Number: SS-743		
Inspection Date:	09-15-2025	-		
Approval Status:	Requires Approval	Approved Date:		
Inspected By:	Brent Willey	Approved By:		
Signature:	SI	Approved Signature:		
Received Checklist fro	m Operations? No			
EVALUATIONS				
Building				
	Good / Service Need	ed Comments		
Building Clean in/out				
Roof Hatch in place				
Belly Doors & Latches				
Vents				
Windows and Screens				
Main door condition inch latches	ıding			
D Rings returned with un # in comments	it? Put			
Change overs returned w	rith unit			
Decals	Good / Service Need	ed Comments		
Danger	00007001715017000	TOTAL		
2924				
Methanol				
Manway	,			
Propane				
Hearing Protection				
Miśc Stickers				
Unit #				
Exterior/Skid Paint				
Interior Paint				



Low Stage Work Order Inspection

·	Good / Service Needed	Comments
3" Dirty Side Drain Valve (dwg #5)		
3" Dirty Side Drain Valve (dwg #5)		
3" Dirty Side Cleanout Valve (dwg #7)		
3" Clean Side Drain Valve (dwg #8)		
3" Water Bypass/Oil Box Drain/Dirty Side Blown Down (dwg #9)		
3" Water Drain Valve (dwg #10)		
3" Water Out Valve (dwg #11)		
3" Condensate Out Vaive (dwg #12)		
3" Bypass Water to Condensate Valve (dwg #13)		
3" Water Leg Upstream of Y- Strainer Valve (dwg #14)		
3" Condensate Leg Upstream of Y-Strainer Valve (dwg #15)		
Condensate Leg V-Ball Valve (dwg #20)		
Condensate Leg V-Ball Valve (dwg #21)		
3" Downstream of Turbine, Condensate Leg (dwg #22)		
3" Downstream of Turbine, Water Leg (dwg #23)		
3" Condensate Bypass Valve (dwg #24)		
3" Water Bypass Valve (dwg #25)		
4" Gas Out Upstream of V-Cone Valve (dwg #26)		
2" Gas Out Upstream of V-Cone Valve		
4" Gate Valve (dwg #31)		
2" Dirty Side Sparge Valve (dwg #34)		
2 ⁻ Clean Side Sparge Valve (dwg #35)		

Manways - Vessel Interior

	Good / Service Needed	Comments	
Manway Dirty Side Platform			
Manway Clean Side Platform			
Visual of Sparge			
Visual of Steam line			
Visual of Weir			

Additional Notes:

Tank has been purged and no oilfield solids or liquids in vessel.



Low Stage Work Order Inspection

Visual of Weir:

Additional Photos:





