

**DEVELON**



**ISUZU  
CARE**

**ISUZU  
TRUCKS**

<b>Service TAX Invoice</b>		Page 1 of 3		Reprint# 1		Doc #: <b>ISCT104641</b>		
Customer No. 10262	Customer Name & Address STATE WIDE SHEDS P.O.BOX 809			Advisor LISA STARR	59	Colour	Team SERVICE	
Doc. Date 13/08/25	DUBBO NSW 2830			Year / Make / Model 01/ISUZU/FVR 950 HD LONG		Tag No.		
Reg. No. BM35KP				Model No. FY-8FS02-660		Carlina		Eng./Trans. 6SD1/
Stock No.				Chassis No.	Kilometres 59821	Prod. Date 09/03/01	Orig. Del. Date	
Purchase Order No. 71601	Driver	Contract No.		Contract Name		Contract Exp. Kms	Exp. Date	
<input type="checkbox"/> CASH	Home Phone	Business Phone (02)68844355	Terms 30	Selling Dealer BRISBANE ISUZU		Delivery Kms. 0	Delivery Date 17/08/01	Warr. Exp. Date 16/08/03
<input type="checkbox"/> CHEQUE	Vehicle ID. JALFVR23RY3000080		Engine No. 6SD1 736742	Date & Time Promised 05/08/25 03:30pm		Time Received 08:00am	Quote Price	Air Pwr Turb
<input type="checkbox"/> CREDIT CARD								
<input type="checkbox"/> ACCOUNT								

.about	Operation	Description	Units	Amount
ob# 1	04IS	DRIVE LINE	Tech(s): BO JH	247.50
		<b>REPAIR OIL LEAKS AROUND GEARBOX</b> Washed down transmission and test drove to confirm oil leak. Replaced gasket on range change interlock valve, checked, all ok.		
ob# 2	01ISALL	Minor service	Tech(s): JH	577.50
		<b>Perform minor service</b> Service vehicle according to schedule - Replaced wiper blades - Replace cab marker light as required <b>Customer Instructions:</b> Replaced engine oil & filter/s Replaced fuel filter/s Replaced PCV filter (if applicable) Lubricated all grease points Inspected tailshaft slip-joint, uni and centre bearing condition Inspected and tensioned turbo and manifold bolts Checked intercooler hoses & clamps Inspected front hub oil Inspected coolant hoses for splits, cracks or deterioration Pressure tested cooling system & checked for leaks/pressure loss Inspected air cleaners and cleaned/replaced if necessary Checked brake pipes/hoses for loose connections/damage Checked clutch & brake pedal freeplay and adjustment Checked and adjusted brakes as required Checked and adjusted clutch Checked all fluid levels and reported any leaks Checked operation of all lights, wipers & horn Checked windscreen wiper condition (replaced if req.) Checked battery & terminal conditions and electrolyte levels Inspected front and rear suspension for damage & excess wear Inspected brake linings for wear and adjusted brakes Fitted service sticker & updated service book		
ob# 3	09IS	FUEL AND EXHAUST	Tech(s): BO JH	412.50
		<b>REPAIR FUEL LEAK AT BOTTOM OF TANK</b> Drained fuel tank and removed fuel tank. Sublet welding repair to repair fuel leak on bottom of tank. Replaced R/H side 'J' bracket on fuel tank and refit fuel tank. Refill tank and checked. All Ok.		

**DEVELON**



**ISUZU  
CARE**

**ISUZU  
TRUCKS**

ARC:AU29048  
MVRL23376  
MVRL44199  
MD14037

Service TAX Invoice		Page 2 of 3	Reprint# 1	Doc #: ISCT104641
Customer No. 10262	Customer Name & Address STATE WIDE SHEDS P.O.BOX 809		Advisor LISA STARR 59	Colour
Doc. Date 13/08/25	DUBBO NSW 2830		Year / Make / Model 01/ISUZU/FVR 950 HD LONG	
Reg. No. BM35KP			Model No. FY-8FS02-660	Carline
Stock No.	Contract No.	Contract Name	Kilometres 59821	Prod. Date 09/03/01
Purchase Order No. 71601	Driver	Contract No.	Contract Exp. Kms	Exp. Date
<input type="checkbox"/> CASH <input type="checkbox"/> CHEQUE <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> ACCOUNT	Home Phone	Business Phone (02)68844355	Terms 30	Selling Dealer BRISBANE ISUZU
	Vehicle ID. JALFVR23RY3000080	Engine No. 6SD1 736742	Date & Time Promised 05/08/25 03:30pm	Delivery Kms. 0
			Time Received 08:00am	Delivery Date 17/08/01
			Quote Price	Warr. Exp. Date 16/08/03
			Air	Pwr
			Turb	

ob# 4 03IS ENGINE Tech(s): JH No Charge  
**ENGINE IDLING ROUGH INTERMITTENTLY**  
 Carried out test drive to check engine idling rough, unable to fault on test drive, customer to monitor.

**Total - Labour 1237.50**

Parts	Qty	Number	Description	Unit Price	Amount
ob# 1	1	IS800467386	SHIFT BRAKE	6.31	6.31
ob# 2	1	IS92955815	KIT FILTER	78.87	78.87
ob# 2	2	IS5876100351	BLADE WIPER 550	15.28	30.56
ob# 2	1	IS2026	LAMP CAB MARKER	25.60	25.60
ob# 3	1	IS8983179540	BRACKET FUEL	571.33	571.33
ob# 3	1	IS1225530371	GASKET BRKT TO	56.72	56.72

**Total - Parts 769.39**

Labour	Inv No	PO No	Description	Rec Date	Amount
ob# 3	55A	1S34619	REPAIR TANK	12/08/25	450.00

**Total - Sublet 450.00**

Petrol, Oils, Lubricants and Supplies				Amount
ob# 2	26.5	Isuzu Diesel Gold 15w40		259.57
ob# 2	1.0	Isuzu MP2 Grease Tube		13.58

**Total - POL 273.15**

Miscellaneous			Amount
ob# A	RND	ROUNDING	-0.01
ob# A	TWS	Workshop materials	15.50
ob# A	FRT	Freight recovery	26.15

**Total - Misc 41.64**

**DEVELON**



**ISUZU  
CARE**

**ISUZU  
TRUCKS**

Service TAX Invoice		Page 3 of 3		Reprint# 1		Doc #: ISCT104641	
Customer No. 10262	Customer Name & Address STATE WIDE SHEDS P.O.BOX 809			Advisor LISA STARR	59	Colour	Team SERVICE
Doc. Date 13/08/25	DUBBO NSW 2830			Year / Make / Model 01/ISUZU/FVR 950 HD LONG		Tag No.	
Reg. No. BM35KP				Model No. FY-8FS02-660	Carline		Eng./Trans. 6SD1/
Stock No.	Purchase Order No. 71601			Contract No.	Contract Name	Contract Exp. Kms	Exp. Date
<input type="checkbox"/> CASH	Home Phone	Business Phone (02)68844355	Terms 30	Selling Dealer BRISBANE ISUZU	Delivery Kms. 0	Delivery Date 17/08/01	Warr. Exp. Date 16/08/03
<input type="checkbox"/> CHEQUE	Vehicle ID. JALFVR23RY3000080		Engine No. 6SD1 736742	Date & Time Promised 05/08/25 03:30pm	Time Received 08:00am	Quote Price	Air Pwr Turb
<input type="checkbox"/> CREDIT CARD							
<input type="checkbox"/> ACCOUNT							

**Total Labour** 1237.50  
**Total Parts** 769.39  
**Total POL** 273.15  
**Total Sublet** 450.00  
**Total Misc** 41.64

**Total Tax** 277.17

**Total Invoice** 3048.85

**TOTAL AMOUNT INCLUDING GST**

FOR YOUR CONVENIENCE OUR E.F.T. DETAILS ARE:  
VESTPAC BSB 032646 ACCOUNT 912427  
WE THANK YOU FOR YOUR BUSINESS

**DEVELON**



**ISUZU  
CARE**

**ISUZU  
TRUCKS**

ARC:AU29048  
MVRL23376  
MVRL44199  
MD14037

**Service TAX Invoice** Page 1 of 1 Doc #: **ISCT103730**

Customer No. 10262	Customer Name & Address STATE WIDE SHEDS P.O.BOX 809			Advisor PAUL DONOVAN 101	Colour	Team SERVICE	
Doc. Date 27/05/25	DUBBO NSW 2830			Year / Make / Model 01/ISUZU/FVR 950 HD LONG		Tag No.	
Reg. No. BM35KP				Model No. FY-8FS02-660	Carline		Eng./Trans. 6SD1/
Stock No.	Purchase Order No. 71271			Contract No.	Contract Name	Contract Exp. Kms	Exp. Date
<input type="checkbox"/> CASH	Home Phone	Business Phone (02)68844355	Terms 30	Selling Dealer BRISBANE ISUZU	Delivery Kms. 0	Delivery Date 17/08/01	Warr. Exp. Date 16/08/03
<input type="checkbox"/> CHEQUE	Vehicle ID. JALFVR23RY3000080		Engine No. 6SD1 736742	Date & Time Promised 21/05/25 03:30pm	Time Received 10:30am	Quote Price	Air Pwr Turb
<input type="checkbox"/> CREDIT CARD							
<input type="checkbox"/> ACCOUNT							

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job# 1	03IS	ENGINE	Tech(s): ML	165.00
<b>Diagnose and repair vehicle stuck on full throttle</b>				
Inspected vehicle fault & found speed limiter/throttle cable adjustment incorrect. Adjusted cable correctly test drove truck & confirmed operation ok.				

**Total - Labour 165.00**

Miscellaneous	Amount
---------------	--------

Job# A FRT	Freight recovery	0.00
Job# A TWS	Workshop materials	5.50

**Total - Misc 5.50**

<b>Total Labour</b>	165.00
<b>Total Parts</b>	0.00
<b>Total POL</b>	0.00
<b>Total Sublet</b>	0.00
<b>Total Misc</b>	5.50

**Total Tax 17.05**

**TOTAL AMOUNT INCLUDING GST**

**Total Invoice 187.55**

FOR YOUR CONVENIENCE OUR E.F.T. DETAILS ARE:  
 VESTPAC BSB 032646 ACCOUNT 912427  
 WE THANK YOU FOR YOUR BUSINESS