

Clients Name		Date 7 May 2025	
Make of Trailer JONCO		Model of trailer JON FLIGHT 19RD	
VIN 1U5B503KXD78P0078		Inspection Completed by SOUTHERN CONNECTIONS INC. 1707 19TH AVE.COALDALE AB T1J 1M1 403-795-6622	
Technicians Name			

LPG Gas System		Grey Water System	
✓	Complete gas leak test	✓	All Drains function
✓	LPG Regularor/pigtales checked and adjusted	✓	Holding tanks have no signs of leaking
✓	All pilots function properly	✓	Knife valves function properly
✓	Furnace/blower/thermostate functions	✓	Toilet Functions Properly
✓	Range/oven functions		
✓	Refrigerator Functions on Gas	Fresh Water System	
✓	Water Heater Functions	✓	Complete a water system leak test
✓	Propane tank in date	✓	City water connection working
		✓	Water pump functions properly
		✓	All sink drains checked
		✓	System functions on self contained & city hook-ups
12 Volt Electrical System		Interior Check	
✓	Battery Electrolytes Level Checked	✓	Floor coverings Acceptable
N/A	Hydrometer Reading os 1.280 in all cells	✓	Counter tops Acceptable
✓	Battery connections Clean and Tight	✓	Curtains Acceptable <i>Bedroom only</i>
✓	Converter/fused/circuit breakers working	✓	All door catches function
✓	Interior Lights all working	✓	All windows functioning
	Stop/tum/tail/brakes/ back up lights working	N/A	Exit window Functions
✓	Porch lights working	✓	Exit Window Functions
✓	Smoke Detector	✓	Check all seats/uphostery/ Flooring
✓	LP Detector	✗	Check all window coverings
✓	Range Hood		
✓	Vent Fants Functioning	Exterior Check	
N/A	Refridgerator wring on 12 Volt	✓	Check for any visible damage
✓	Monitor panel working in all functions	✓	window/door/cubby seals in good condition
✓	front/rear electric jacks working	✓	Roof seals in good condition
✓	front leg working	N/A	Slide seal in good condition
✓	Break-away switch functioning	N/A	Side seal in good condition
✓	12 Volt charging ports working	✓	Entry door /locks functions
		✓	Entry Steps functioning
		✓	Cubby interior in good condition
		✓	Cubby latches and locks work
			Decals and skins condition is good
		N/A	Toy hauler door works & party deck in good condition
		N/A	Slide Roof in good conditong
		N/A	Slide moves in and out smoothly and is aligned
110 Volt Electrical			
✓	Converter/fuses/circuit breakers		
✓	interior / exterior Receptacles		
✓	Interior lights		
✓	refridgerator working on 110 Volt		
✓	Air conditioning working		
✓	GFI receptical test		
✓	110 v power cord in good condition		
N/A	Generator operating properly		

	Chassis Check		
		✓	Rock Guard in good condition
		✓	Wheel wells are lined
✓	No apparent undercarriage damage	✓	Hitch/coupler checked
✓	All wheels torques to specification	✓	Stablizing Jacks work
✓	Tire pressure correct		Vent covers in good condition
N/A	Spare Tire pressure correct	✓	Skyllight in good condition
✓	Suspension Checked	✓	Antenna in good condition
✓	Wheel bearings checked		
✓	Brakes pass test		Findings from the Technician
	Accessories Checked		
N/A	Slide Awnings function and good condition		
✓	Awning arms and awning in good condition		
N/A	Stereo/dvd/tv work		
N/A	speakers all function		
✓	Microwave works		
N/A	Solar working and connected correctly		
✓	Batteries connected correctly		

Technician Notes

- ✓ ① INSTALLED 2X NEW PROPANE TANK ✓
- ✓ ② INSTALLED NEW GROUP 27 12V BATTERY ✓
- ✓ ③ REPLACED ALL INTERIOR BULBS WITH LED BULBS Done ✓
- ✓ ④ SMOKE DETECTOR NEEDS BATTERY
- ✓ ⑤ A/C FILTER NEEDS CLEANING CLEANED AND REPLACED ✓
- ⑥ ALL WINDOW COVERINGS MISSING IN LIVING ROOM
- ⑦ 2X CUPBOARD DOORS MISSING
- ⑧ DINING TABLE MISSING
- ⑨ MICROWAVE MISSING TURNTOBE & PLATE
- ⑩ INSTALLED NEW 20LB TANK COVER ✓
- ⑪ REPLACE WHEELS & TIRES ✓

205/75/14