

A08-7



Custom Track Service Percent Worn

FINNING INTERNATIONAL INC.

M PIDHERNEYS INC (CA-0001785)
Rocky Yard

Prepared By: Mike P Friederici Jr.

Model	D6TLGPVP	Inspection Date	23Sep25
Manufacturer	Caterpillar	Next Inspection Date	--
Serial Number	MH700639	Next Inspection Hours	--
Reference Number	7858	<u>Underfoot Conditions</u>	
Hour Meter Reading	8488	Impact	Moderate
Hours Per Week	--	Abrasion	Moderate
Total Odometer Reading	--	Moisture	Moderate
Forward Odometer	--	Packing	Moderate
Reverse Odometer	--	Bushing Allowable Wear	Greater
Distance Per Week	--	Link Allowable Wear	Greater

Track System	Acceptable Range (mm)		Measurement (mm)		Condition	
	Min	Max	Left	Right	Left	Right
Track Sag						
	41.0	51.0	42.0	43.0	Good	Good
Link Roller System						
					5%	5%

Position		Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (mm)		Percent Worn	
Component		Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
Link Assembly		Left: 3913925				Right: 3913925				Pitch: 8 In (203.2 Mm)				Sections: 45	
Track Links		4182091	4182091	Replaced	Replaced	22Sep25	22Sep25	8488	8488	--	--	43.0 (U)	43.0 (U)	0%	0%
Bushing (Ext)		3966615	3966615	Replaced	Replaced	22Sep25	22Sep25	8488	8488	--	--	13.5 (U)	13.5 (U)	0%	0%
Track Shoes		Left Width: 790mm				Right Width: 790mm									
		2944980	2944979	Replaced	Replaced	22Sep25	22Sep25	8488	8488	--	--	77.5 (U)	77.5 (U)	0%	0%
Idlers															
Front		3954326	3954325	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	21.0 (D)	21.0 (D)	<0%	<0%
Rear		3954326	3954325	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	20.5 (D)	21.0 (D)	<0%	<0%
Carrier Rollers															
		2355974	2355974	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	198.0 (C)	197.0 (C)	4%	8%
Track Rollers															
Front	S	3967353	3967353	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	46.6 (U)	46.8 (U)	9%	7%
2	D	3985218	3985218	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	46.8 (U)	47.1 (U)	7%	5%
3	S	3967353	3967353	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	--	--	--	--
	Condition: Guarded					Condition: Guarded									
4	D	3985218	3985218	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	47.0 (U)	47.0 (U)	5%	5%
5	D	3985218	3985218	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	46.9 (U)	46.9 (U)	5%	5%
6	S	3967353	3967353	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	--	--	--	--
	Condition: Guarded					Condition: Guarded									
7	D	3985218	3985218	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	46.9 (U)	47.0 (U)	5%	5%
8	S	3967353	3967353	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	46.9 (U)	46.6 (U)	5%	9%
Sprockets															
		1730946	1730946	Replaced	Replaced	14Jan25	14Jan25	8015	8015	--	--	221.0 (T)	221.0 (T)	21%	21%

(U) Ultrasonic | (C) Caliper | (D) Depth Gauge | (T) Tape | (E) Estimated

Recommendations