FY17-21



Icon Energy Services Ltd. 268 Clearview Drive Red Deer County, Alberta, T4E 0A1 Phone: (403) 340-2225

NDT REPORT

Inspection Date

No.

1-Jun-25

DS-0994

Email: ndt@iconenergyservices.ca					Work Order #	ICE-23	ICE-23952					
10014	NAME OF TAXABLE PARTY.	Serie Philip	NOT THE REAL PROPERTY.			•	PO#		-			
Customer CHALLAND PIPELINE LTD.					Test Method	Test Method AS			ASTM E709			
Branch			Rocky Mou	ıntain House			Inspection Typ	Inspection Type Certification				
Equipment Type Side Boom					Location	Challar	Challand - Yard					
Make			Caterpillar				Procedure	MT ND	MT NDT-0000 Section 4			
Model			D6D				Acceptance St	CSA W	CSA W59/API 8C/ICON Spec			
Capacity			40,000 lbs				Yoke Manufac	Magsw	Magswitch			
Size			-				Yoke Calibration	1-Jun-2	1-Jun-25			
Other		-				Blacklight Man	Blacklight Manufacturer Labino					
OEM S/N		04X06906				Blacklight Calil	Blacklight Calibration 1-Jun-25					
Customer ID -				Lightmeter Manufacturer Spectroline								
Rig/Unit: 126						Lightmeter Cal	ibration	21-Jun	-24			
				Magnetic Parti	Magnetic Particles Powder							
						Material Temp	Material Temp (Celsius) (5°C to 70°C)					
EQUIPMENT					TEST MEDIL	TEST MEDIUM TECHNIQUE			INIQUE			
Hand Yoke		No.	N4846	Alloy Analyzer		No.	Wet	Х	<u>MPI</u>		<u>LPI</u>	
Perm Magnet	Х	No.	31820120287	Hardness Tester		No.	Dry	Х	AC		Water Washable	
Blacklight		No.	35217	UT Detector		No.	Colour Contrast	Х	DC		Post Emulsified	
Coil		No.	C306	UT Probe		No.	Fluorescent		Continuous	Х	Solvent Removable	
Gauss Meter		No.	-	Lightmeter		No. 2181659	Penetrant Dye		Residual		Dwell Time (min)	
Surface Condition Painted				UTX			_	Develop Time (min)				

EXAMINATION:

Magnetic Particle and Visual Examination was performed on 100% of the accessible areas on the items listed above.

PHOTO/NOTES:



RESULTS:

NDT-0401-00

No relevant indications were noted at the time of inspection.

2023-11-08

The results of inspected items reported by the company to the customer represent good faith opinions only and are not to be considered warranties or guarantees of quality, classification or usability of items inspected

Technician Signature Assistant Client Rep/Signature **BRENT WOODS** MT2/XF2/DS1 DARRELL SPENCE CGSB Reg.# 18438 SNT-TC-1A Reg.# 18438 DS1# DS1I_118119022023 Document Information Doc# Rev. Rev. Date Doc Name Reviewer Approver Appr. Date

BW

2023-11-08



ANNUAL INSPECTION - Sideboom Tractor and Boom

Hours:	9361	
Date:	June 1, 2025	

DS-0994

VT=VISUAL MT=MAG PARTICLE

SIDEBOOM TRACTOR	VT MT OK N/A	NOTES		
Boom to Frame Mounting	X X X			
Boom Mount Pins and Retainers	x x			
Counter Weight Mounting/Structure	x x x			
Counter Weight Track/Cylinders	x x			
ROPS Structure	x x		ROPS S/N:	-
SIDEBOOM STICK			SIDEBOOM STI	ск
Boom Sections (Welds)	x x x		Make:	DANLIFT
Boom Sections (Camber/Twist Sweep)	x x		Model:	20' D6D
Boom Hinge	x x x		S/N:	04X06906
Boom Pins/Hardware/Retainers	x x		Capacity:	-
Boom Cathead/Sheave/Pin	x x x			
JIB ATTACHMENT			JIB ATTACHME	NT
Jib Boom Section (Welds)	Т		Make:	- 1
Jib Boom Section (Camber/Twist/Sweep)			Model:	
Jib Pins/Hardware/Retainers	X		S/N:	
old i morrial availar tetalina i				
MAIN LINE BLOCK/RIGGING			BLOCK/HOOK	
Block/Sheave Condition	x x		Make:	-
Hook/Latch Condition	X		Model:	
Hardware/Pins/Retainers	x x		S/N:	
Cable/Rigging/Hardware	x x		Capacity:	-
Winch Mounts/Fasteners/Structure	x x x			
HOIST LINE BLOCK/RIGGING			BLOCK/HOOK	
Block/Sheave Condition	X X		Make:	-
Hook/Latch Condition	x x x		Model:	
Hardware/Pins/Retainers	X X		S/N:	-
Cable/Rigging/Hardware	X X		Capacity:	
Winch Mounts/Fasteners/Structure	x x x			
GENERAL				
Capacity and Controls Clearly Marked	x x			
Anti-Two Block Device	x x			
General Condition/Corrosion	x x			
Load Indicator	x x			
Load Chart	x x			
Comments				
and				
Recommendations				

Document Information								
Doc#	Rev.	Rev. Date	Doc Name	Reviewer	Approver	Appr. Date		
NDT-0510-00	8	2024-11-20	Annual Inspection Checklists	BW	RE	2024-11-20		