



J20-4

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record PRESSURE TEST REPORT						QF-044	
				Tank S/N 10BFA7224DF0C7232		WO No. SV-24059		Rev: 6 Page 1 of 1 Test Date SEPT. 1- 2023			
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7		Mfr BRENNER		Tank Spec DOT407AL		Mfr Date OCT./12		Retest Required On SEPT. 2028			
		Assembler BRENNER		Min Thickness, Heads (in) .293 in		Min Thickness, Shell (in) .223 in		Special Services NO			
Phone No.		Tank Type SUPER B TAIL				Certification Date OCT./12		Original Test Date OCT./12			
Tank is Lined NO	Tank is Insulated YES	Both	Inspection Location WESTLOCK		VIN 10BFA7224DF0C7232			Material 5454-H32			
Owners's Serial No. 22B		TCNR / MDIN / CRN CT0195			Unit No 22B		MAWP 25 PSI		# Compartments 1		
Test Pressure 45 PSI		Test Medium WATER									
PREPARATION		Complies N/A	Concerns	Fails	Re-test after repair	PIPING & ACCESSORIES		Complies N/A	Concerns	Fails	Re-test after repair
1. External & Internal visual (& thickness if required) done		X				1. Assemble hose and piping on unit		X			
2. Select proper gauges and SRV		X				2. Mount test head at top of piping		X			
3. Inspect reclosing vents, inert & red flag		X				3. Press to 80% MAWP&disconnect		X			
COMPARTMENT HYDRO TEST		Complies N/A	Concerns	Fails	Re-test after repair	4. Check for leaks & 10 min retention		X			
1. Mount test head at top. Visible from safe distance		X				5. Bleed off pressure & drain		X			
2. Fill test compartment		X				COMPLETION		Complies N/A	Concerns	Fails	Re-test after repair
3. Pressure up to Test pressure & disconnect hose		X				1. Flush per 300WP		N/A			
4. Check for leaks &/or 10min retention/Bleed of pressure to MAWP/10min retention		X				2. Tag valve & placard if required		N/A			
5. Apply soap water, check for leak and/or Bleed off pressure		N/A				3. Sticker as appropriate		X			
6. Activate vent to confirm set pressure. Bleed off pressure & drain		X				4. Original Wabash file. Copies to owner		X			
PRV		Compartment 1		Compartment 2		PRV Test Report QF-046 Completed and Attached?		MC330/331 / TC331/341/11/51/60 tanks only			
Make GIRARD						1. Is tank QT or NQT		N/A			
Serial Number 74738001007						2. Stress relieved after manufacture? (New Tanks)		N/A			
Set Pressure 30 PSI 2" HG						3. If applicable: Stress relief after repair?		N/A			
Compartment 3		Compartment 4		Compartment 5		Location:		N/A			
						4. Off-truck remote emergency shutdown?		N/A			
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)						TANK VOLUME (LITERS)		29,526			
Current Disposition of Tank Tested											
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☒ Condemned (removed from service) ☐											
CERTIFICATE OF INSPECTION COMPLIANCE We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.											
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93											
Inspector Signature 						Tester Signature 					
Name: MAURY LITKE						Name: JOENARD JOROLAN					
Title: INSPECTOR						Title: TESTER					
Date: SEPT. 1- 2023						Date: SEPT. 1- 2023					