







		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record				QF-042	
				INTERNAL VISUAL / LINING INSPECTION				Rev: 6 PAGE 1 OF 1	
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7		Tank S/N 12-10399		WO No. SV-25223		Inspection Date DEC. 9- 2024			
		Mfr HUTHCHINSON		Tank Spec TC 406 CRUDE		Mfr Date Jun 2012			
Phone No.		Assembler HUTHCHINSON		Min Thickness, Heads (in) 4.39 MM		Min Thickness, Shell (in) 4.39 MM		Retest Required On DEC. 2029	
Tank is Lined		Tank is Insulated		Both NO		Inspection Location WESTLOCK		VIN 2H9AJCHG5DT002399	
Owners's Serial No. T2030		TCRN / MDIN / CRN 10399		Unit No T2030		MAWP 20.7 KPA		Material 5454-H32	
Comments:		Inspection Location WESTLOCK		VIN 2H9AJCHG5DT002399		Material 5454-H32		# Compartments 1	
LINING INSPECTION		Yes		No		N/A		Complies	
Internal lining Inspection		X						N/A	
Comments:								Concerns	
WF MPI: If QT or NQT w/o PWHT: Tank passed Inspection?		Yes		No		N/A		Fails	
Comments:									
INTERNAL VISUAL EXAMINATION		Complies		Concerns					
1. Head surfaces		X							
2. Shell welds, seams and surface		X							
3. Baffle welds and surfaces		X							
4. Manways, signs of leakage		X							
5. Float can		X							
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)									
6. Gauge cans (temp. press.)									
7. Sump									
8. Piping									
9. Nozzle									
10. Internal valves									
11. Dumps									
12. Internal grounding									
13. Overlay patches (None allowed)									
14. Corrosion strips									
- If yes, provide Location									
MC330/331 / TC331/341/11/51/60 tanks only									
1. Is tank QT or NQT									
2. Stress relieved after manufacture? (New Tanks)									
3. If applicable: Stress relief after repair? Complete/Local?									
Location:									
4. Off-truck remote emergency shutdown?									
Current Disposition of Tank Tested									
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☐ Condemned (removed from service) ☐									
CERTIFICATE OF INSPECTION COMPLIANCE									
We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature 									
Name: MAURY LITKE									
Title: INSPECTOR									
Date: DEC. 9- 2024									





		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record EXTERNAL VISUAL INSPECTION				QF-041 Rev: 7 PAGE 1 OF 1							
				Tank S/N 12-10399		WO No. SV-25223		Inspection Date DEC. 9- 2024							
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7 Phone No.				Mfr HUTHCHINSON		Tank Spec TC 406 CRUDE		Mfr Date Jun 2012		Retest Required On Jun 2027					
				Assembler HUTHCHINSON		Min Thickness, Heads (in) 4.39 MM		Min Thickness, Shell (in) 4.39 MM		Special Services NO					
Tank Type TRIDEM TANKER				Certification Date Jun 2012				Original Test Date Jun 2012							
Tank is Lined		Tank is Insulated		Both NO		Inspection Location WESTLOCK				VIN 2H9AJCHG5DT002399		Material 5454-H32			
Owners's Serial No. T2030				TCRN / MDIN / CRN 10399				Unit No T2030		MAWP 20.7 KPA		# Compartments 1			
MARKINGS				Complies		Concerns		EXTERNAL EXAMINATION				Complies		Concerns	
1. TDG Nameplate legible & correct. VIN numbers match				X				1. Barrel weld seams and attachments				X			
2. Placarding provisions				X				2. Hold down bolts and tank mounting				X			
3. Tests/inspections marked on vessel				X				3. Pipe and fittings protected w/ shear section				X			
4. Vapor/Liquid marked correctly.				N/A				4. Structural components, outriggers, crossmembers				X			
5. Railway crossing decal				X				5. Manways; Shell; signs of leakage?				X			
6. Internal Grounding on TC 312/412				N/A				6. Overturn protection adequate				X			
SAFETY DEVICES				Complies		Concerns		7. Bumper&protection adequate: Height must not exceed 30"				X			
1. Primary Venting, press & vacuum				X				8. Level indicator operational				X			
2. Total Vent cap (SCFM)				X				9. Appurtenances on repads				X			
3. Grounding provisions				X				10. Ladder sound and tight				X			
4. Internal self closing stop valve on outlet				X				11. Overlay Patches (None allowed)				NO			
5. Remote emergency shut off for outlets				X				12. Tank wall corroded or abraded				NO			
6. Thermal shut off for outlets				X				13. Condition of hoses and connections				NO			
7. Items 4, 5 & 6 not required on "Crude"				X				MC330/331 / TC331/341/11/51/60 tanks only							
8. Items 3 to 6 not revised, if tank is in class 8 service				N/A				1. Is tank QT or NQT				N/A			
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)								2. Stress relieved after manufacture? (New Tanks)				N/A			
								3. If applicable: Stress relief after repair? Complete/Local?				N/A			
								Location:				N/A			
								4. Off-truck remote emergency shutdown?				N/A			
Current Disposition of Tank Tested															
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☐ Condemned (removed from service) ☐															
CERTIFICATE OF INSPECTION COMPLIANCE We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.															
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93															
Inspector Signature 										Fire Extinguisher Mounted to Unit and Available:					
Name: MAURY LITKE										Complies		Location			
Title: INSPECTOR										X		D/S			
Date: DEC. 9- 2024															

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Report UPPER COUPLER INSPECTION				QF-058	
				Rev: 2		PAGE 1 OF 1			
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7 Phone No.		Tank S/N 12-10399		WO No. SV-25223		Test Date: DEC. 9- 2024			
		Tank Mfr HUTHCHINSON		Tank Spec TC 406 CRUDE		Mfr Date Jun 2012		Retest Required On DEC. 2029	
Assembler HUTHCHINSON		Min Thickness, Heads (in) 4.39 MM		Min Thickness, Shell (in) 4.39 MM		Special Services NO			
		Tank Type TRIDEM TANKER		Certification Date Jun 2012		Original Test Date Jun 2012			
Tank is Lined		Tank is Insulated		Both NO		Inspection Location WESTLOCK		VIN 2H9AJCHG5DT002399	
Material 5454-H32		Owners's Serial No. T2030		TCRN / MDIN / CRN 10399		Unit No T2030		MAWP 20.7 KPA	
# Compartments 1		Trailer Mfr HUTHCHINSON		Trailer Material STEEL		Trailer Mfr Date Jun 2012			
PREPARATION		Complies		Concerns		Fails		Re-test after repair	
1. Trailer Blocked		X							
2. Kingpin Gauge on Hand		X							
UPPER COUPLER		Complies		Concerns		Fails		Re-test after repair	
1. Kingpin 90° ± 1° for 19"		X							
2. Upper Plate Not Down 1/8" at 10"		X							
3. Upper Plate Not Down 1/4" at 19"		X							
4. Upper Plate Not 0.65" within 19"		X							
5. Loose or Missing Bolts		X							
6. Remove Upper Coupler		X							
7. Replace Upper Coupler		X							
1. Corrosion		X							
2. Abrasion		X							
3. Cracks		X							
4. Dents		X							
5. Distortions		X							
6. Weld Defects		X							
7. Other Weakness		X							
8. Repaired as Necessary		X							
COMPLETION		Complies		Concerns		Fails		Re-test after repair	
1. Original Wabash File		X							
2. Copies to Owner		X							
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)									
Current Disposition of Trailer Coupler Tested:									
Returned to Service X					Repair Required ☐				
CERTIFICATE OF INSPECTION COMPLIANCE									
We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature									
									
Name: MAURY LITKE									
Title: INSPECTOR									
Date: DEC. 9- 2024									

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Assurance Record LEAKAGE TEST REPORT				QF-045	
				Tank S/N 12-10399	WO No. SV-25223	Rev: 5	Page 1 of 1		
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7				Mfr HUTHCHINSON	Tank Spec TC 406 CRUDE	Mfr Date Jun 2012	Test Date: DEC. 10- 2024		
Phone No.				Assembler HUTHCHINSON	Min Thickness, Heads (in) 4.39 MM	Min Thickness, Shell (in) 4.39 MM	Retest Required On Jun 2027		
				Tank Type TRIDEM TANKER	Certification Date Jun 2012	Special Services NO			
				Inspection Location WESTLOCK	VIN 2H9AJCHG5DT002399	Original Test Date Jun 2012			
Tank is Lined		Tank is Insulated	Both NO			Material 5454-H32			
Owners's Serial No. T2030		TCRN / MDIN / CRN 10399		Unit No		MAWP 20.7 KPA	# Compartments 1		
Test Pressure		2.5 PSI		Test Medium		WATER			
PREPARATION		Complies N/A	Concerns	Re-test after repair	COMPARTMENT LEAKAGE TEST		Complies N/A	Concerns	
1. External & Internal visual (& thickness if required) done		X			5. Check for leaks & 10 min retention		X		
2. Ensure all valves and plumbing are leak tight		X			6. Bleed of pressure and drain		X		
3. Select proper gauges and SRV		X			COMPLETION		Complies N/A	Concerns	
4. Inspect reclosing vents, inert & red flag		X			1. Flush per 300WPP		X		
COMPARTMENT LEAKAGE TEST		Complies N/A	Concerns	Re-test after repair	2. Tag valve & placard if required		X		
1. Assemble hose and piping on unit		X			3. Sticker as appropriate		X		
2. Mount test head at top. Visible from safe distance		X			4. Original Wabash file. Copy to owner		X		
3. Fill test compartment		X			MC330/331 / TC331/341/11/51/60 tanks only				
4. Press to 80% MAWP & disconnect		X			1. Is tank QT or NQT		N/A		
PRV		Compartment 1	Compartment 2	PRV Test Report QF-046 Completed and Attached?	2. Stress relieved after manufacture? (New Tanks)		N/A		
Make	TIONA VENTED				3. If applicable: Stress relief after repair?		N/A		
Release Pressure	1 PSI				Location:		N/A		
Set Pressure	1 PSI				4. Off-truck remote emergency shutdown?		N/A		
Compartment 3	Compartment 4	Compartment 5		N	TANK VOLUME (LITERS)		38,000		
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)									
Current Disposition of Tank Tested									
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☐ Condemned (removed from service) ☐									
CERTIFICATE OF INSPECTION COMPLIANCE									
We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature				Tester Signature					
									
Name:	MAURY LITKE			Name:	FREDDIE TUBOG				
Title:	INSPECTOR			Title:	TESTER				
Date:	DEC. 10- 2024			Date:	DEC. 10- 2024				




		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record PRESSURE TEST REPORT				QF-044 Rev: 6 Page 1 of 1	
		Tank S/N 12-10399		WO No. SV-25223		Test Date DEC. 10- 2024			
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7 Phone No.		Mfr HUTHCHINSON		Tank Spec TC 406 CRUDE		Mfr Date Jun 2012		Retest Required On DEC. 2025	
		Assembler HUTHCHINSON		Min Thickness, Heads (in) 4.39 MM		Min Thickness, Shell (in) 4.39 MM		Special Services NO	
Tank Type TRIDEM TANKER		Inspection Location WESTLOCK		VIN 2H9AJCHG5DT002399		Certification Date Jun 2012		Original Test Date Jun 2012	
Tank is Lined	Tank is Insulated	Both NO	Material 5454-H32						
Owners's Serial No. T2030		TCRN / MDIN / CRN 10399		Unit No T2030		MAWP 20.7 KPA		# Compartments 1	
Test Pressure 5 PSI		Test Medium WATER							
PREPARATION		Complies N/A	Concerns	Fails	Re-test after repair	PIPING & ACCESSORIES		Complies N/A	Concerns
1. External & Internal visual (& thickness if required) done		X				1. Assemble hose and piping on unit		X	
2. Select proper gauges and SRV		X				2. Mount test head at top of piping		X	
3. Inspect reclosing vents, inert & red flag		X				3. Press to 80% MAWP & disconnect		X	
COMPARTMENT HYDRO TEST		Complies N/A	Concerns	Fails	Re-test after repair	4. Check for leaks & 10 min retention		X	
1. Mount test head at top. Visible from safe distance		X				5. Bleed off pressure & drain		X	
2. Fill test compartment		X				COMPLETION		Complies N/A	Concerns
3. Pressure up to Test pressure & disconnect hose		X				1. Flush per 300WP		X	
4. Check for leaks &/or 10min retention/Bleed of pressure to MAWP/10min retention		X				2. Tag valve & placard if required		X	
5. Apply soap water, check for leak and/or Bleed off pressure		N/A				3. Sticker as appropriate		X	
6. Activate vent to confirm set pressure. Bleed off pressure & drain		X				4. Original Wabash file. Copies to owner		X	
PRV		Compartment 1	Compartment 2		PRV Test Report QF-046 Completed and Attached?	MC330/331 / TC331/341/11/51/60 tanks only 1. Is tank QT or NQT 2. Stress relieved after manufacture? (New Tanks) 3. If applicable: Stress relief after repair? Location: 4. Off-truck remote emergency shutdown?			
Make	TIONS VENTED					N/A			
Release Pressure	1 PSI					N/A			
Set Pressure	1 PSI					N/A			
Compartment 3	Compartment 4	Compartment 5				N/A			
						N/A			
						N/A			
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)					TANK VOLUME (LITERS)		38,000		
Current Disposition of Tank Tested New Tank Entered in to Service ☐ Returned to Service ☐ Repair Required ☐ Condemned (removed from service) ☐									
CERTIFICATE OF INSPECTION COMPLIANCE We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations. Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature 					Tester Signature 				
Name: MAURY LITKE					Name: FREDDIE TUBOG				
Title: INSPECTOR					Title: TESTER				
Date: DEC. 10- 2024					Date: DEC. 10- 2024				



		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record B620 REPAIR REPORT		QF-070 Rev: 0 PAGE 1 OF 1	
		Tank S/N 12-10399		WO No. SV-25223		Inspection Date DEC. 10 - 2024	
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7		Mfr HUTHCHINSON		Tank Spec TC 406 CRUDE		Mfr Date Jun 2012	
		Assembler HUTHCHINSON		Min Thickness, Heads 4.39 MM		Min Thickness, Shell 4.39 MM	
Phone No.		Tank Type TRIDEM TANKER		Certification Date Jun 2012		Retest Required On	
Tank is Lined	Tank is Insulated	Both NO	Inspection Location WESTLOCK	VIN 2H9AJCHG5DT002399		Material 5454-H32	
Owners's Serial No. T2030		TCRN / MDIN / CRN 10399		Unit No T2030		MAWP 20.7 KPA	
						# Compartments 1	

The location of the defect shall be indicated in the table below. The graphical boxes can be used for further clarification, if needed.



LOCATION OF DEFECTS IDENTIFIED		METHOD OF REPAIR	
1	TANK LEAKS BEHIND DOLLY LEGS	1	LOCATE LEAK & WELD UP
2	UPPER COUPLER PULLED DOWN IN CENTER	2	BUILD & INSTALL NEW ONE
3		3	
4		4	
5		5	
6		6	
7		7	
8		8	
9		9	
10		10	
11		11	
12		12	
13		13	
14		14	

Current Disposition of Tank Tested

Returned to Service ☒ Re-test was required ☐ Condemned (removed from service) ☐

CERTIFICATE OF INSPECTION COMPLIANCE

We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.

Wabash Mfg Inc - TC TDG Certificate of Registration #25-93

Inspector Signature		Welder Signature (if repair involved welding)	
Date:	DEC. 10- 2024	DEVIN LLOYD	Weld Procedure
Name:	MAURY LITKE		W-GMAW-AL-1A
Title:	INSPECTOR		
Sign:	