

S17-6
GR-FEB



Trailer Quarterly Inspection



Date	1 AUG 24	Unit	28	CVIP Due	Nov 24
License Plate	SR9-67	Mileage	16385		

✓ Indicates Pass X indicates Fail (Comments must be made on all Failures)

Undercarriage		
1	Inspect for Damage	✓
2	Inspect 5th Wheel Plate & King Pin	✓
3	Inspect Landing Gear	X
4	Inspect Frame & Cross Members (Cracks/Damage)	X
5	Inspect Suspension Components (Damage/Wear)	✓
6	Check Brake Components (Record)	✓
7	Check Brake Operation	✓
8	Adjust Brakes	✓
9	Check Air System (Leaks)	✓
10	Check Wheel bearing, hubs, Seals, Oil Level	✓
11	Grease	✓

Exterior		
1	Check all Lights, Reflectors, Reflective Tape	✓
2	Check Fenders, Mud Flaps	✓
3	License Plate Condition	✓
4	Check Tire Condition (record)	✓
5	Check Tire Pressure (record) Adjust if Necessary	✓
6	Visual inspection of Rims, Studs, Lug Nuts	✓
7	Tires Rotated (Except Wheelers)	✓
8	Torque Wheel Nuts	✓
Secondary Attachments		
1	Signs, Placard holders	✓
2	Tool/Storage Boxes	✓
3	Strap Rollers	✓
4	Tarps, (Inspect, Lube, Confirm Operation)	✓

PSI & Tread Depth

PSI	100	100	100	100	100	100	100	100
32nd	9mm	4mm	5mm	8mm	14mm	14mm	14mm	14mm
	100	100	100	100	100	100	100	100
	8mm	6mm	11mm	11mm	12mm	12mm	4mm	5mm
	100	100	100	100	100	100	100	100
	15mm	15mm	9mm	10mm	10mm	9mm	13mm	14mm

Brake Lining & Travel

Thickness				
Travel				

Comments: DAMAGED pin on Landing leg (repaired).
weld crack on L/H side Front of Trailer

Inspected by: IAN

Signature:



Trailer Quarterly Inspection



Date	28 MAY 2024	Unit	28	CVIP Due	Nov 24
License Plate	SLY9-67	Mileage	15482		

✓ Indicates Pass X indicates Fail (Comments must be made on all Failures)

Undercarriage		
1	Inspect for Damage	✓
2	Inspect 5th Wheel Plate & King Pin	✓
3	Inspect Landing Gear	✓
4	Inspect Frame & Cross Members (Cracks/Damage)	✓
5	Inspect Suspension Components (Damage/Wear)	✓
6	Check Brake Components (Record)	✓
7	Check Brake Operation	✓
8	Adjust Brakes	✓
9	Check Air System (Leaks)	✓
10	Check Wheel bearing, hubs, Seals, Oil Level	✓
11	Grease	✓

Exterior		
1	Check all Lights, Reflectors, Reflective Tape	X
2	Check Fenders, Mud Flaps	X
3	License Plate Condition	X
4	Check Tire Condition (record)	✓
5	Check Tire Pressure (record) Adjust if Necessary	✓
6	Visual inspection of Rims, Studs, Lug Nuts	X
7	Tires Rotated (Except Wheelers)	✓
8	Torque Wheel Nuts	✓
Secondary Attachments		
1	Signs, Placard holders	✓
2	Tool/Storage Boxes	✓
3	Strap Rollers	✓
4	Tarps, (Inspect, Lube, Confirm Operation)	✓

PSI & Tread Depth

PSI	100	100	100	100	100	100	100	100
32nd	9	6	6	8	14	14	14	14
	100	100	100	100	100	100	100	100
	10	8	12	12	13	13	5	6
	100	100	100	100	100	100	100	100
	14	13	10	14	11	10	15	15

Brake Lining & Travel

Thickness	8	9	7	8
Travel	1 1/2	1 1/4	1 1/2	1 1/4
	10	10	9	9
	1 1/2	1 1/2	1 1/2	1 1/2
	7	8	8	7
	1 1/2	1 1/2	1 1/2	1 1/2

Comments:

Rear lights inop
Missing R/H/R Mud Flap
License plate light inop
Replaced R/H centre axle wheel rim

Inspected by: IAN

Signature: _____