

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



J26-28
 MAY

HIGHWAY TANK LEAKAGE "K" INSPECTION REPORT

Account#	41	NEXT REQUIRED INSF	Feb-27
OWNER	Neway Oilfield Services	UNIT#	329
ADDRESS	Rocky Mountain House, Alberta	MFG'S SERIAL#	4934
DATE	February 12/2026	DATE OF MFG	03/2006
TELEPHONE	403-846-6954	TANK SPECIFICATION	DOT 407
TANK MFG	Tremcar Inc.	COMPART/CAPACITY	32,000 Liter's
MEDIUM	Pneumatic	MAWP	35 PSI
VISCOSITY		1 80% OF MAWP	28 PSI
TANK ASSEMBLER	Tremcar Inc.	TCRN/MDIN	N/A

Areas of Inspection	Pass		
	Yes	No	N/A
Venting that relieves at less than test pressure closed or inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hose tested to 75 psi or 120% of marked MAWP which ever is greater	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Piping are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Valves are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No leakage detected after pressure maintained for 5 minutes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector: Greg Mulligan

Disposition Statement: Return to Service

Signature

Repair performed:

Defects observed:

Comments:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK THICKNESS "T" TEST REPORT

Account#	41	NEXT REQUIRED INSPECTION	Feb-31
OWNER	Neway Oilfield Services	UNIT#	329
ADDRESS	Rocky Mountain House,	MFG'S SERIAL#	4934
DATE	February 12/2026	DATE OF MFG	03/2006
TELEPHONE	403-846-6954	TANK SPECIFICATION	DOT 407
TANK MFG	Tremcar Inc.	COMPART/CAPACITY	32,000 Liter's
Head Material Thickness		Not Listed	MINIMAL 3.56 M.M.
Shell Material Thickness		Not Listed	MINIMAL 3.28 M.M.
Tank Assembler	Tremcar Inc.	TCRN/MDIN	N/A
Testing Device Serial #		TT0001	
Testing Device thickness respond		4.00 MM	
Calibrated Date / Expiry Date		SELF CALB. / STEP BLOCK	

Areas of Inspection	Minimum M.M.	Pass		
		Yes	No	N/A
Head.	4.07 M.M.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shell.	3.43 M.M.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Piping.	N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Underside of the tank.	3.43 M.M.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Calibrated Date / Expiry Date.	February 12/2026	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Around Upper Coupler.	N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Nominal Liquid Level Lines.	N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Shell Reinforcements / Repads.	N/A.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Inspector: Greg Mulligan
 Special Service of Tank : Standard Service
 Repair Performed

Disposition Statement: Return To Service

Signature

Defects Observed

Comment:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK EXTERNAL "V" INSPECTION REPORT

Account#	41	NEXT REQUIRED INSPECTION	Feb-27
OWNER	Neway Oilfield Services	UNIT#	329
ADDRESS	Rocky Mountain House, Albr	MFG'S SERIAL#	4934
DATE	February 12/2026	DATE OF MFG	03/2006
TELEPHONE	403-846-6954	TANK SPECIFICATION	DOT 407
TANK MFG	Tremcar Inc.	COMPART/CAPACITY	32,000 Liter's
TANK ASSEMBLER	Tremcar Inc.	TCRN/MDIN	N/A

Areas of Inspection	PASS			Description of Defect	Repaired	
	Yes	No	N/A		Yes	No
Data plate legible and correct	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Accident damage protection (Roll - Over & Bumper etc)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Support Structure (cradle, bolster, frame & sills)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Corrosion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Dents and Cracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Welds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Gaskets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Flange Retainers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Fittings/Nozzles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Valves Operational & Leak Proof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Emergency Devices Operational	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PS Front Thermal Protection Missing	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRV/Vents Tested	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Visual Pass	<input type="checkbox"/>	<input type="checkbox"/>
Tank Identification & Markings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Piping & Hoses voids free of residue, unplugged, no leakage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Fixed & hard plumbed hoses free of exposed reinforcement, kinks, flatness or permanently deformed wire braids, soft spots, damaged or loose fittings, missing bolts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Manhole Tightening Devices Operable	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Relief devices tested, reinstalled & operative	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Visual Pass	<input type="checkbox"/>	<input type="checkbox"/>
Manhole Covers Leak Proof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Hose Identification, test markings are legible, test dates, tank markings applied	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	No Hose's on Unit.	<input type="checkbox"/>	<input type="checkbox"/>

Comments

Signature

Box 247 Rocky Rapids, AB
 Inspector: Greg Mulligan.

Standard Service
 Disposition Statement: Return To Service