

Cardon Auto Repair Service

Cardon Auto Repair Service

(780) 963-8288

chevpartsguy@hotmail.com

1102 B Yellowhead Highway, AB-16, Parkland County, AB, Canada, T7Y 0G1

Business/GST#: 838676294

A28-1
MAY

Invoice # 51228

Against Estimate#: 11474

Created: Jul 16, 2025

Invoiced: Jul 18, 2025

Cam Janke

1979 Ford F-150

VIN: X15JKFC5646

Mileage: 38729 km

License Plate:

Out of Province Inspection

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Out Of Province Inspection- Automotive & Light Truck	Out of Province Inspection	\$190.00	1	\$190.00
			Amount: \$190.00	Disc: \$0.00	Subtotal: \$190.00

Belt installation

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Replace Alternator belt	Remove power steering belt to access alternator steering belt. Install new alternator belt and install original power steering belt	\$150.00	0.8	\$120.00
2	257350 Alternator Belt	Alternator belt	\$38.14	1	\$38.14
			Amount: \$158.14	Disc: \$0.00	Subtotal: \$158.14

Front Brake Repair

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Brake Job Front	Install front brake pad set, Front brake hose and front brake rotors.. Includes repack f front wheel bearings	\$150.00	3	\$450.00
2	PF7013AM Front brake pad set		\$65.10	1	\$65.10
3	4885555 Front brake rotor	Front brake rotor	\$225.75	2	\$451.50
4	36748 Passenger side front brake hose	Passenger side front brake hose	\$32.55	1	\$32.55
5	36749 Drivers side front brake hose	Drivers side front brake hose	\$32.55	1	\$32.55

Cardon Auto Repair Service

Cardon Auto Repair Service

(780) 963-8288

chevpartsguy@hotmail.com

1102 B Yellowhead Highway, AB-16, Parkland County, AB, Canada, T7Y 0G1

Business/GST#: 838676294

Invoice # 51228

Against Estimate#: 11474

Created: Jul 16, 2025

Invoiced: Jul 18, 2025

6	Brake Fluid Dot 3	\$8.50	1	\$8.50
7	Front Wheel Seals-19743	\$18.05	2	\$36.10
		Amount: \$1,076.30	Disc: \$0.00	Subtotal: \$1,076.30

Front brake caliper replacement

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Replace front brake calipers	Replace front brake calipers.(With front brake job)	\$150.00	0.8	\$120.00
2	2221XA Passenger side front brake caliper	Passenger side front brake caliper	\$86.80	1	\$86.80
3	2221XB Drivers side front brake caliper	Drivers side front brake caliper	\$86.80	1	\$86.80
		Amount: \$293.60	Disc: \$0.00	Subtotal: \$293.60	

Rear drum replacement

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Replace rear brake drums	Replace rear brake drums. Re-adjust brake shoes	\$150.00	1	\$150.00
2	4401455 Rear brake drum	Rear brake drum	\$187.50	2	\$375.00
		Amount: \$525.00	Disc: \$0.00	Subtotal: \$525.00	

Burnish in new brake system

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Burnish new brakes	Drive vehicle. apply brakes from 60 KPH to 8 KPH for 15 brake applications to "Break in" new brake pads and rotors.	\$150.00	0.5	\$75.00
		Amount: \$75.00	Disc: \$0.00	Subtotal: \$75.00	

Cardon Auto Repair
Service

Cardon Auto Repair Service

(780) 963-8288

chevpartsguy@hotmail.com

1102 B Yellowhead Highway, AB-16, Parkland County,
AB, Canada, T7Y 0G1

Business/GST#: 838676294

Invoice # 51228

Against Estimate#: 11474

Created: Jul 16, 2025

Invoiced: Jul 18, 2025

Service Amount	\$2,318.04
Part	\$1,213.04
Labor	\$1,105.00
Total RO Fees	
Shop supplies	\$110.50
Environmental Fee	\$6.00
Subtotal	\$2,434.54
Taxes (Sales Tax - 5%)	\$121.76
Grand total	\$2,556.30
Paid to date	\$2,556.30
Remaining Balance	\$0.00

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature:

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information

VIN	X	1	5	J	K	F	C	5	6	4	6				
-----	---	---	---	---	---	---	---	---	---	---	---	--	--	--	--

Make	Model	Year	Odometer
Ford	Lgt Convtnl F	1979	38723

Customer Information

Last Name	First Name
Janke	Cam

Address	Postal Code
54022 Rge Rd 275	T7X3V4

Section 1 - Pre-Inspection

Component	P	F	NA	Component	P	F	NA
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓		
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓		
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓		
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓		
1.3a. CV Joint Road Test Result			✓	1.3g. Odometer (if equipped) Operation	✓		
1.3b. Universal Joint Road Test Result	✓						

NOTES:

Section 2 - Onboard Diagnostic Systems

Component	P	F	NA	Component	P	F	NA
2.1a. PCM Codes Present			✓	2.4b. SRS Lamp Fails To Illuminate			✓
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate			✓	2.4c. SRS Lamp Remains Illuminated			✓
2.2a. ABS Codes Present			✓	2.4d. Airbag(s) Present			✓
2.2b. ABS Lamp Fails to Illuminate			✓	2.4e. Airbag Cover Integrity			✓
2.2c. ABS Lamp Remains Illuminated			✓	2.5. Electronic Stability Control (ESC)			✓
2.3a. Brake System Warning Lamp Fails to Illuminate	✓			2.6. Powertrain Warning Lamps			✓
2.3b. Brake System Warning Lamp Remains Illuminated	✓			2.7. Other Safety Systems			✓
2.4a. SRS Codes Present			✓				

NOTES:

Section 3 - Interior

Component	P	F	NA	Component	P	F	NA
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓		
3.2. Rear View Mirror	✓			3.12. HVAC	✓		
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓		
3.4. Horn	✓			3.14. Accelerator	✓		
3.5. Seats	✓			3.15. Service Brake Pedal	✓		
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly			✓
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓		
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓		
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout			✓
3.10. Auxiliary Lamp Indicator(s)			✓				

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass							
Component	P	F	NA	Component	P	F	NA
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓		
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓		
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓		
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓		
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass			✓

NOTES:

Section 5 - Lamps							
Component	P	F	NA	Component	P	F	NA
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓		
5.2. Daytime Running Lamps			✓	5.8. Rear Side Marker Lamps	✓		
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓		
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓		
5.5. Auxilliary Lamps				5.11. Emergency Lighting			✓
5.6. Front Side Marker Lamps	✓						

NOTES:

Section 6 - Exterior, General							
Component	P	F	NA	Component	P	F	NA
6.1. Fuel Cap	✓			6.3. Bumpers	✓		
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation			✓

NOTES:

Section 7 - Under Hood							
Component	P	F	NA	Component	P	F	NA
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder			✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓		
7.3. Remote Starter Operation			✓	7.9. Exhaust Manifold(s)	✓		
7.4. Battery	✓			7.10. Oil Leaks	✓		
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓		
7.6. Brake Master Cylinder	✓						

NOTES:

Section 8 - Steering and Suspension							
Component	P	F	NA	Component	P	F	NA
8.1. Wheel Bearings	✓			8.8. Steering Gear	✓		
8.2. Ball Joints (front and rear)			✓	8.9. Rack & Pinion			✓
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓		
8.4. Pitman Arm	✓			8.11. Control Arms	✓		
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓		
8.6. Steering Stabilizer / Damper			✓	8.13. Springs	✓		
8.7. Steering Shaft Assembly	✓						

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF:8 mm,RF:8 mm,LR:8 mm,RR:8 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		

NOTES:

Section 10 - Brakes							
Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:280.01 mm,RR:280.05 mm	✓		
10.2. Park Brake Lining- LR:6 mm,RR:6 mm	✓			10.6. Brake Rotor Thickness- LF:30.10 mm,RF:30.11 mm	✓		
10.2. Brake Lining- LF:10 mm,RF:10 mm,LR:6 mm,RR:6 mm	✓			10.7. Brake Drum Condition (general)	✓		
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Drum- LR:280.01 mm,RR:280.05 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						

NOTES:

Section 11 - Under Vehicle							
Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #5863797)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection

2025/07/18


Technician Number

A3153

Facility Number

18045

Signature



Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the Initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/07/18

Customer Signature

