

M12-12  
JUN

G&D Tank Testing and Repair  
Box 247 Rocky Rapids, AB  
1-780-898-0962  
TC Canada Reg. # TC-25-1247



### HIGHWAY TANK INTERNAL "I" INSPECTION REPORT

<b>Account#</b>	16	<b>NEXT REQUIRED INSPECTION</b>	May.2027
<b>OWNER</b>	KMC Oilfield Services	<b>UNIT#</b>	TT-41
<b>ADDRESS</b>	Spruce Grove, AB	<b>MFG'S SERIAL#</b>	CF40122
<b>DATE</b>	May. 17 2022	<b>DATE OF MFG</b>	May. 2013
<b>TELEPHONE</b>	780-960-2129	<b>TANK SPECIFICATION</b>	TC-407
<b>TANK MFG</b>	Lazer Inox	<b>COMPART/CAPACITY</b>	44000 L
<b>Tank Assembler</b>	Lazer Inox	<b>TCRN/MDIN</b>	14400

Areas of Inspection	Pass			Description of Defect	Repaired	
	Yes	No	N/A		Yes	No
Corrosion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Dents and Cracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Welds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Gaskets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Flange Retainers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Baffles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Bulkheads	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Insulated	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Lining	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Internal Piping	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>

Comments: No Defects Found

Special Service of Tank: Standard Service  
Disposition Statement: Return to Service

Inspector: Shawn Lauer

Signature:

G&D Tank Testing and Repair  
 Box 247 Rocky Rapids, AB  
 1-780-898-0962  
 TC Canada Reg. # TC-25-1247



**HIGHWAY TANK HYDROSTATIC "P" INSPECTION REPORT**

<b>Account#</b>	16	<b>NEXT REQUIRED INSPECTION</b>	May.2027
<b>OWNER</b>	KMC Oilfield Services	<b>UNIT#</b>	TT-41
<b>ADDRESS</b>	Spruce Grove, AB	<b>MFG'S SERIAL#</b>	CF40122
<b>DATE</b>	May. 17 2022	<b>DATE OF MFG</b>	May. 2013
<b>TELEPHONE</b>	780-960-2129	<b>TANK SPECIFICATION</b>	TC-407
<b>TANK MFG</b>	Lazer Inox	<b>COMPART/CAPACITY</b>	44000 L
<b># OF COMPARTMENTS</b>	1	<b>DIGITAL MONOMETER SERIAL#</b>	N/A
<b>MEDIUM</b>	Water.	<b>GAUGE SERIAL #</b>	SWD001/SWD002
<b>TANK ASSEMBLER</b>	Lazer Inox	<b>TCRN/MDIN</b>	14400

HYDRO TEST PRESSURE AS PER TABLE 7.3: 40 P.S.I

\*All surfaces must be inspected under test pressure and domes completely filled with test medium. Please ensure that adjacent compartments are empty.\*

Procedure Check List	Yes	No	N/A	Comments
Fittings: Hose & Piping	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
All Closures in Place	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Relief devices inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Valves Closed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Heat/Refrigerant lines at Atmospheric Pressure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Pressure regulator adjusted & tested	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Test Pressure stable for minimum 10 minutes:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Compartment 1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Compartment 2	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A
Compartment 3	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A
Relief devices inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Tank returned to Service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A

Comments: No Defects Found

Disposition Statement: Return to Service

Inspctor: Shawn Lauer

Signature: