



M12-23
 JUN

HIGHWAY TANK EXTERNAL "V" INSPECTION REPORT

Account#	17	NEXT REQUIRED INSPECTION	June. 2027
OWNER	KMC Oilfield Services	UNIT#	TT-43
ADDRESS	Spruce Grove, AB	MFG'S SERIAL#	CF40406
DATE	June. 3, 2026	DATE OF MFG	July. 2013
TELEPHONE	780-960-2129	TANK SPECIFICATION	TC-407
TANK MFG	Lazer Inox	COMPART/CAPACITY	43000 L
TANK ASSEMBLER	Lazer Inox	TCRN/MDIN	14300

Areas of Inspection	PASS			Description of Defect	Repaired	
	Yes	No	N/A		Yes	No
Data plate legible and correct		✓		Weld cert plates back on	✓	
Accident damage protection (Roll - Over & Bumper etc)	✓	□	□	N/A	□	□
Support Structure (cradle,bolster,frame &sills)	✓	□	□	N/A	□	□
Corrosion	✓	□	□	N/A	□	□
Dents and Cracks	✓	□	□	N/A	□	□
Welds	✓	□	□	N/A	□	□
Gaskets	✓	□	□	N/A	□	□
Flange Retainers	✓			N/A		
Fittings/Nozzles	□	✓	□	Rear vent line camlock leaking from threads	✓	□
Valves Operational & Leak Proof	□	✓	□	Vent valves and belly valves leaking	✓	□
Emergency Devices Operational	✓	□	□	N/A	□	□
PSV/Vents Tested	✓	□	□	N/A	□	□
Tank Identification & Markings	✓	□	□	N/A	□	□
Piping & Hoses voids free of residue, unplugged, no leakage	✓	□	□	N/A	□	□
Fixed & hard plumbed hoses free of exposed reinforcement, kinks, flatness or permanently deformed wire braids, soft spots, damaged or loose fittings, missing bolts	✓	□	□	N/A	□	□
Manhole Tightening Devices Operable	✓	□	□	N/A	□	□
Relief devices tested, reinstalled & operative	✓	□	□	N/A	□	□
Manhole Covers Leak Proof	✓	□	□	N/A	□	□
Hose Identification, test markings are legible, test dates, tank markings applied	□	□	✓	No Hoses Present at Time of Inspection	□	□

Comments: Welded cert plates back on, Replaced rear vent line camlock, replaced vent valves and belly valves.

Special Service of Tank: Standard Service
Disposition Statement: Returned to Service
Inspector: Shawn Lauer

Signature:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK LEAKAGE "K" INSPECTION REPORT

Account#	17	NEXT REQUIRED INSPECTION	June. 2027
OWNER	KMC Oilfield Services	UNIT#	TT-43
ADDRESS	Spruce Grove, AB	MFG'S SERIAL#	CF40406
DATE	June. 3, 2026	DATE OF MFG	July. 2013
TELEPHONE	780-960-2129	TANK SPECIFICATION	TC-407
TANK MFG	Lazer Inox	COMPART/CAPACITY	43000 L
MEDIUM	Air	MAWP	30 PSI
VISCOSITY	1	80% OF MAWP	24 PSI
TANK ASSEMBLER	Lazer Inox	TCRN/MDIN	14300

Areas of Inspection	Pass		
	Yes	No	N/A
Venting that relieves at less than test pressure closed or inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hose tested to 75 psi or 120% of marked MAWP which ever is greater	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Piping are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Valves are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No leakage detected after pressure maintained for 5 minutes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: See External Inspection Report

Defects observed:

Repairs performed:

Disposition Statement: Returned to Service

Signature:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK INTERNAL "I" INSPECTION REPORT


Account#	17	NEXT REQUIRED INSPECTION	June. 2031
OWNER	KMC Oilfield Services	UNIT#	TT-43
ADDRESS	Spruce Grove, AB	MFG'S SERIAL#	CF40406
DATE	June. 3, 2026	DATE OF MFG	July. 2013
TELEPHONE	780-960-2129	TANK SPECIFICATION	TC-407
TANK MFG	Lazer Inox	COMPART/CAPACITY	43000 L
Tank Assembler	Lazer Inox	TCRN/MDIN	14300

Areas of Inspection	Pass			Description of Defect	Repaired	
	Yes	No	N/A		Yes	No
Corrosion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Dents and Cracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Welds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Gaskets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Flange Retainers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Baffles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Bulkheads	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Insulated	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Lining	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Internal Piping	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>

Comments: No Defects Found

Special Service of Tank: Standard Service
 Disposition Statement: Return to Service

Inspector: Shawn Lauer

Signature: 

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK HYDROSTATIC "P" INSPECTION REPORT

Account#	17	NEXT REQUIRED INSPECTION	June. 2031
OWNER	KMC Oilfield Services	UNIT#	TT-43
ADDRESS	Spruce Grove, AB	MFG'S SERIAL#	CF40406
DATE	June. 3, 2026	DATE OF MFG	July. 2013
TELEPHONE	780-960-2129	TANK SPECIFICATION	TC-407
TANK MFG	Lazer Inox	COMPART/CAPACITY	43000 L
# OF COMPARTMENTS	1	DIGITAL MONOMETER SERIAL#	N/A
MEDIUM	Water.	GAUGE SERIAL #	SWD001/SWD002
TANK ASSEMBLER	Lazer Inox	TCRN/MDIN	14300

HYDRO TEST PRESSURE AS PER TABLE 7.3: 45 P.S.I

All surfaces must be inspected under test pressure and domes completely filled with test medium. Please ensure that adjacent compartments are empty.

Procedure Check List	Yes	No	N/A	Comments
Fittings: Hose & Piping	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
All Closures in Place	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Relief devices inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Valves Closed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Heat/Refrigerant lines at Atmospheric Pressure	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Pressure regulator adjusted & tested	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Test Pressure stable for minimum 10 minutes:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Compartment 1	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A
Compartment 2	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A
Compartment 3	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A
Tank returned to Service	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A

Comments: See External Inspection Report

Disposition Statement: Return to Service

Inspctor: Shawn Lauer

Signature:



HIGHWAY TANK THICKNESS "T" TEST REPORT

Account#	17	NEXT REQUIRED INSPECTION	June. 2031
OWNER	KMC Oilfield Services	UNIT#	TT-43
ADDRESS	Spruce Grove, AB	MFG'S SERIAL#	CF40406
DATE	June. 3, 2026	DATE OF MFG	July. 2013
TELEPHONE	780-960-2129	TANK SPECIFICATION	TC-407
TANK MFG	Lazer Inox	COMPART/CAPACITY	43000 L
Head Material Thickness:	4.76 MM	HEAD MINIMAL:	4.03 MM
Shell Material Thickness:	3.43 MM	SHELL MINIMAL:	3.28 MM
Tank Assembler	Lazer Inox	TCRN/MDIN	14300
Testing Device Serial # TT02 - ZX-6			
Testing Device thickness respond: 4.00 MM			
Calibrated Date / Expiry Date:		Self Calibrated June. 3, 2026/ Step Block	

Areas of Inspection	Minimum Reading (inches)	Pass		
		Yes	No	N/A
Shell	<input checked="" type="checkbox"/> 3.49 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Head	<input checked="" type="checkbox"/> 4.30 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Piping	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Underside of the tank	<input checked="" type="checkbox"/> 3.51 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Corroded Areas	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Around Upper Coupler	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Nominal Liquid Level Lines	<input checked="" type="checkbox"/> 3.50 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shell Reinforcements / Repads	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments: No Defects Found

Defects Observed:

Repair Performed:

Special Service of Tank: Standard Service
Disposition Statement: Return to Service
Inspector: Shawn Lauer

Signature: 

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK UPPER COUPLER "UC" INSPECTION REPORT

Account#	17	NEXT REQUIRED INSPECTION	June. 2031
OWNER	KMC Oilfield Services	UNIT#	TT-43
ADDRESS	Spruce Grove, AB	MFG'S SERIAL#	CF40406
DATE	June. 3, 2026	DATE OF MFG	July. 2013
TELEPHONE	780-960-2129	TANK SPECIFICATION	TC-407
TANK MFG	Lazer Inox	COMPART/CAPACITY	43000 L
TANK ASSEMBLER	Lazer Inox	TCRN/MDIN	14300

Remove Upper Coupler from Tank prior to Inspection

Inspection Criteria	Comments	Pass		
		Yes	No	N/A
Corroded areas	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Abraded areas	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cracks	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dents	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Distortions	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Defects in welds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Other unsafe conditions	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: Removed and Installed With Hardware by customer
 Inspected by G&D

Repair Performed:

Defects Observed:

Special Service of Tank: Standard Service

Disposition Statement: Returned to Service

Inspector: Shawn Lauer

Signature: