

G&D Tank Testing and Repair  
 Box 247 Rocky Rapids, AB  
 1-780-898-0962  
 TC Canada Reg. # TC-25-1247



M12-44  
 JUN

**HIGHWAY TANK THICKNESS "T" TEST REPORT**

<b>Account#</b>	4	<b>NEXT REQUIRED INSPECTION</b>	June. 2031
<b>OWNER</b>	KMC Oilfield Services	<b>UNIT#</b>	189
<b>ADDRESS</b>	Spruce Grove, AB	<b>MFG'S SERIAL#</b>	2W91A1823CKN50340
<b>DATE</b>	June. 3, 2026	<b>DATE OF MFG</b>	Jan. 2012
<b>TELEPHONE</b>	780-960-2129	<b>TANK SPECIFICATION</b>	TC-407 AL
<b>TANK MFG</b>	Wabash MFG INC	<b>COMPART/CAPACITY</b>	22710 L
<b>Head Material Thickness:</b>	9.53 MM	<b>HEAD MINIMAL:</b>	7.01 MM
<b>Shell Material Thickness:</b>	6.35 MM	<b>SHELL MINIMAL:</b>	5.79 MM
<b>Tank Assembler</b>	Wabash MFG INC	<b>TCRN/MDIN</b>	407-AL-025-78
<b>Testing Device Serial #</b>	TT02 - ZX-6		
<b>Testing Device thickness respond:</b>	4.00 MM		
<b>Calibrated Date / Expiry Date:</b>	Self Calibrated June. 17, 2026/ Step Block		

Areas of Inspection	Minimum Reading (inches)	Pass		
		Yes	No	N/A
Shell	<input checked="" type="checkbox"/> 6.38 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Head	<input checked="" type="checkbox"/> 9.15 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Piping	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Underside of the tank	<input checked="" type="checkbox"/> 6.35 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Corroded Areas	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Around Upper Coupler	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Nominal Liquid Level Lines	<input checked="" type="checkbox"/> 6.36 MM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shell Reinforcements / Repads	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Comments: No Defects Found

Defects Observed:

Repair Performed:

Special Service of Tank: Standard Service

Disposition Statement: Return to Service

Inspector: Shawn Lauer

Signature: