

C40-16
JUN


G&D Tank Testing and Repair
Box 247 Rocky Rapids, AB
1-780-898-0962
TC Canada Reg. # TC-25-1247



HIGHWAY TANK LEAKAGE INSPECTION REPORT

Account#	41	NEXT REQUIRED INSPECTION	Jul-26
OWNER	Neway Oilfield Services	UNIT#	319
ADDRESS	Rocky Mountain House, Alberta	MFG'S SERIAL#	5HTDL4931E5L26912
DATE	July 2/2025	DATE OF MFG	07/2013
TELEPHONE	403-846-6954	TANK SPECIFICATION	DOT 407 AL
TANK MFG	Heil Trailer International Co	COMPART/CAPACITY	12,200 Gallon's
MEDIUM	Pneumatics	MAWP	30 PSI
VISCOSITY		1 80% OF MAWP	24 PSI
TANK ASSEMBLER	Heil Trailer International Co	TCRN/MDIN	N/A

Areas of Inspection	Pass		
	Yes	No	N/A
Venting that relieves at less than test pressure closed or inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hose tested to 75 psi or 120% of marked MAWP which ever is greater	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Piping are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Valves are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No leakage detected after pressure maintained for 5 minutes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector: Greg Mulligan Disposition Statement: Return to Service Signature 

Repair performed:

Defects observed:

Comments:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK THICKNESS TEST REPORT

Account# 41 **NEXT REQUIRED INSPECTION** Jul-30
OWNER Neway Oilfield Services **UNIT#** 319
ADDRESS Rocky Mountain House, **MFG'S SERIAL#** SHTDL4931E5L26912
DATE July 2/2025 **DATE OF MFG** 07/2013
TELEPHONE 403-846-6954 **TANK SPECIFICATION** DOT 407 AL
TANK MFG Heil Trailer Internationa **COMPART/CAPACITY** 12,200 Gallon's
Head Material Thickness 9.525 M.M. **MINIMAL** 8.331 M.M.
Shell Material Thickness 6.35 M.M. **MINIMAL** 5.892 M.M.
Tank Assembler Heil Trailer Internationa **TCRN/MDIN** N/A
Testing Device Serial # TT0001
Testing Device thickness respond 4.00 MM
Calibrated Date / Expiry Date SELF CALB. / STEP BLOCK

Areas of Inspection	Minimum M.M.	Pass		
		Yes	No	N/A
Head.	8.90 M.M.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shell.	6.25 M.M.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Piping.	N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Underside of the tank.	6.25 M.M.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Calibrated Date / Expiry Date.	July 2/2025	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Around Upper Coupler.	N/A.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Nominal Liquid Level Lines.	N/A.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Shell Reinforcements / Repads.	N/A.	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Inspector: Greg Mulligan

Disposition Statement: Return To Service

Special Service of Tank : Standard Service

Signature

Repair Performed

Defects Observed

Comment:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK EXTERNAL INSPECTION REPORT

Account#	41	NEXT REQUIRED INSPECTION	Jul-26
OWNER	Neway Oilfield Services	UNIT#	319
ADDRESS	Rocky Mountain House, Alb.	MFG'S SERIAL#	5HTDL4931E5L26912
DATE	July 2/2025	DATE OF MFG	07/2013
TELEPHONE	403-846-6954	TANK SPECIFICATION	DOT 407 AL
TANK MFG	Heil Trailer International Co	COMPART/CAPACITY	12,200 Gallon's
TANK ASSEMBLER	Heil Trailer International Co	TCRN/MDIN	N/A

Areas of Inspection	PASS			Description of Defect	Repaired	
	Yes	No	N/A		Yes	No
Data plate legible and correct	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Accident damage protection (Roll - Over & Bumper etc)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Support Structure (cradle, bolster, frame & sills)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Corrosion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Dents and Cracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Welds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Gaskets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Flange Retainers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Fittings/Nozzles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Valves Operational & Leak Proof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Emergency Devices Operational	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	D/S Second Emergency Shut Down Swicth Not Working	<input checked="" type="checkbox"/>	<input type="checkbox"/>
PRV/Vents Tested	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Visual Pass	<input type="checkbox"/>	<input type="checkbox"/>
Tank Identification & Markings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Piping & Hoses voids free of residue, unplugged, no leakage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Fixed & hard plumbed hoses free of exposed reinforcement, kinks, flatness or permanently deformed wire braids, soft spots, damaged or loose fittings, missing bolts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Manhole Tightening Devices Operable	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Relief devices tested, reinstalled & operative	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Visual Pass	<input type="checkbox"/>	<input type="checkbox"/>
Manhole Covers Leak Proof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A.	<input type="checkbox"/>	<input type="checkbox"/>
Hose Identification, test markings are legible, test dates, tank markings applied	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	No Hose's on Unit.	<input type="checkbox"/>	<input type="checkbox"/>

Comments

Signature

D/S Plac Card Holder Is Loose From Tank

Special Service of Tank:
 Inspector: Greg Mulligan.

Standard Service
 Disposition Statement: Return To Service