

036-1
Jul

G&D Tank Testing and Repair
Box 247 Rocky Rapids, AB
1-780-898-0962
TC Canada Reg. # TC-25-1247



HIGHWAY TANK EXTERNAL INSPECTION REPORT

Account#	1	NEXT REQUIRED INSPECTION	July, 2026
OWNER	Weber Fuel Distributors	UNIT#	103
ADDRESS	Nisku, AB	MFG'S SERIAL#	46AT3063M93004680
DATE	July, 21, 2025	DATE OF MFG	April, 2009
TELEPHONE	780-951-5081	TANK SPECIFICATION	TC 406 MS
TANK MFG	Hamm's Tanks	COMPART/CAPACITY	8105/8105/5700L
TANK ASSEMBLER	Hamm's Tanks	TCRN/MDIN	406-MS-03-EL

Areas of Inspection	PASS			Description of Defect	Repaired	
	Yes	No	N/A		Yes	No
Data plate legible and correct	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Accident damage protection (Roll - Over & Bumper etc)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Support Structure (cradle, bolster, frame & sills)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Corrosion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Dents and Cracks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Welds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Gaskets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Flange Retainers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Fittings/Nozzles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Valves Operational & Leak Proof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Emergency Devices Operational	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
PSV/Vents Tested	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Leak Test Only	<input type="checkbox"/>	<input type="checkbox"/>
Tank Identification & Markings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Piping & Hoses voids free of residue, unplugged, no leakage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Fixed & hard plumbed hoses free of exposed reinforcement, kinks, flatness or permanently deformed wire braids, soft spots, damaged or loose fittings, missing bolts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Manhole Tightening Devices Operable	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Adjusted manway 1 and 3 lid tension	<input type="checkbox"/>	<input type="checkbox"/>
Relief devices tested, reinstalled & operative	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Leak Test Only	<input type="checkbox"/>	<input type="checkbox"/>
Manhole Covers Leak Proof	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	N/A	<input type="checkbox"/>	<input type="checkbox"/>
Hose Identification, test markings are legible, test dates, tank markings applied	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	No Hoses Present at Time of Inspection	<input type="checkbox"/>	<input type="checkbox"/>

Comments: No defects found.

Special Service of Tank: Standard Service
Disposition Statement: Returned to Service
Inspector: Shawn Lauer

Signature:

G&D Tank Testing and Repair
 Box 247 Rocky Rapids, AB
 1-780-898-0962
 TC Canada Reg. # TC-25-1247



HIGHWAY TANK LEAKAGE INSPECTION REPORT

Account#	1	NEXT REQUIRED INSPECTION	July, 2026
OWNER	Weber Fuel Distributors	UNIT#	103
ADDRESS	Nisku, AB	MFG'S SERIAL#	46AT3063M93004680
DATE	July, 21, 2025	DATE OF MFG	April, 2009
TELEPHONE	780-951-5081	TANK SPECIFICATION	TC 406 MS
TANK MFG	Hamm's Tanks	COMPART/CAPACITY	8105/8105/5700L
MEDIUM	Air	MAWP	3 P.S.I.
VISCOSITY	1	80% OF MAWP	2.4 P.S.I.
TANK ASSEMBLER	Hamm's Tanks	TCRN/MDIN	406-MS-03-EL

Areas of Inspection	Pass		
	Yes	No	N/A
Venting that relieves at less than test pressure closed or inoperative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hose tested to 75 psi or 120% of marked MAWP which ever is greater	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Piping are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Valves are in place and operative	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
No leakage detected after pressure maintained for 5 minutes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: No Defects Found

Defects observed: None

Repairs performed: None

Disposition Statement: Return to Service

Inspector: Shawn Lauer

Signature: