



Vehicle Standards and Inspection

F02-3
SEP

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P276523

P276523

Station #: 71131

Station Name: TKC Trucking and Picker Service

Technician #: 90508

Technician Name: Derrick Ching

Signing Officer #: 85781

Signing Officer Name: Troy Ching

Customer Details:

Name: **TKC Trucking and Picker Service Ltd.**

Address: Box 2337, Kindersley, Saskatchewan, S0L 1S0

Inspection Completed Date: 17Jul2026

Inspection **Expiry Date: 31Jul2027**

Vehicle Details:

VIN: 2A9LB4035CN125042

Hubometer Reading: 15903 km

Year: 2012

Vehicle Make/Model: ASPEN TRAILER/ASPEN

Plate: 65J352

Jurisdiction: Alberta

Unit: TL17

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71131 Station Name: TKC Trucking and Picker Service
Technician #: 90508 Technician Name: Derrick Ching
Signing Officer #: 85781 Signing Officer Name: Troy Ching

Customer Details:

Name: TKC Trucking and Picker Service Ltd. Address: Box 2337, Kindersley, Saskatchewan, S0L 1S0

Vehicle Details:

VIN: 2A9LB4035CN125042 Hubometer Reading: 15903 km
Year: 2012 Vehicle Make/Model: ASPEN TRAILER ASPEN

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 8 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 8 in

Brake(1): No Brake

N/A

Wheel3-On : Tire Tread Depth: 22 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 22 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 18 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 10 in

Brake(1): No Brake

N/A

Wheel3-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 15 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 10 in

Brake(1): No Brake

N/A

Wheel3-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13/16 in • Cam Rotation: 30 degrees • Brake Stroke: 1.5 in



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71131

Station Name: TKC Trucking and Picker Service

Technician #: 90508

Technician Name: Derrick Ching

Signing Officer #: 85781

Signing Officer Name: Troy Ching

Customer Details:

Name: TKC Trucking and Picker Service Ltd.

Address: Box 2337, Kindersley, Saskatchewan, S0L 1S0

Vehicle Details:

VIN: 2A9LB4035CN125042

Hubometer Reading: 15903 km

Year: 2012

Vehicle Make/Model: ASPEN TRAILER ASPEN

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Wheel4 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # P276523

Inspection Completed Date: 17Jul2026

Trailer and Semi-Trailer Inspection Certificate

VOID WITHOUT
DECAL

This Certificate is issued under the authority of the Province of Saskatchewan

Vehicle Standards and Inspection

Date Inspection Started 7 07 2026 day month year Date Inspection Completed 17 07 2026 day month year Inspection Expiry Date 3 00 6 2026 day month year Trailer ☒ Semi-Trailer ☐ Converter/Jeep/Pony/Booster ☐ Brake Type Air ☒ Hydraulic ☐ Electric ☐ Pass ☒ Fail ☐ Out-of-Service Condition ☐ FTR ☐ TLV ☐ PMVI ☒	INSPECTING STATION Station Number 71131 Station Name _____ City _____ Signing Officer Number 85781 Signing Officer Signature _____ Station Phone Number _____ Technician Number 90508 Technician Signature _____ PMP STATION DECAL ISSUED TO: PMP Station # _____ PMP Station Name _____ PMP Technician # _____ Technician Signature _____ Vehicle Owner: TKC TRUCKING AND PICKER SERVICES LTD. Address _____ City _____ Province _____ Postal Code _____ Phone _____ Licence Number 65J352 Prov AB Serial Number 2A9LB4035CN125042 Hubometer Reading 15903 Hubom. Type ☒ km ☐ mi Make ASPEN Model Trailer Year 2012 Unit # TL7
--	---

Circle Items Requiring Attention
R = Item Rejected C = Item Corrected

No.	R	C	TRAILER EXTERIOR	Ref #	No.	R	C	TRAILER EXTERIOR	Ref #	No.	R	C	CHASSIS	Ref #
01			Vehicle Identification Number	5	10			Auxiliary Equipment	5	18			Sliding Axle Assembly (if equipped)	8
02			Lamps	6	11			Fire Extinguisher	5	19			Tires/Wheels	9
			Reflex Reflectors	6	12			Wheel Bearings	9	20			Frame/Crossmembers/Mounts	8
04			Retro Reflective Markings	6	13			Trailer Hitch	10	21			Suspension/Axles	2
05			Battery/Wiring Condition	7	14			Rear Impact Guard	8	22			Hyd Brake System/Components	3.1
06			Trailer Power Cord	7	15			Attached Equipment	8	23			Air Brake System/Components	3.2
07			Mudflaps/Fenders	8	16			Fuel System	1	24			Elec Brake System/Components	3.1
08			Landing Gear	8	17			Exhaust/Emission System	1	25			Self-Steering Axle	2 & 4
09			Cargo Bodies/Vessels	8										

Tire Tread Depth (in/mm) Front 8 18 10 Rear 8 10 10 Front 22 15 13 Rear 22 15 13	Drum Size/Rotor Thickness (in/mm) Front _____ Rear _____ Brake Stroke (in/mm) Front 1.5 1.5 1.5 Rear 1.5 1.5 1.5	Brake Cam Rotation (degree°) Front 30° 30° 30° Rear 30° 30° 30°	An "X" is placed in the box(es) below indicates a full brake inspection was performed with wheel(s) removed. Wheel Position Front ☐ ☐ ☐ ☐ ☐ ☐ Rear ☐ ☐ ☐ ☐ ☐ ☐ Brake Lining Thickness (in/mm) 13/16 13/16 13/16 13/16 13/16 13/16
--	--	--	---

Record final accepted measurements in all areas above.

Remarks: _____

Vehicle received without repairs by:

Signature _____ This inspection is not an authorization for repairs. Permission from the owner must be obtained.