

R24-1
SEP

Our File
K41582

TECHNICAL FIELD REPORT

Inspection Date
2026-08-24

To: **404172 AB Ltd**
Fontaine Pipeline
PO Box 53
Aldersyde, AB T0L0A0

Attn: Mr. Ray Fontaine

Re: Inspection of Genie Manlift
Model Z-34/22N, S/N Z34N06-6078, Unit 30142724
Location: 450214 82nd Str. E Aldersyde Ab.
No PO Required:



Visual examinations and magnetic particle inspections were performed on the above-described equipment. The specific items examined and our inspection findings were as follows:

1. Wheel Rims (4x) - no defects noted.
2. Steering Knuckles (2x) - no defects noted.
3. Undercarriage - no defects noted.
4. Ring Gear (visual) - no defects noted.
5. Rotating Frame - no defects noted.
6. Counterweight - no defects noted.
7. Lower Lift Stage - no defects noted.
8. Lower Floating Pedestal - no defects noted.
9. Upper Lift Stage - no defects noted.
10. Upper Floating Pedestal - no defects noted.
11. Boom Butt Section - no defects noted.
12. Boom Tip Section - no defects noted.
13. Articulating Jib Assembly - no defects noted.
14. Manbasket Adapter - no defects noted.
15. 500 lb SWL Manbasket - no defects noted.

Sticker has been issued
• • **FORMAL REPORT TO FOLLOW** • •

Inspector:

A handwritten signature in blue ink, appearing to read 'Jamie Winter', is written over a horizontal line.

Jamie Winter

Appendix




Figure 1: I D Tag