

PRE-USE-VEHICLE (Picker Truck)

Information

-  Picker Trucks > PT44
-  Newforce Drayton Valley Shop/Yard/Office
-  Monday, December 9th 2024, 8:21 AM (MST -07:00)

Unit Information

Unit#

- ☒ Picker Trucks > PT44

Odometer/hours reading # 189777

Next Service due # 192500

Yes ☒ No NA Next service due within 1000Km

Driver

 Mike Parker

Picker Certification expiry date

 August 17, 2027

Vehicle inspection items

- ☒ ☒ ☒ Insurance and registration
- ☒ ☒ ☒ Cab (cleanliness, rips, tears)
- ☒ ☒ ☒ Heater/dofrost
- ☒ ☒ ☒ Windshield wipers/washer
- ☒ ☒ ☒ Glass and mirrors
- ☒ ☒ ☒ Dash lights
- ☒ ☒ ☒ Signal lights
- ☒ ☒ ☒ Hazard lights
- ☒ ☒ ☒ Headlights (High beam/low beam)
- ☒ ☒ ☒ Brake lights
- ☒ ☒ ☒ Marker lights
- ☒ ☒ ☒ Fluid Levels (oil, anti freeze, washer, brake, power steering, hydraulic fluids)

 Couldn't check hood won't open

*Cable ordered
In stock.*

- ☒ ☒ ☒ Back up alarm

☒ ☒ ☒ **Drum system**

☒ ☒ ☒ **Dents, Scratches, or Damage (check (X) if damage is found)**

☒ **Rusty deck**

☒ ☒ ☒ **Electric brake system (trailer brakes)**

☒ ☒ ☒ **Cargo securement (Nets, straps, etc.)**

☒ ☒ ☒ **Hitch**

☒ ☒ ☒ **Have you completed pre use inspection on trailer**

☒ ☒ ☒ **Wheels hubs and fasteners**

☒ ☒ ☒ **Hydraulics**

☒ ☒ ☒ **Air compressors**

☒ ☒ ☒ **Air system**

☒ ☒ ☒ **Air brake warning lights, low pressure, vacuum failure**

☒ ☒ ☒ **Fire Extinguisher, first aid kit, reflective triangles**

Details of defects. (Please add pictures and detailed descriptions).

☒ **Rusty deck back tires wore water in fuel tires wore on back hood wont open**

Picker - Visual - inspection items

☒ ☒ ☒ **Load charts & control symbols (must be legible on both sides of the unit)**

☒ **Half missing**

☒ ☒ ☒ **Outrigger pads**

☒ ☒ ☒ **Hydraulic fluid levels**

☒ ☒ ☒ **All mounting bolts**

☒ ☒ ☒ **Hydraulic system leaks**

☒ ☒ ☒ **Cracks dents on main boom**

☒ ☒ ☒ **Cracks dents on outer boom**

☒ ☒ ☒ **Load hook fastener**

☒ ☒ ☒ **Load hook Not stretched**

☒ ☒ ☒ **Load hook Not worn**

☒ ☒ ☒ **Load hook safety latch in place and functioning (must snap into the closed position)**

☒ ☒ ☒ **Cylinder seals**

☒ ☒ ☒ **Cylinder rams**

☒ ☒ ☒ **Hoses**

☒ ☒ ☒ **Hydraulic tubing**

☒ ☒ ☒ Outrigger latches

☒ ☒ ☒ Outrigger locks

☒ ☒ ☒ Outrigger levers

☒ ☒ ☒ Outrigger control valve

☒ ☒ ☒ PTO - System

Details of defects. (Please add pictures and detailed descriptions).

☰ Rusty deck fuel transfer pump slow wore back tires water in fuel

Picker - Operational check

☒ Yes ☐ No ☐ NA Parking brake functions

☒ Yes ☐ No ☐ NA PTO - Engages properly

☒ Yes ☐ No ☐ NA Engine RPM (normal RPM between 1200 - 1500)

☒ Yes ☐ No ☐ NA Outriggers fully extend

☒ Yes ☐ No ☐ NA Outriggers levers working

☒ Yes ☐ No ☐ NA Warm oil adequately

☒ Yes ☐ No ☐ NA Booms extended

☒ Yes ☐ No ☐ NA Hydraulic cylinders extended

Details of defects. (Please add pictures and detailed descriptions).

☰ No Response

Original

Mike Parker, Crew Foreman

📅 December 9th 2024, 8:21 AM (MST -07:00)

📍 53.2294454, -114.9849293



Revised on December 9th 2024, 9:41 AM (MST -07:00)

Current View

Mike Parker, Crew Foreman

📅 December 9th 2024, 9:41 AM (MST -07:00)

📍 53.2294454, -114.9849293

