W18-2
DEC

DYNAMIC ENERGY GROUP INC.
Box 730
Grande Prairie, AB T8V 3R5
Phone: (780) 876-8949
Fax: (780) 830-0580

HOSE ASSEMBLY INSPECTION & TESTING

CARRIER: Dynamic		**DATE:** Feb 2026
UNIT # 271	**WORK ORDER:**	**IDENTIFICATION / SERIAL #** 27102
CSA:	**NON CSA:** ✓	**HOSE LOCATION:**
HOSE DESCRIPTION: 1.5 Artic super flex		**HOSE LENGTH:** 20 ft

TRUCK [✓] **TRAILER** [ ] **PUP TRAILER** [ ] **FILTER UNIT** [ ] **SPARE** [ ]

TEST TYPE: **HYDROSTATIC** [✓] **TEST MEDIUM:** **WATER** [✓]

TEST PRESSURE 180 PSi **TEST LENGTH** 10 min **HAWP** 150 PSi

#	ITEM INSPECTED	PASS	FAIL	REMARKS
1	Damage to the hose cover that exposes the reinforcement.	✓		
2	Kinked, flattened, or permanently deformed wire braid.	✓		
3	Soft spots when not under pressure and bulging under pressure, or loose outer coating.	✓		
4	Damaged, slipping or excessively worn hose couplings.	✓		
5	Loose or missing bolts or fastenings on bolted hose coupling assemblies.	✓		
6	Deteriorated legibility or absence of the serial or identification number and HAWP.	✓		
7	Test hose continuity with multimeter. Record the results in the remarks column			

[✓] **PASS – Return to Service** [ ] **FAIL – Remove from Service**

Install Marking according to CSA B620 Section 7.2.10.7 [✓]

Name and Address of Inspection / Test Facility

Dynamic Energy Group Inc.
13501 99 Street
Grande Prairie, AB
T8V 7N9

Name of Tester: Ethan Telset

Signature: Ethan

Date of Inspection: Feb 2026 **Date of Expiry:** Feb 2027

This Hose Inspection is in accordance with and meets the requirements of CSA B620-03 Clause 7

DYNAMIC ENERGY GROUP INC.
Box 730
Grande Prairie, AB T8V 3R5
Phone: (780) 876-8949
Fax: (780) 830-0580

HOSE ASSEMBLY INSPECTION & TESTING

CARRIER: Dynamic		DATE: Feb 2026
UNIT # 271	WORK ORDER:	IDENTIFICATION / SERIAL # 27103
CSA:	NON CSA: ✓	HOSE LOCATION:
HOSE DESCRIPTION: 2 inch Attic SuPer flex		HOSE LENGTH: 6 ft

TRUCK [✓] TRAILER [ ] PUP TRAILER [ ] FILTER UNIT [ ] SPARE [ ]

TEST TYPE: HYDROSTATIC [✓] TEST MEDIUM: WATER [✓]

TEST PRESSURE [180 PSI] TEST LENGTH [10 min] HAWP [150 PSI]

#	ITEM INSPECTED	PASS	FAIL	REMARKS
1	Damage to the hose cover that exposes the reinforcement.	✓		
2	Kinked, flattened, or permanently deformed wire braid.	✓		
3	Soft spots when not under pressure and bulging under pressure, or loose outer coating.	✓		
4	Damaged, slipping or excessively worn hose couplings.	✓		
5	Loose or missing bolts or fastenings on bolted hose coupling assemblies.	✓		
6	Deteriorated legibility or absence of the serial or identification number and HAWP.	✓		
7	Test hose continuity with multimeter. Record the results in the remarks column			

[✓] PASS – Return to Service [ ] FAIL – Remove from Service

Install Marking according to CSA B620 Section 7.2.10.7 [✓]

Name and Address of Inspection / Test Facility

Dynamic Energy Group Inc.
13501 99 Street
Grande Prairie, AB
T8V 7N9

Name of Tester: Ethan Telfer

Signature: Ethan

Date of Inspection: Feb 2026 Date of Expiry: Feb 2027

This Hose Inspection is in accordance with and meets the requirements of CSA B620-03 Clause 7

RESOURCE
PURCHASING & SUPPLY

11537 – 97 Ave
GRANDE PRAIRIE, AB T8V 5R9
780-532-1702
Resource@rpsi.ca
www.resourcepurchasingandsupply.ca

- HOSE INSPECTION CERTIFICATE -

CUSTOMER: DYNAMIC ENERGY GROUP

CERTIFICATION #RPS177531

CURRENT HOSE ID:

PO #: 5609-271-01

DATE: FEB 7/2026

INVOICE #: 1522087

ORDER #: 177531

PASS: YES

I D x LENGTH 2" X 22

FAIL:

MATERIAL: BUCTTAD

REASON:

DESCRIPTION: 2" X 22FT ARCTICFLEX TANK TRUCK HOSE

COUPLING (end 1): BAL-200D-SS

COUPLING (end 2): BA200A-SS

CONTINUITY TEST:
PASS 3.00 OHM

STATED WORKING PSI: 150

TEST PRESSURE: 225 (1.5 x WORKING)

DURATION

START 9:45AM

FINISH TIME: 10:00AM (15 MINUTES)

ASSEMBLED OR
INSPECTED & TESTED BY: BRANDON VISSER
PRINT NAME

Brandon Visser
SIGN

TEST CERTIFIIED BY: NICK HEARN
PRINT NAME

Nick Hearn
SIGN

VISUAL INSPECTION OBSERVATIONS: