



Commercial Vehicle Inspection Report

Decal Number: GM80808
Decal Expiry Date: 2027-Apr-30
Inspection Number: 21741125

Inspection Result:

PASS

FACILITY: MADROCK ENTERPRISES LTD. / S20367
INSPECTOR: STEWART, PEARCE Hunter / 201510
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2026-Apr-20 12:00 PM MST
INSP. COMPLETE: 2026-Apr-20 03:00 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 06422L
LICENCED GW(kg): 0
VEHICLE YEAR: 2009
MAKE: DOEPKER
MODEL:
REGI: 13863133
UNIT/FLEET#: 21204
BODY STYLE: Lowbed Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2DESNSZ3091022695
OWNER/LESSEE NAME: sage creek offroad service, N/A
ADDRESS: 11111 enterprise way
Fort St John, British Columbia
V1J8C9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) SLACKS OUT OF ADJUSTMENT. AXLE 2 AND 3 . CHANGE SLACK BUSHINGS
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) LEFT MARKER LIGHT OUT RIGHT MARKER LIGHT RIGHT REAR MARKER LIGHT
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) LEFT MUD FLAP
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30L	Automatic	42	45	16	13	12	13	
2	Clamp	30L	Automatic	43	45	13	13	13	13	
3	Clamp	30L	Automatic	45	45	10	11	12	9	

Comment: CHANGE SHOES AND DRUMMS ON RIGHT #3

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	90	90
2	80	90
3	80	110

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	13
Lining (Shoe)	15	11
Lining (Shoe)	13	9

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: STEWART, PEARCE Hunter

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Apr-21 11:05 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/21/2026 11:05:56 AM MST