



Commercial Vehicle Inspection Report

Decal Number: GM80803
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21692032

Inspection Result:
PASS

FACILITY: MADROCK ENTERPRISES LTD. / S20367
INSPECTOR: STEWART, PEARCE Hunter / 201510
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2026-Mar-10 09:00 AM MST
INSP. COMPLETE: 2026-Mar-10 10:00 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 21480L
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2006
MAKE: DOEPKER
MODEL:
REGI: 03047219
UNIT/FLEET#: 21205
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2DEHBFZ3061017034
OWNER/LESSEE NAME: sage creek oilfield service, N/A
ADDRESS: 11111 enterprise way
Fort St John, British Columbia
V1J8C9, Canada

Vehicle Identification (VIN)	Repaired (same day)	VIN PLATE GONE
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	LEFT REAR AIR BAG REPLACED
Section 3 - Brake System	Repaired (same day)	REAR AXLE BRAKE POTS
Section 3A - Air Brakes	Repaired (same day)	WHEEL SEAL
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REAR MARKER LIGHTS
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	30 CROSS MEMBERS REPLACED
Section 9A - Tires	Repaired (same day)	3 FLAT TIRES
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	40	40	7	7	8	7	
2	Clamp	30	Automatic	35	35	13	13	5	8	
3	Clamp	30	Automatic	35	36	7	8	13	13	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	62
2	74	80
3	55	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	14	14
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: STEWART, PEARCE Hunter

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-11 08:56 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement.

CV/SE014

3/11/2026 8:58:38 AM MST