



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GK44194
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21648959

Inspection Result:
PASS

FACILITY: MADROCK ENTERPRISES LTD. / S20367
INSPECTOR: STEWART, PEARCE Hunter / 201510
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Annual
INSPECTION START: 2026-Jan-30 12:00 PM MST
INSPECTION COMPLETE: 2026-Jan-30 02:00 PM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 21481L
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2006
MAKE: MANAC
MODEL:
REGI: 03124907
UNIT/FLEET#: 21206
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2M513161561106229
OWNER/LESSEE NAME: SAGE CREEK OILFIELD SERVICE, N/A
ADDRESS: 11111 ENTERPRISE WAY
Fort St John, British Columbia
V1J8C9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) #1 R AND #3 LEFT BRAKE POTS BROKEN
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	35	19	9	7	10	10	
2	Clamp	30	Automatic	36	32	12	10	11	12	
3	Clamp	30	Automatic	37	35	8	10	5	6	

Comment: CHANGED SHOES AND DRUM RIGHT #2

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	70
2	60	102
3	40	45

Comment: 1 RIGHT BRAKE POT CHANGED

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	16
Lining (Shoe)	15	8
Lining (Shoe)	18	16

Comment: RIGHT #2 SHOES REPLACED

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: STEWART, PEARCE Hunter

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-31 10:19 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSICVP at the Commercial Vehicle Safety Enforcement.

CVSED014

1/31/2026 10:19:31 AM MST