



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GK44190
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21645069

Inspection Result:

PASS

FACILITY: MADROCK ENTERPRISES LTD. / S20367
INSPECTOR: STEWART, PEARCE Hunter / 201510
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2026-Jan-27 02:00 PM MST
INSP. COMPLETE: 2026-Jan-27 05:00 PM MST

J01-6

VEHICLE JUR: British Columbia
PLATE #: 27829L
LICENCED GW(kg): 0
VEHICLE YEAR: 2021
MAKE: BRANDT
MODEL: H650

REGI: 13602529
UNIT/FLEET#:
BODY STYLE: LOWBOY TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2BYHN3PP2MD000403
OWNER/LESSEE NAME: SAGE CREEK OILFIELD SERVICE, N/A
ADDRESS: 11111 ENTERPRISE WAY
Fort St John, British Columbia
V1J8C9, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	38	35
2	Clamp	30	Automatic	36	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
18	18	18	19	
18	18	18	19	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	44	45
2	36	35

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	17
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: STEWART, PEARCE Hunter
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jan-26 01:16 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/28/2026 1:16:45 PM MST