



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GK44188
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21644991

Inspection Result:
PASS

FACILITY: MADROCK ENTERPRISES LTD. / S20367
INSPECTOR: STEWART, PEARCE Hunter / 201510
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2026-Jan-27 08:00 AM MST
INSP. COMPLETE: 2026-Jan-27 10:00 AM MST

VEHICLE JUR: British Columbia
PLATE #: 27830L
LICENCED GVW(kg): 0
VEHICLE YEAR: 2021
MAKE: BRANDT
MODEL: R40

REGI: 13602512
UNIT/FLEET#:
BODY STYLE: Lowbed Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2BYHJZEHDMD000411
OWNER/LESSEE NAME: SAGE CREEK OILFIELD SERVICE, N/A
ADDRESS: 11111 ENTERPRISE WAY
Fort St John, British Columbia
V1J8C9, Canada

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Repaired (same day) SPRING BRAKE VALVE
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Passed
Section 5 - Instruments and Auxiliary Equipment Passed
Section 6 - Lamps Passed
Section 7 - Electrical System Repaired (same day) MARKER LIGHT
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	29	29
2	Clamp	30	Automatic	28	29
3	Clamp	30	Automatic	28	29

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15	14	13	14	
15	15	15	16	
15	15	16	16	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	60
2	40	60
3	60	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	15	16
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: STEWART, PEARCE Hunter

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jan-26 12:46 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CV/SED014

1/28/2026 12:46:06 PM MST