

03899369

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

Date Inspection Started 06 DAY 01 MO. 25 YR.	Station Number A3019	Station Name R. LEWANDOSKI FARM	City SANDWICH	A894013
Date Inspection Completed 08 DAY 01 MO. 25 YR.	Mechanic Number M9054	Mechanic Signature Daniel Rydzek	Station Phone Number 204-585-2520	
Inspection Expiry Date 31 DAY 01 MO. 26 YR.	Vehicle Owner LANCE C HIGGOTT			
Address _____ City _____ Province _____ Postal Code _____ Phone _____				
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input checked="" type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number TA91326	Prov. MB	NSC # _____	Odometer Reading _____ Odom. Type <input type="checkbox"/> km <input type="checkbox"/> mi
Vehicle Identification Number 2LDH42838DF054474		Make LOPE	Model GRAN	Year 13
<input checked="" type="checkbox"/> Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
<input checked="" type="checkbox"/>		Section 1 - Power Train: Defects (if any)
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Section 2 Suspension: Defects (if any) 7(c) AXLE 2 SHOCK ABSORBERS LEAKING.
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 15(c) AXLE 1 R BRAKE LININGS WORN
<input checked="" type="checkbox"/>		Section 4 - Steering: Defects (if any)
<input checked="" type="checkbox"/>		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
<input checked="" type="checkbox"/>		Section 6 - Lamps: Defects (if any)
<input checked="" type="checkbox"/>		Section 7 - Electrical System: Defects (if any)
<input checked="" type="checkbox"/>		Section 8 - Body: Defects (if any)
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Section 9 - Tire & Wheel: Defects (if any) 4(b) TIRE INFLATIONS
<input checked="" type="checkbox"/>		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth mm				Air Pressure PSI			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	9	11	4	8	100	100	100	60
2	10	14	12	11	100	100	100	70
3	5	6	9	4	100	100	60	100
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: MANITOBA "A" SAFETY 23/02/24
A778722

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____

Vehicle Identification Number (VIN): 1G1ZB574121000000

Model Year: 2000

Make: Chevrolet

Model: Blazer

Engine: 4.8L V6

Drive: 4WD

Color: Black

Weight: 4500

Seating: 7

Other: None

Section	Item	Condition	Notes
Section 1 - Front End	1. Hood	Good	
	2. Bumper	Good	
	3. Grille	Good	
	4. Headlight	Good	
Section 2 - Side	5. Door	Good	
	6. Window	Good	
	7. Mirror	Good	
	8. Wheel	Good	
Section 3 - Rear	9. Trunk	Good	
	10. Bumper	Good	
	11. Tail Light	Good	
	12. Exhaust	Good	

Section 4 - Interior

Section 5 - Exterior

Section 6 - Engine

Section 7 - Drivetrain

Section 8 - Brakes

Section 9 - Suspension

Section 10 - Steering

Section 11 - Electrical

Section 12 - Safety

Section 13 - Other

Inspector: [Signature]

Date: 10/10/00

Vehicle: 2000 Chevrolet Blazer

Engine: 4.8L V6

Drive: 4WD

Color: Black

Weight: 4500

Seating: 7

Other: None