04073628 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE** Manitoba J02-1

Vehicle Safety Box 45064 Regent Postal Outlet Winnipeg, MB R2C 5C7 1-204-985-8500

Manitoba C081327

Date Inspection Started: DAY 15 MO. 04 YR. 26

Date Inspection Completed: DAY 16 MO. 04 YR. 26

Inspection Expiry Date: DAY 30 MO. 04 YR. 27

Station Number: AC10116 Station Name: GLENLAT ENT. City: Winkler

Mechanic Number: M218181 Mechanic Signature: [signature] Station Phone Number: 857-6388

Vehicle Owner: A YARD OR 2

Address: City: Province: Postal Code: Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: CP21774 Prov.: MB NSC #: MB611697 Odometer Reading: 246835 Odom. Type: ☒ km ☐ mi

Vehicle Identification Number: 2HSFWAJTX1H616121 Make: INT Model: 9200 Year: 00 Unit #: 105

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

X Truck GVWR 24000 KGS ___ Truck Tractor ___ Trailer ___ Semi-Trailer ___ Bus ___ School Bus ___ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
	X	**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any) 7B WIPER BLADES FAIL TO CLEAR PROPERLY
X	X	***Section 6 - Lamps:*** Defects (if any) 15 CENTRE LID LAMP INOPERATIVE.
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	.670	.630	16.534	16.510	1/2	1/2
2	.830	.830	16.516	16.380	1 1/2	1 1/2
3	.830	.830	16.560	16.540	1 1/4	1 1/4
4						
5						
	Final Measurement					

Tread Depth 32nd

Axle	Initial L	Initial L	Initial R	Initial R	Corrected L	Corrected L	Corrected R	Corrected R
1		9	13					
2	11	12	11	10				
3	11	13	13	13				
4								
5								

Air Pressure

Axle	Initial L	Initial L	Initial R	Initial R	Corrected L	Corrected L	Corrected R	Corrected R
1		100	100					
2	100	100	100	100				
3	100	100	100	100				
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande

PRESENT THIS COPY WHEN REGISTERING VEHICLE