



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ80475
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21431414

Inspection Result:

PASS

FACILITY: NICOMEKL HEAVY DUTY LTD. / S20215
INSPECTOR: Mazurowski, Bartłomiej Bodhan / 113614
WORK ORDER #:

INSR. TYPE: Complete
INSR. CLASS: Class 3 - Trailer and Semi-Trailer
INSR. REASON: Annual

INSR. START: 2025-Jul-17 03:30 PM PDT
INSR. COMPLETE: 2025-Jul-17 05:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 17358U
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2009
MAKE: JINDO
MODEL:

REGI: 03747738
UNIT/FLEET#: 84
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: LV1GT53349S105660
OWNER/LESSEE NAME: PHEONIX ENTERPRISES LTD, PHEONIX ENTERPRISES LTD
ADDRESS: 200-19429 54 AVE, 200-19429 54 AVE
Surrey, British Columbia
V3S 7X2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	36	36	11	11	11	11	
2	Clamp	30	Automatic	36	36	14	14	13	13	
3	Clamp	30	Automatic	36	36	14	14	14	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	50
2	45	60
3	40	40

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	16
Lining (Shoe)	16	15
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor/Drum		
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Mazurowski, Bartłomiej Bodhan

Road Test Date:

Signature:

Road Tester:

This inspection Report was submitted to CVSE on 2025-Jul-19 11:24 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. registering carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

7/19/2025 11:25:08 AM PDT