



Commercial Vehicle Inspection Report

Decal Number: GJ45075
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21376496

Inspection Result:
PASS

FACILITY: N.K. AUTOMOTIVE TRUCK & DIESEL / S3838
INSPECTOR: VEEKEN, NICHOLAS JOHANNES / 100029
WORK ORDER #: 37533
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Jun-03 08:30 AM PDT
INSP. COMPLETE: 2025-Jun-03 10:00 AM PDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 1995
MAKE: TRAILKING
MODEL:
REGI: 01583719
UNIT/FLEET#:
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1TKB04826SM116622
OWNER/LESSEE NAME: cti contractors ltd, cti contractors ltd
ADDRESS: 100-2150 steel road
Prince George, British Columbia
v2k5b7, Canada

| | |
|---|---|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Not Applicable |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Repaired (same day) replace slack adj #1 & 2 lh |
| Section 3A - Air Brakes | Passed |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary Equipment | Not Applicable |
| Section 6 - Lamps | Repaired (same day) marker & signal |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

| Axles | Type | Size | Slack Adj. | Left | Right |
|-------|-------|------|------------|------|-------|
| 1 | Clamp | 30 | Automatic | 35 | 35 |
| 2 | Clamp | 30 | Automatic | 35 | 35 |
| 3 | Clamp | 30 | Automatic | 35 | 35 |

Comment:

Tire Tread Depth (mm)

| Outer L | Inner L | Inner R | Outer R | Steering |
|---------|---------|---------|---------|----------|
| 9.5 | 13.5 | 12.7 | 12.7 | |
| 15.1 | 11.9 | 10.3 | 11.1 | |
| 15.1 | 15.1 | 10.3 | 12.7 | |

Comment:

Air Brake Camshaft Rotation (degrees)

| Axles | Left | Right |
|-------|------|-------|
| 1 | 39 | 75 |
| 2 | 48 | 45 |
| 3 | 63 | 78 |

Comment:

Brake Lining/Pad (mm)

| Lining/Pad | Left | Right |
|---------------|------|-------|
| Lining (Shoe) | 19 | 17 |
| Lining (Shoe) | 18 | 18 |
| Lining (Shoe) | 17 | 17 |

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

| Rotor/Drum | Left | Right |
|------------|------|-------|
| Drum | | |
| Drum | | |
| Drum | | |

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: VEEKEN, NICHOLAS JOHANNES
Road Test Date:
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-03 12:41 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

FILE COPY

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014

6/3/2025 12:41:49 PM PDT