04063350

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba C048445

Date Inspection Started: DAY 23 MO. 02 YR. 26

Date Inspection Completed: DAY 24 MO. 02 YR. 26

Inspection Expiry Date: DAY 28 MO. 02 YR. 27

Station Number: A2019 Station Name: R Lewandoski Farms City: Sandy Lake

Mechanic Number: M9415 Mechanic Signature: [signature] Station Phone Number: 204-585-2120

Vehicle Owner: Charlene M Lewandosky

Address: City: Province: Postal Code: Phone:

[X] Pass/Safe Vehicle
[X] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: TE4082 Prov.: MB NSC #: Odometer Reading: Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 2DEGBSA338102412610 Make: Dopker Model: Gran Year: 08 Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer [X] Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Circle Brake Type. Defects (if any): 3A(15-B) axle 1L lining worn; 3A(15-D worn) axle 1L + 3L drums
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 9(1-B) axle 1 L inside + out tread depth.
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	new	18	new	16.560	1.5	1.5
2	18	18	16.550	16.555	1.5	1.5
3	15	17	new	16.590	1.5	1.5
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
1	3	3	6	7	16	16			16	16						
2	13	12	6	9												
3	11	11	6	6												
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE