Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number:	PA20510	Inspection Result:	
Decal Expiry Date:	2027-Aug-31		**PASS**
Inspection Number:	21890555		

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Aug-21 07:00 AM MST
INSPECTOR:	WASSENAAR, MICHAEL ANTHONY / 200357	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Aug-21 07:30 AM MST
WORK ORDER #:		**INSP. REASON:**	Annual		

VEHICLE JUR:	British Columbia	**REGI:**	13534285	**VIN:**	1FD0W5HT0MEC15957
PLATE #:	XX1492	**UNIT/FLEET#:**	PT7	**OWNER/LESSEE NAME:**	DENALI ENERGY SERVICES, LTD
LICENCED GVW(kg):	17300	**BODY STYLE:**	Flat Deck	**ADDRESS:**	PO BOX 236
VEHICLE YEAR:	2021	**ODOMETER:**	272125 KM		Pouce Coupe, British Columbia
MAKE:	FORD	**HUB ODOMETER:**			V0C 2C0, Canada
MODEL:		**BRAKE TYPE:**	Hydraulic		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Tire Tread Depth (mm)

Axles	Outer L	Inner L	Inner R	Outer R	Steering
1	6			6	✔
2	6	6	6	6	

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	13	13
Pad	13	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor	39.00	39.00
Rotor	39.00	39.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: WASSENAAR, MICHAEL ANTHONY **Signature:**

This Inspection Report was submitted to CVSE on 2026-Aug-21 08:43 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE. KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/21/2026 8:44:03 AM MST

Commercial Vehicle Inspection Report

Decal Number: PA20511
Decal Expiry Date: 2027-Aug-31
Inspection Number: 21890563

Inspection Result: **PASS**

FACILITY:	NORTHERN B.C. TRUCKERS' / N5398	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Aug-21 07:30 AM MST
		INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	**INSP. COMPLETE:**	2026-Aug-21 08:00 AM MST
INSPECTOR:	WASSENAAR, MICHAEL ANTHONY / 200357	**INSP. REASON:**	Annual		
WORK ORDER #:					

VEHICLE JUR:	British Columbia	**REGI:**	14024068	**VIN:**	2T9HC1208AT166641
PLATE #:	25119K	**UNIT/FLEET#:**	T 08	**OWNER/LESSEE NAME:**	DENALI ENERGY SERVICES, LTD
LICENCED GVW(kg):	0	**BODY STYLE:**	Flat Deck Trailer	**ADDRESS:**	PO BOX 236
VEHICLE YEAR:	2010	**ODOMETER:**			Pouce Coupe, British Columbia
MAKE:	TRAIL PRO	**HUB ODOMETER:**			V0C 2C0, Canada
MODEL:	GOOSE	**BRAKE TYPE:**	Electric		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	**Passed with Caution**	LEFT REAR CORNER MARKER MISSING
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Depth (mm)

Axles	Outer L	Inner L	Inner R	Outer R	Steering
1	6	4	8	8	
2	8	8	8	8	

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	5	5
Lining (Shoe)	5	5

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	305.80	305.90
Drum	305.50	305.50

Comment:

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: WASSENAAR, MICHAEL ANTHONY **Signature:**



This Inspection Report was submitted to CVSE on 2026-Aug-21 08:48 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/21/2026 8:48:23 AM MST