KOVA ENGINEERING | 780.296.4765 ca.info@industrial-ia.com | 4404 94 Street NW Edmonton, AB T6E 6T7 | kova.com

FORMAL STRUCTURAL REPORT

Denali Energy Services Ltd.
PO Box 236
Dawson Creek, BC V0C 2C0

Attention: Connor Pewarchuk

Owner: Denali Energy Services Ltd.

Structural Inspection of Fassi Articulating Crane

MODEL: F85B.0.24, **SERIAL:** 0850-1209, **UNIT:** PT4

ODOMETER: 306,870 km

LOCATION: Denali Yard

DATE OF INSPECTION: September 26, 2026

PURCHASE ORDER: PT4

OUR FILE: X07025-3

Visual examinations and magnetic particle inspections were performed on the above-described equipment in accordance with Kova Engineering Inspection Plan (KSIP3-X07025-3). The specific items examined and our inspection findings were as follows:

1. Outriggers (2x) - no defects noted.
2. Main Frame - no defects noted.
3. Pedestal Turret - no defects noted.
4. Main Boom Section - no defects noted.
5. Articulating Boom Section - no defects noted.
6. First Hydraulic Boom Extension - no defects noted.
7. Second Hydraulic Boom Extension - no defects noted.
8. Third Hydraulic Boom Extension - no defects noted.
9. Hydraulic Boom Tip Extension - no defects noted.
10. 5.4 tonne S.W.L. Alloy Swivel Load Hook - no defects noted.

THE EQUIPMENT IS JUDGED STRUCTURALLY SUITABLE FOR ITS INTENDED SERVICE.

Yours very truly,
KOVA ENGINEERING LTD.
the Crane Certification Bureau™

PROFESSIONAL ENGINEER PROVINCE OF BRITISH COLUMBIA M. HANES #31510 2026-Sep-30
PN: 1001263

PROFESSIONAL ENGINEER ALBERTA MATT HANES ID 89047 2026-Sep-30

PERMIT TO PRACTICE
KOVA ENGINEERING LTD.
RM SIGNATURE:
RM APEGA ID #: 89047
DATE: 2026-Sep-30
PERMIT NUMBER: P005138
The Association of Professional Engineers and Geoscientists of Alberta (APEGA)

Matt Hanes, P. Eng.
MH:vwo