

507-1

Vehicle and Equipment Asset Recovery Form

DATE: 21 FEB 26

VEHICLE INFORMATION: Unit 117

YEAR: 2012 MAKE: NISSAN MODEL: LEAF  
VIN #: JN1AZ0CPXCTD15795 MILEAGE: 7043 Km  
GAS: \_\_\_\_\_ DIESEL: \_\_\_\_\_ PROPANE: \_\_\_\_\_ HYBRID: \_\_\_\_\_ OTHER: EV  
VEHICLE RUNS:  YES  NO DRIVE TRAIN: AWD  FWD  RWD  4X4  
DATE AND STATUS OF COMMERCIAL VEHICLE CVP: \_\_\_\_\_ NI

LIST OF ITEMS EXTRAS, MANUALS, ACCESSORIES, SPARE PARTS: BATTERY CAPACITY  
AS DOCUMENTED FAILURE. SEE ATTACHED QUOTE  
FOR REPAIR ESTIMATE.

EQUIPMENT INFORMATION:

MAKE: \_\_\_\_\_ MODEL: \_\_\_\_\_

ITEM DESCRIPTION: \_\_\_\_\_

LIST OF ITEMS EXTRAS, MANUALS, ACCESSORIES, SPARE PARTS: \_\_\_\_\_

F

