

rb RITCHIE BROS. Diagnostic Report
Auctioneers®

2018 International DuraStar 4300

Test Information	
Engine	Cummins B 6.7 (6.7)
Engine Serial	CMMNS*6B u17D067000000*74086797
VIN	1HTMMMMNXJH471856
Driveline	Class 7 4x2
Body	Truck MDHD: Conventional
Test Time	April 21, 2026, 1:16 p.m.
File Length	43.733 s

Usage		
Label	Value	Units
Engine Odometer	277,483	mi
Odometer (Instrument Cluster #1)	277,458	mi
Engine Total Hours of Operation	12,979.7	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	0	%

Engine On/Off
Engine running

Check Engine Light
No check engine lights on

Emissions Deleted/Tampered
No

Faults				
DM	Controller Name	SPN Name	FMI Name	Count
Active	Body Controller	Disengage Differential Lock Request - Rear Axle 1	Erratic, Intermittent, or Incorrect	1
Previous	Engine #1	Aftertreatment 1 Diesel Particulate Filter Intake Temperature	High-moderate severity	1
Previous	Engine #1	Aftertreatment Diesel Particulate Filter System	Erratic, Intermittent, or Incorrect	2
Previous	Brakes - System Controller	Battery Potential / Power Input	Voltage Above Normal	104
Previous	Brakes - System Controller	Wheel Sensor ABS Axle 2 Left	Erratic, Intermittent, or Incorrect	66
Previous	Brakes - System Controller	Brake System Dump Modulator Valve Solenoid Axle 1 Right	Current Below Normal	9
Previous	Instrument Cluster #1	Source Address 11	Abnormal Update Rate	122
Previous	Instrument Cluster #1	Source Address 3	Abnormal Update Rate	1
Previous	Body Controller	Manufacturer Assignable SPN	Special Instruction	1
Previous	Body Controller	Manufacturer Assignable SPN	Erratic, Intermittent, or Incorrect	1
Previous	Body Controller	Source Address 0	Data Error	2
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Particulate Filter Intake Temperature	High-moderate severity	1
Emissions Previous	Engine #1	Aftertreatment Diesel Particulate Filter System	Erratic, Intermittent, or Incorrect	2