

Submission	Section Name	Name	Unit #	Date	Unit Hours	Description of Work	Total Time to Complete Work
27968	Work Completed	Doug	219	11/23/2022	4460	Removed left front tire chain.	1
27986	Work Completed	Doug	219	11/26/2022	4699	Serviced engine oil and fuel. Cleared ice from fuel lines. Secured cross bar from cab to the hood. Tightened loose fitting on rear bank valve. Changed fuel filters(Wouldn't prime because frozen). Replaced	6.5
28010	Work Completed	Doug	219	11/30/2022	4753	3 amp fuse. Pumped up right front tire due to low air pressure(to 20 psi).	5
28025	Work Completed	Doug	219	12/02/2022	4754	Replaced 3 amp fuse-machine fired right up.	0.5
28040	Work Completed	Doug	219	12/05/2022	4779	Replaced fuses. Still has issues with fuel level sensor popping fuse.	1
28061	Work Completed	Darcy	219	11/15/2022	4510	Changed hose under fuel tanks.	4
28063	Work Completed	Darcy	219	11/16/2022	4540	Installed pin back into arch.	1.5
28082	Work Completed	Darcy	219	11/22/2022	4630	Tightened up chains.	2
28099	Work Completed	Darcy	219	11/30/2022	4712	Fuel codes-needed main filter.	1.5
28109	Work Completed	Darcy	219	12/01/2022	4705	Fuel filter issues. Codes derate.	2
28117	Work Completed	Darcy	219	12/05/2022	4779	Removed fuel lines to remove water. Drain fuel tanks and replaced filters.	5
28160	Work Completed	Darcy	219	12/13/2022	4875	Blown arch hose. Changed boom cylinder hose. Added 3 pails of hydraulic oil and 1 jug of engine oil. Checked air filter and	2
28167	Work Completed	Doug	219	12/13/2022	4875	installed left front tire chain.	4
28195	Work Completed	Ken	219	12/15/2022	4889	Repair tire chains.	2.5
28209	Work Completed	Ken	219	12/16/2022	4890	Took chain off, reset, installed back on.	3
28296	Work Completed	Ken	219	01/03/2023	4969	Oil change.	2
28320	Work Completed	Doug	219	01/04/2023	4982	Deactivated seat.	0.5
28353	Work Completed	Darcy	219	01/09/2023	5000	Replaced O-ring on drive pump.	2
28375	Work Completed	Darcy	219	01/10/2023	5023	Repaired blown grapple hose.	2
28427	Work Completed	Darcy	219	01/17/2023	5145	Bent guards and replaced arch hose.	3.5
28461	Work Completed	Ken	219	01/20/2023	5200	Oil change. Fixed oil leak on arch.	1
28467	Work Completed	Darcy	219	01/20/2023	5200	Oil change.	2
28510	Work Completed	Darcy	219	01/25/2023	5298	Installed tire chains.	6
28556	Work Completed	Doug	219	01/30/2023	5300	Took inventory on what parts are needed.	1
28575	Work Completed	Doug	219	01/31/2023	5376	Removed arch.	7
28703	Work Completed	Ken	219	02/15/2023	5383	Put arch back together.	4
28708	Work Completed	Darcy	219	02/15/2023	5383	Put arch back on.	4
28739	Work Completed	Dustin	219	02/20/2023	5383	Helped find leak in swivel manifold.	3
28742	Work Completed	Doug	219	02/20/2023	5383	Worked with Dustin on rotate manifold issue(broken bolts on top plate).	2
28819	Work Completed	Darcy	219	03/01/2023	5508	Overdrive clutch code-checked fluids/wiring.	2
28976	Work Completed	Doug VanDerVlugt	219	03/13/2023	5610	changed RS speed sensor welded broken arch pin ear, re installed arch pin, re installed light housing, replaced fuse - 15 amp for	1.5
28984	Work Completed	Doug VanDerVlugt	219	03/15/2023	5631	lights	2.5
29053	Work Completed	Ken Martens	219	03/13/2023	5610	oil change, fix side light	3
29349	Work Completed	Wade Sanchuck	219	07/12/2023	5696	pumped up the tire on unit	1
29448	Work Completed	Herman Peters	219	08/02/2023	5696	wash unit	6
29482	Work Completed	Doug VanDerVlugt	219	07/25/2023	5698	made repair list, boosted	2
29539	Work Completed	Herman Peters	219	08/03/2023	5696	wash unit	9
29540	Work Completed	Herman Peters	219	08/08/2023	5696	wash unit	12
29541	Work Completed	Herman Peters	219	08/09/2023	5696	wash unit	12
29542	Work Completed	Herman Peters	219	08/10/2023	5696	wash unit	4
29674	Work Completed	Dustin Hackworth	219	08/23/2023	5699	do complete oil service, finish filling new diff, transfer case, and front diff	6
29675	Work Completed	Dustin Hackworth	219	08/24/2023	5699	add remaining oil in rear diff, transfer case, front diff for service completion take arch off of unit to inspect the pins and bushings. put arch back together, get guards for unit and place	1
29699	Work Completed	Dustin Hackworth	219	08/29/2023	5699	them where it is needed	11

29703 Work Completed	Wade Sanchuck	219 08/29/2023	5696 help Dustin with arch, take it apart and inspect it and put it back together again	3
29719 Work Completed	Dustin Hackworth	219 09/05/2023	5968 install gaurds, weld bolts and check lights	12
29721 Work Completed	Dustin Hackworth	219 09/06/2023	5968 tighten and adjusted bolts, check pins, repair guards and bolt cab down	9
29724 Work Completed	Dustin Hackworth	219 09/07/2023	5698 repair leak on cylinder hose, remove cylinder for repairs.	9
29729 Work Completed	Dustin Hackworth	219 09/08/2023	5968 put arch cylinder on, remove arm arch cylinder	2
29739 Work Completed	Dustin Hackworth	219 09/12/2023	5968 put on cylinder	1.5
29753 Work Completed	Dustin Hackworth	219 09/13/2023	5968 put on cylinder and guards	1
29761 Work Completed	Dustin Hackworth	219 09/15/2023	5968 weld blades to grapple for stability, take apart	2
29766 Work Completed	Dustin Hackworth	219 09/18/2023	5968 change bushings in grapple	6
29778 Work Completed	Wade Sanchuck	219 09/18/2023	5968 weld new pear bushings	2
29821 Work Completed	Wade Sanchuck	219 10/13/2023	5968 changed flat tire	1.5
29829 Work Completed	Dustin Hackworth	219 10/16/2023	5696 put chains on	5
29940 Work Completed	PJL Oilfield	219 11/01/2023	6038 repair 2 front chains	3
30071 Work Completed	Doug	219 11/21/2023	5714 changed RH speed sensor, tighten 2 hose clamps on main pump	2.5
30078 Work Completed	Doug	219 11/22/2023	5714 replaced o-ring, adjusted seat, tighten all loose cap screws in cab, repaired warning alarm	7.5
30105 Work Completed	Doug	219 11/24/2023	5715 greased, replaced seleniod for drive motor, replace FR light, flipped stump pan on rear frame	4
30158 Work Completed	Doug	219 11/29/2023	5739 tighten hyd filter	0.5
30179 Work Completed	Doug	219 12/04/2023	5776 inflated tire LF	1
30204 Work Completed	Doug	219 12/07/2023	5803 replaced clevis RF	1
30220 Work Completed	Doug	219 12/08/2023	5821 looked into radio issues	1
30239 Work Completed	Doug	219 12/12/2023	5850 added 1 jug engine oil, removed broken grapple brake pin, replaced pin, greased friction disc pack shaft	6
30241 Work Completed	Doug	219 12/13/2023	5868 removed LF tire chain, reinstalled	2
30255 Work Completed	Doug	219 12/15/2023	5911 replaced 2 clevis, tighten the rest	1.5
30260 Work Completed	Doug	219 12/18/2023	5938 tighten chains	3
30263 Work Completed	Doug	219 12/19/2023	5953 service engine oil, replaced strap step, fixed joystick	2.5
30346 Work Completed	Doug	219 12/28/2023	6036 tighten hyd filter, added 1 jug of engine oil	1.5
30429 Work Completed	Doug	219 01/08/2024	6108 check over, cleanded up treads on LR hub bolt hole	5
30454 Work Completed	Doug	219 01/10/2024	6120 replaced bolt on right door screen	0.5
30487 Work Completed	Doug	219 01/16/2024	6144 tighten loose fitting on steering cylinder, tighten loose hyd filter, replaced missing wheel bolts	2.5
30519 Work Completed	PJL Oilfield	219 01/18/2024	6171 check codes, bad wiring behind seat	4
30553 Work Completed	Dustin	219 01/22/2024	6219 change grapple hose inside arm	5
30558 Work Completed	PJL Oilfield	219 01/22/2024	6219 replace #16 hose and bulk head	5
30570 Work Completed	PJL Oilfield	219 01/23/2024	6238 instal seat harness, change module out	4
30583 Work Completed	PJL Oilfield	219 01/24/2024	6238 change fuse, repair wires on seat module	3
30672 Work Completed	Doug	219 02/01/2024	6329 changed #16 hose	2.5
30741 Work Completed	PJL Oilfield	219 02/07/2024	6405 replaced hose, top up oil	6
30771 Work Completed	Doug	219 02/09/2024	6349 removed boom cyld	2
30792 Work Completed	Doug	219 02/12/2024	6470 serviced engine oil, fuel and air checked, changed fuel line	4
30856 Work Completed	Doug	219 02/16/2024	6544 aired up tire, replaced missing clevis RF tire	3.5
30883 Work Completed	Doug	219 02/21/2024	6592 repaird wire behind seat, replaced 2 clevis.	9
30998 Work Completed	PJL Oilfield	219 03/06/2024	6707 inflate two rear tires	1
31008 Work Completed	PJL Oilfield	219 03/07/2024	6727 change hose in arch	3
31255 Work Completed	Doug	219 05/15/2024	6838 removed stump pans and side guards	1
31277 Work Completed	Dustin	219 05/23/2024	6838 drain all oil out of engine and transfer case and both diffs, change all filters and top up everthing with oil changed all air filters, prime fuel, install guards, repair bolt holes, straighten guards, weld mesh on engine	6
31284 Work Completed	Dustin	219 05/24/2024	6838 guard, readjust grill to close	12
31295 Work Completed	Wade	219 05/29/2024	6838 welded guards	3

31297 Work Completed	Dustin	219 05/29/2024	6838 replace brake pin on grapple replaced splined grapple pin, front top center light, check drive line, tighten FOPS mount, straighten	1
31299 Work Completed	Doug	219 05/29/2024	6843 bottom cab guards, replaced step and checked pins and bushings	12
31302 Work Completed	Doug	219 05/30/2024	6843 change LR tire, inflate LF tire	2.5
31306 Work Completed	Doug	219 05/31/2024	6843 secured slip stick tube, replaced seat direction sensor, review park brake issue	11
31309 Work Completed	Wade	219 05/31/2024	6838 inspect issues with unit	2
31312 Work Completed	Doug	219 06/03/2024	6843 change door sensor	2.5
31322 Work Completed	Doug	219 06/05/2024	6938 repair park brake, change out ignition and seat harness, buttoned up skidder	4.5
31338 Work Completed	Wade	219 06/11/2024	6838 welded crack on bump stops	1
31761 Work Completed	Doug	219 09/23/2024	6847 changed RF tire, flipped DEF tank stump pan, welded crack on rear frame	2.5
31773 Work Completed	Doug	219 09/25/2024	6847 installed RF tire,	5
31794 Work Completed	Doug	219 10/03/2024	6849 installed LF tire chains	3
31817 Work Completed	Phillip	219 10/09/2024	6855 installed tire chain on rear tires	4
31841 Work Completed	Dustin	219 10/09/2024	6855 install tire chains	3
31879 Work Completed	Doug	219 10/19/2024	6933 tighten hyd filters, changed #20 o-ring under cab, added hyd oil	3.5
31880 Work Completed	Doug	219 10/20/2024	6933 changed battery	2
31928 Work Completed	PJL	219 10/25/2024	6966 tighten BL chains	2
31930 Work Completed	PJL	219 10/25/2024	7000 change RR tire	2
31933 Work Completed	PJL	219 10/26/2024	7015 change engine oil and filters, fuel and air filters	3
31959 Work Completed	PJL	219 10/29/2024	7049 repair chains	3
31963 Work Completed	Phillip	219 10/29/2024	7049 remove and reinstall rear chains	1
31970 Work Completed	PJL	219 10/30/2024	7059 swap joice stick	3
31995 Work Completed	PJL	219 11/02/2024	7118 change RR tire	2
32001 Work Completed	PJL	219 11/04/2024	7140 repair FR chain	2
32033 Work Completed	PJL	219 11/07/2024	7140 repair FL track chain	2
32049 Work Completed	PJL	219 11/09/2024	7228 change RL tire	4
32058 Work Completed	PJL	219 11/11/2024	7274 change engine oil and filter, air filter and fill up tires, change hose in arch, top up hyd oil	5
32097 Work Completed	PJL	219 11/18/2024	7381 check codes and fuses	2
32103 Work Completed	PJL	219 11/19/2024	7390 exchanged relay for acc power	3
32108 Work Completed	Phillip	219 11/12/2024	7280 change alternator	4
32118 Work Completed	Phillip	219 11/14/2024	7303 repair rear cab lights	1.5
32120 Work Completed	Phillip	219 11/15/2024	7344 repair oil leak on grapple rotate	2.5
32185 Work Completed	Phillip	219 11/26/2024	7556 straighten front grill and put in new bolts, change motor oil and filters	3
32213 Work Completed	PJL	219 11/30/2024	7628 repair leak on arch	3
32263 Work Completed	PJL	219 12/06/2024	7628 change arch cyld	2
32280 Work Completed	Phillip	219 12/10/2024	7781 change hyd hose for grapple rotate	3
32316 Work Completed	Phillip	219 12/12/2024	7836 change motor oil and filters, air , oil and fuel. change 3 lights on top of cab, tighten up left side front chains	4
32372 Work Completed	Phillip	219 12/18/2024	7959 repair oil leak on boom	3
32396 Work Completed	Phillip	219 12/20/2024	7994 repair oil leak on boom	4
32408 Work Completed	Doug	219 12/27/2024	8014 replaced #16 hose on boom	4.5
32469 Work Completed	PJL	219 01/06/2025	8137 change oil and fitler	1
32496 Work Completed	PJL	219 01/08/2025	8161 adjust door rod	2
32505 Work Completed	PJL	219 01/09/2025	8189 repair broken plug under cab	4
32535 Work Completed	PJL	219 01/13/2025	8275 change hose in arch	2
32713 Work Completed	PJL	219 01/16/2025	repair leaking hose on arch	2
32726 Work Completed	PJL	219 01/20/2025	8437 oil change, and filters - oil, fuel and air	2
32738 Work Completed	PJL	219 01/24/2025	8437 change hose on arch, blow out cab	3
32752 Work Completed	PJL	219 01/29/2025	8611 change fan belt and tensioner	5
32760 Work Completed	PJL	219 01/31/2025	8659 repair door latch and install new step	2

32767 Work Completed	PJL	219 02/01/2025	8659 change FL tire	2
32779 Work Completed	PJL	219 02/05/2025	8720 cold start, top up coolant	2
			oil change and filters, 2 hyd hoses on boom cyld, repair oil leak on dozer cyld. change FL tire and install	
32786 Work Completed	Phillip	219 02/06/2025	8748 chain, change grapple yoke shaft and splined part for shaft	7
32794 Work Completed	PJL	219 02/08/2025	8786 change hose in arch, top up oil	4
32835 Work Completed	PJL	219 02/14/2025	8934 change valve stem FL tire	2
32869 Work Completed	PJL	219 02/19/2025	9047 oil change and filter	2
32888 Work Completed	PJL	219 02/22/2025	9047 change hose in arch and blow down machine	4
32921 Work Completed	PJL	219 02/26/2025	9154 repair top cab lights	2
32935 Work Completed	PJL	219 02/27/2025	9196 repair lights in arch	3
32973 Work Completed	PJL	219 03/01/2025	9201 change hose in arch and top up oil	4
32992 Work Completed	Doug	219 03/11/2025	9207 removed tire chains, removed guards,	1.5
33001 Work Completed	Doug	219 03/12/2025	9207 remove guards, start 2000 hrs service	2.5
33008 Work Completed	Doug	219 03/13/2025	9207 change tranny filter and oil, and hyd filter	2
33014 Work Completed	Doug	219 03/14/2025	9207 serviced front and rear diff, reattached joystick left.	5
			install new step, change out the side colom for heat vents, change hot/cold selector switch, install	
33368 Work Completed	Wade	219 07/16/2025	9211 bushings in boom	5
33371 Work Completed	Doug	219 07/16/2025	9211 installed right side steps, removed and re;aced arch/boom bushings and pin	7.5
33393 Work Completed	Wade	219 07/21/2025	9211 install guards	5
			Replaced 2 wheel bolts, fuel tank mount, cross over valve and hose at arch to boom. made guard for 2-way	
33394 Work Completed	Doug	219 07/21/2025	9218 antena and installed	8.5
			replaced - light and small round vent. finished installing gurads, filled water tank, and greased unit,	
33400 Work Completed	Doug	219 07/22/2025	9224 charged A/C	6
33406 Work Completed	Wade	219 07/23/2025	9211 changed the arc bushing and tires,	12
33407 Work Completed	Doug	219 07/23/2025	9224 arch bushings and tire chains	6
33413 Work Completed	Doug	219 07/24/2025	9224 replaced key switch fuse	0.5
33428 Work Completed	Doug	219 07/29/2025	9233 repaired 2 frayed wires	2
33484 Work Completed	Doug	219 08/08/2025	9383 reinstalled boom arch pin with shims	1.5
33494 Work Completed	Doug	219 08/11/2025	9405 changed boom, grapple and alterator	10.5
33499 Work Completed	Doug	219 08/12/2025	9405 replaced #4 hose, light wire and greased boom and grapple.	10.5
33508 Work Completed	Doug	219 08/13/2025	9418 re installed RF tire chains	3
33526 Work Completed	Doug	219 08/18/2025	9476 serviced engine oil, replaced 2 small round vents	2
33542 Work Completed	Doug	219 08/21/2025	9476 removed seat base, replaced door latch	2.5
33570 Work Completed	Doug	219 08/27/2025	9512 tighten up loose fitting on boom cyld, right side	1
33595 Work Completed	Doug	219 09/02/2025	9591 replaced fuse and arm seat harness	1
33683 Work Completed	Doug	219 09/17/2025	9761 replaced broken vent and 3 lights	1
33705 Work Completed	PJL	219 09/20/2025	9797 change oil and filters	3
33861 Work Completed	Phillip	219 10/21/2025	9887 install two chains in the back, change front lift chain	6
33864 Work Completed	PJL	219 10/21/2025	install 2 new chain in rear and 1 used chain in front, remove guards for washing	12
33866 Work Completed	Phillip	219 10/22/2025	9887 install all guards	2
33949 Work Completed	PJL	219 11/03/2025	10050 change oil and filters, clean air filter	2
34044 Work Completed	PJL	219 11/15/2025	10296 repair leak under cab and on arch cyld, oil change and filters - oil, air and fuel.	4
34047 Work Completed	Rylan	219 11/15/2025	10296 change o-ring, serviced	4
34072 Work Completed	Rylan	219 11/18/2025	10368 changed step	4
34106 Work Completed	Rylan	219 11/27/2025	10543 oil and air filter change, tighten tire chains	4
34124 Work Completed	Rylan	219 12/01/2025	10629 tighten loose fitting, topped up oil	2
34186 Work Completed	PJL	219 11/27/2025	10550 help with chains	2
34190 Work Completed	Phillip	219 11/27/2025	10543 change seat wire harness, tighten all 4 tire chains	4
34207 Work Completed	PJL	219 11/30/2025	10609 repair rear arch lights, instal new light box and light	3
34229 Work Completed	Phillip	219 12/03/2025	10984 change seat harness, repair oil leak on boom cyld and seat compressor issue	6

34238 Work Completed	Phillip	219 12/04/2025	10699 repair electrical on seat compressor	3
34266 Work Completed	PJL	219 12/07/2025	10770 change eoil and filters, fuel, air. repair rear light bracket	3
34398 Work Completed	Rylan	219 01/05/2026	11022 instal gas cap, and straighten light bracket	3
34415 Work Completed	Rylan	219 01/07/2026	11067 oil change, oil and air filters	3
34421 Work Completed	Rylan	219 01/08/2026	11091 removed grapple	6
34433 Work Completed	Rylan	219 01/09/2026	11095 install grapple, and two new hoses on, adjusted lights, filled with oil and remounted radio	8
34437 Work Completed	PJL	219 01/09/2026	11844 change shaft and 2 hose to grapple	8
34475 Work Completed	Rylan	219 01/13/2026	11144 tighten chains, repaired leak on side of hyd pump	6
34644 Work Completed	Phillip	219 01/29/2026	11363 oil change and filters - oil, fuel and air. change side steps	6
34805 Work Completed	Rylan	219 02/22/2026	11689 change seat harness	2
34806 Work Completed	Rylan	219 02/23/2026	11689 repair e-step, topped up coolant, install new conncetor on seat harness	6
34819 Work Completed	Rylan	219 02/28/2026	11795 welded bushings in	3
34820 Work Completed	Rylan	219 03/01/2026	11807 change o-ring on plug in grapple	4
34870 Work Completed	PJL	219 02/13/2026	11598 change hose in arch, top up oil	3
34875 Work Completed	PJL	219 02/15/2026	11610 change out bad seat harness	4
34879 Work Completed	PJL	219 02/16/2026	11623 change oil and filters - oil and air. tighten all chains	4
34886 Work Completed	PJL	219 02/18/2026	check code, change broken filter for clutch preasure, top up oil	3
34889 Work Completed	PJL	219 02/19/2026	11615 change hose in arch, top up oil	3
34951 Work Completed	Rylan	219 03/08/2026	11913 change hose on grapple	13
35253 Work Completed	Wade	219 06/17/2026	11913 removed boom bushings for line boring	12
35268 Work Completed	Wade	219 06/19/2026	11913 installed new bushings	6
35375 Work Completed	Kyle	219 07/25/2026	11913 200hr Service	6
35382 Work Completed	Kyle	219 07/26/2026	12000 remvoe fuel filter housing, install panels, remove and replace A/C compressor	5
35383 Work Completed	Kyle	219 07/27/2026	12000 charge A/C system, install panels, replace stop switch and repair door window guards	12
35388 Work Completed	Kyle	219 07/29/2026	12000 perform running checks, install new step slings	6
35391 Work Completed	Clinton	219 07/29/2026	12000 installed panels	4
35399 Work Completed	Kyle	219 07/30/2026	12000 remove grapple and boom	3
35407 Work Completed	Kyle	219 08/12/2026	12100 replace boom and grapple break	12
35408 Work Completed	Kyle	219 08/05/2026	12100 hose repair on boom, and clean out blower heater box	12
35417 Work Completed	Kyle	219 08/07/2026	12000 repair lights on cab	3
35542 Work Completed	Clinton	219 09/10/2026	12044 installed fitting to bypass heater valve, topped up coolant,	3
35549 Work Completed	Clinton	219 09/11/2026	12058 replaced heater valve	4