

Submission	Section Name	Name	Unit #	Date	Unit Hours	Description of Work	Total Time to Complete Work
28004	Work Completed	Doug	602	11/29/2022	24822	Reattached steering cylinder(threaded it in as far as possible-then welded).	1
28012	Work Completed	Doug	602	11/30/2022	24828	Boosted.	1
28037	Work Completed	Doug	602	12/05/2022	24829	Changed and aired up tire.	2
28084	Work Completed	Darcy	602	11/23/2022	24797	Diagnosed grader wiring issues and blown U-joint.	3
28096	Work Completed	Darcy	602	11/26/2022	24797	Replaced drive shaft U-joint.	2
28105	Work Completed	Darcy	602	11/30/2022	24828	Front fender busted off. Changed batteries.	1.5
28134	Work Completed	Ken	602	12/09/2022	24830	Installed grader snow wing.	4.5
28139	Work Completed	Ken	602	12/10/2022	24830	Changed hose going from front to back.	9
28144	Work Completed	Darcy	602	12/12/2022	25012	Ripper hose.	2
28218	Work Completed	Ken	602	12/17/2022	25020	Replaced O-ring.	2
28260	Work Completed	Ken	602	12/29/2022	25241	Changed grader cylinder.	3
28266	Work Completed	Ken	602	12/30/2022	25254	Changed motor oil.	2
28413	Work Completed	Darcy	602	01/13/2023	25460	Replaced teeth and changed a hose.	3.5
28492	Work Completed	Ken	602	01/24/2023	25603	Changed hose. Resealed valve on pump.	7
28506	Work Completed	Ken	602	01/25/2023	25624	Installed 12 V plug and fixed lights.	3
28580	Work Completed	Ken	602	02/01/2023	25741	Oil change.	2
28602	Work Completed	Ken	602	02/02/2023	25758	Fixed joystick buttons and window.	3.5
28632	Work Completed	Ken	602	02/07/2023	25835	Changed tips.	1
28694	Work Completed	Ken	602	02/14/2023	25967	Changed alternator.	4
28715	Work Completed	Ken	602	02/16/2023	26009	Fixed electrical problem on tire tilt. Fixed moboard and fender.	4
28765	Work Completed	Ken	602	02/23/2023	26111	Moboard tightened and changed tips.	1
28828	Work Completed	Ken	602	03/02/2023		Changed tips and fixed lights.	2
28864	Work Completed	Ken	602	03/06/2023	26304	Oil change.	2
28913	Work Completed	Darcy	602	03/10/2023	26389	Replaced rear tire.	4
28930	Work Completed	Darcy Unruh	602	03/21/2023	26390	tighten trunyan bolts, looked over machine	4
28950	Work Completed	Wade Sanchuck	602	04/12/2023	26541	removed side shift for reselling	2
29025	Work Completed	Wade Sanchuck	602	04/03/2023	26541	remove wing, repair oil leak	6
29026	Work Completed	Wade Sanchuck	602	04/04/2023	26541	remov wing cylinder, fix engine oil leak from oil filter housing	5
29029	Work Completed	Wade Sanchuck	602	04/05/2023	26541	removed EGR and exhaust - both leaking	9
29047	Work Completed	Doug VanDerVlugt	602	04/11/2023	26541	help Wade	1.5
29048	Work Completed	Wade Sanchuck	602	04/11/2023	26541	put bushing in two cylinder, put exhaust back on, new EGR cooler	10
29149	Work Completed	Dustin Hackworth	602	04/25/2023	26541	wash unit	10
29150	Work Completed	Dustin Hackworth	602	04/26/2023	26541	finish washing, put guards back on	3
29155	Work Completed	Wade Sanchuck	602	04/17/2023	26541	finnished resealing side shift cylinder and put it back on, put wing cylinder back on, set up ware plates for the blade	10
29156	Work Completed	Wade Sanchuck	602	04/18/2023	26541	changed oil in rear diff, changed oil in chain drive and got oil samples, changfed oil in tranny and oil samples	10
29157	Work Completed	Wade Sanchuck	602	04/19/2023	26541	drilled out and tapped a bolt for the wing blade pin keeper, put the grader in the wash bay - ready for washing	3
29237	Work Completed	Doug VanDerVlugt	602	06/13/2023	26543	make a repair list	1.5
29288	Work Completed	Doug VanDerVlugt	602	06/21/2023	26543	checked issue with tandams	1
29709	Work Completed	Wade Sanchuck	602	09/01/2023	26541	drove to mill and fixed the steering cylinder that unthreaded from the tie rod end	1.5
29772	Work Completed	Wade Sanchuck	602	09/21/2023	26541	put tandom together, intall camera in grader	11
29773	Work Completed	Wade Sanchuck	602	09/20/2023	26541	replace bushings	12
29776	Work Completed	Wade Sanchuck	602	09/19/2023	26541	move to shop, grade yard	1
29785	Work Completed	Wade Sandchuck	602	09/25/2023	26541	repair oil leak on trany	2.5
29942	Work Completed	Doug	602	11/01/2023	26556	installed wing, replaced bolt on rear wing cylinder	5
30237	Work Completed	Dustin	602	12/12/2023		install new rad and mirror on RS, replace hose and fittings	10.5

30245 Work Completed	Dustin	602 12/13/2023		replace hose and fittings	4
30270 Work Completed	Phillip	602 12/04/2023	26680	change ice picks, tighten engine oil filter	3
30330 Work Completed	Dustin	602 12/21/2023	26832	Change picks on blade	2.5
30339 Work Completed	Wade	602 12/27/2023	26851	remove BGR, filled engine with coolant, remove exhaust manifold to drain coolant	11
30343 Work Completed	Wade	602 12/28/2023	26851	Install EGR cooler, complete service	6
30353 Work Completed	Dustin	602 12/28/2023	26851	took off turbo and exhaust, oil change	5
				change antifreeze reservoir, change motor oil, change engine drain hose, change solenoid and clutch	
30358 Work Completed	Phillip	602 12/29/2023	26852	pressure valve	2
30369 Work Completed	Dustin	602 01/03/2024	26905	replace bolts on rottory pump, repair guard on hyd hose	2
30381 Work Completed	Dustin	602 01/04/2024	26918	change 54 picks, bolt guard for rottory pump hose	3
30408 Work Completed	PJL Oilfield	602 01/05/2024	26935	check problem with fan belt, install new pulley and belt	3
30411 Work Completed	PJL Oilfield	602 01/05/2024	27010	tighten shims for blade	1
30419 Work Completed	PJL Oilfield	602 01/07/2024	26995	check hyd lead, broken fitting, weld, top up oil	3
30436 Work Completed	Phillip	602 01/08/2024	27018	repair armrest wires	2.5
30459 Work Completed	PJL Oilfield	602 01/10/2024	27100	change hyd hose on blade, top up oil	3
30510 Work Completed	Dustin	602 01/18/2024	27124	change hose on left front tire area	2
30520 Work Completed	Phillip	602 02/13/2024	27124	change hyd hose on right side front wheel	3
30527 Work Completed	Dustin	602 01/19/2024	27155	tighten filter	4
30527 Work Completed	Dustin	602 01/19/2024	27155	check done for service	4
30542 Work Completed	PJL Oilfield	602 01/21/2024	27163	unplugged solenoid for articulated steer	2
30566 Work Completed	Phillip	602 01/23/2024	27163	change bolts and grease nipples	1
30613 Work Completed	PJL Oilfield	602 01/27/2024	27283	inspeck header fan, not running, need to order new one	3
30646 Work Completed	PJL Oilfield	602 01/30/2024	27300	start to remove heater motor	4
30655 Work Completed	PJL Oilfield	602 01/31/2024	27300	finish installing heater motor, change switch for wing	4
30666 Work Completed	Dustin	602 02/01/2024	27300	change oil and filter, fuel filters	3
30707 Work Completed	PJL Oilfield	602 02/04/2024	27323	Install lights on front of cab	2
30737 Work Completed	Dustin	602 02/06/2024	27359	install camera and gps box	3
30766 Work Completed	PJL Oilfield	602 02/09/2024	27550	blow out air filter	3
30767 Work Completed	Phillip	602 02/09/2024	27550	repair electrical issues on stereo	2
30794 Work Completed	Doug	602 02/12/2024	27490	change air filter	1.5
30801 Work Completed	PJL Oilfield	602 02/13/2024	27505	change fuel filters, clean inline filter	3
30817 Work Completed	PJL Oilfield	602 02/14/2024	27480	remove o-ring	3
30823 Work Completed	Phillip	602 02/14/2024	27531	repair electrical on radio	4
30835 Work Completed	Phillip	602 02/15/2024	27561	clean inline fuel filter and change air filter	2
30859 Work Completed	PJL Oilfield	602 02/18/2024	27604	remove exhaust elbow, replace 3 bolts, reattached elbow	4
30999 Work Completed	PJL Oilfield	602 03/06/2024	27868	fix hyd leak on swivel for blade	3
31481 Work Completed	Dustin	602 07/23/2024	28012	remove guards	1
31509 Work Completed	Wade	602 07/29/2024	28081	service	5
				change front hub oils, engine oil and filter, fuel filters, DIFF oil, tranny oil and filter, hyd filter, gear box oil	
31512 Work Completed	Wade	602 07/30/2024	28081	and repair steel line for coolant to the EGR	9
31527 Work Completed	Wade	602 07/31/2024	28081	changed two A/C lines, filled coolant reservoir back up	4
31530 Work Completed	Wade	602 08/01/2024	28081	instal A/C vac, charge and test	3.5
				check all plugs, repaired pinched wire on cab roof, change out lights. Rewire right rear corner light, remove	
31543 Work Completed	Dustin	602 08/06/2024	28081	two lights	10
31544 Work Completed	Wade	602 08/06/2024	28081	change o-ring on oil filter housing	2
31553 Work Completed	Dustin	602 08/07/2024	28081	tie up wires for lights, put guards on	1
31581 Work Completed	Wade	602 08/13/2024	28082	put new blocks on the mow board and new wear stripes	2.5
31588 Work Completed	Wade	602 08/14/2024	28082	install new blocks and wear strips on grader, install shims and set,	10
31610 Work Completed	Wade	602 08/19/2024	28082	removed left and right front wheel and hub, replace bushings on left	8.5
31614 Work Completed	Wade	602 08/20/2024	28082	completed the left and right hub	6

31625 Work Completed	Wade	602 08/21/2024	28082	right hub bushings installed, removed left wheel cap to replace broken bolts	10
31631 Work Completed	Wade	602 08/22/2024	28082	installed left wheel cap on new bolts and filled with oil,	3
31672 Work Completed	Wade	602 09/03/2024	28084	cut a trunion off, repaired oil leak on RF wheel	10
31969 Work Completed	Doug	602 10/30/2024	28098	recalibrated transmission	3
31985 Work Completed	Doug	602 11/01/2024	28104	removed picks, changed egr temp sensor	1
32071 Work Completed	PJL	602 11/13/2024	28732	repair loose wire on alternator	3
32081 Work Completed	PJL	602 11/14/2024	28132	instal new diode, change picks	2
32139 Work Completed	PJL	602 11/20/2024	28252	change 4 grease fittings on guard	1
32159 Work Completed	PJL	602 11/23/2024	2834	change hose for blade lift	3
32171 Work Completed	PJL	602 11/25/2024	28354	change o-rings on hose	1
32268 Work Completed	PJL	602 12/08/2024	28593	Change oil and filter, change fuel and air filter	2
32272 Work Completed	Doug	602 12/09/2024	28616	installed wing, changed hose on wing	4.5
32318 Work Completed	Phillip	602 12/12/2024	28665	repair electrical on light bar	0.5
32325 Work Completed	Doug	602 12/13/2024	28683	switched around toggles for wing and adjusted	1
32400 Work Completed	Doug	602 12/21/2024	28839	replace main belt on wing	2
32438 Work Completed	Doug	602 01/03/2025	28955	drill hole for cotter pin in wing bolt	1
32461 Work Completed	Doug	602 01/06/2025	29032	reassembled rear wing cyld, replaced front signal light	2.5
32506 Work Completed	PJL	602 01/09/2025	29103	change picks, switch for wing and #2 hose for wing	4
32522 Work Completed	PJL	602 01/11/2025	29117	remove door and broken glass	2
32524 Work Completed	PJL	602 01/12/2025	29117	install glass and door	3
32543 Work Completed	PJL	602 01/14/2025	29144	install all new shims in blade, change motor oil and fitler, fuel and air filters, top up tranny	5
32708 Work Completed	PJL	602 01/16/2025	29213	replace 2 o-rings, on blade rotor	2
32743 Work Completed	PJL	602 01/26/2025	29398	top up tranny, look for leaks, remove joy stick	4
32764 Work Completed	PJL	602 02/01/2025	29444	insall wing on, weld bolts	4
32770 Work Completed	PJL	602 02/02/2025	29456	replace hose on pump, topup hyd oil	6
32855 Work Completed	PJL	602 02/17/2025	29361	instal new shims in blade circle	3
32874 Work Completed	Phillip	602 02/20/2025	29672	change hyd hose side wing	3
32903 Work Completed	PJL	602 02/24/2025	29696	oil change and filters, oil, air and fuel	3
32911 Work Completed	PJL	602 02/25/2025	29696	change hos on front wheel	5
32916 Work Completed	Phillip	602 02/26/2025	29711	repair oil leak on blade	2
32997 Work Completed	Phillip	602 03/11/2025	27800	remove side wing	2
33000 Work Completed	PJL	602 03/11/2025	29711	remove wing	3
33045 Work Completed	Doug	602 03/24/2025	29918	Remove stump pan and guards	5
33052 Work Completed	Doug	602 03/26/2025	29918	service engine, and front hubs,	6
33054 Work Completed	Doug	602 03/27/2025	29918	serviced pinion grear drive for circle, blade slides LS, tie rods L&R, steering cyld and Left tie rod, Set toe. changed - R steering cyld tie rod, pins and bushings, R-blade slides, Air filter, and cab filters. Replaced -	8.5
33058 Work Completed	Doug	602 03/28/2025	29918	service lights, removed ball and cup off the front drag frame	10
33066 Work Completed	Doug	602 03/31/2025	29918	change a-frame wear pieces on frnt ball	6
33075 Work Completed	Wade	602 04/03/2025	29918	install new mirror, oil and filter change on tranny,	
33076 Work Completed	Wade	602 04/04/2025	29918	install new rubber blocks on Rad, install ball mount on front.	6
33079 Work Completed	Wade	602 04/07/2025	29918	oil change in rear diff, and change filters	2
33081 Work Completed	Wade	602 04/08/2025	29918	repair brake oil leak	8
33082 Work Completed	Wade	602 04/09/2025	29918	oil change in tandoms, change ball pin for side shift cyld	4
33082 Work Completed	Wade	602 04/09/2025	29918	install FL wheel hub seals	10
33083 Work Completed	Wade	602 04/10/2025	29918	remove steering valve and changed bushings in steering column	6
33085 Work Completed	Wade	602 04/11/2025	29918	instal plate to hold rad in, instal new parts in steering valve, remove old ball and weld on new one	10
33086 Work Completed	Wade	602 04/14/2025	29920	instal new cyld on side shift, inspect wire harness	10
33087 Work Completed	Wade	602 04/15/2025	29920	install new wire harness,	10

33090 Work Completed	Wade	602 04/16/2025	29920	changed out lights on cab, installed guards	4
33092 Work Completed	Doug	602 04/16/2025	29920	assisted Wade with wiring issues	2
33095 Work Completed	Wade	602 04/17/2025	29920	installed new 6 wheel drive controller, bushings for the blade lift,	10
33118 Work Completed	Doug	602 05/01/2025	29920	change grader blades and check A/C	2
33123 Work Completed	Doug	602 05/02/2025	29920	inspect A/C, leaking need parts	3
33129 Work Completed	Doug	602 05/15/2025	29920	replaced hose and o-ring RF hub, hose on A/C compressor, charged and cleaned AC system	6
33329 Work Completed	Doug	602 07/08/2025	29964	A/C issues, checked vacuum, leak at condensore	1.5
33332 Work Completed	Doug	602 07/09/2025	29964	changed A/C condensore, vacuumed A/C system, rechared A/C and tightened dif filter	3.5
33608 Work Completed	Wade	602 09/05/2025	30030	look in A/C issue, requires new system	1
33638 Work Completed	Wade	602 09/09/2025	30080	repair A/C and leak in front neck	3
33651 Work Completed	Wade	602 09/10/2025	30080	replaced A/C compresor and recharged A/C. replaced a belt tentioner, flushed out rad	12
33981 Work Completed	Wade	602 11/06/2025	30105	change pic boards and instal wing	5
33987 Work Completed	Wade	602 11/07/2025	30105	change wing blade, replac hose for wing,	7
34006 Work Completed	Wade	602 11/10/2025	30107	inspect vehicle for random wing movement. bad solenoid	5
34108 Work Completed	Wade	602 11/27/2025	30111	instal shifter	4
34363 Work Completed	Doug	602 12/19/2025	30208	blew out air filter,	1
34401 Work Completed	Doug	602 01/05/2026	30301	replaced o-ring wing	0.5
34439 Work Completed	Phillip	602 01/09/2026	30334	change main bolt on side wing, and thermostate, work on side wing hyd issue	6
34486 Work Completed	Rylan	602 01/14/2026	30425	oil change and filters - fuel, oil and air. change tips	6
34636 Work Completed	PJL	602 01/28/2026		instal new shim in balde, change grease fitting	4
34772 Work Completed	Doug	602 02/18/2026	31056	repair leak at FL tire, replaced missing bolt on circle slide, repair lights, replaced solenoid for wing lift	9
34774 Work Completed	Wade	602 02/18/2026	31054	oil change, repair lights and oil leaks, top tranny oil, replaced solenoid on valve block for wing	8
34778 Work Completed	Wade	602 02/19/2026	31072	replace two way and antenna, repair wiring for power	3
34781 Work Completed	Doug	602 02/20/2026	31096	repair wing lift joystick	2
34831 Work Completed	Wade	602 03/06/2026	31381	removed 2 hoses, repaired loose seat	7
34832 Work Completed	Doug	602 03/06/2026		leak between bell housing and tranny	3
34903 Work Completed	PJL	602 02/23/2026		replaced broken bolt in wing	3
34924 Work Completed	PJL	602 03/02/2026		repair front lights	2
34982 Work Completed	Doug	602 03/13/2026	31480	tighten muffler clamp, replaced main pin on wing blade with bolt	4
35008 Work Completed	Doug	602 03/23/2026	31650	change out air filter and top up hyd tank	5
35013 Work Completed	Rylan	602 03/23/2026	31650	oil change and filters, drain and refilled hyd oil	3
35031 Work Completed	Rylan	602 03/26/2026	31727	change hose	5