

RITCHIE BROS. Diagnostic Report Auctioneers[®]

2018 Western Star Sleeper

Test Information

Engine	Detroit Diesel DD15 (14.8)
VIN	5KJJBHDR4JLJV4915
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: Conventional
Test Time	Dec. 4, 2025, 1:14 p.m.
File Length	9.606 s

Usage

Label	Value	Units
Engine Odometer	861,187	mi
Odometer (Instrument Cluster #1)	861,187	mi
Engine Total Hours of Operation	11,211.25	h

Engine On/Off

Engine running

Check Engine Light

 MIL - Emissions malfunction

Emissions Deleted/Tampered
No

Faults				
<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Exhaust Emission Controller	Manufacturer Assignable SPN	Special Instruction	7